

CLEANING/REPAIR REPORT - AHERA

40 CFR 763.91(c) (INITIAL CLEANING) Unless the building has been cleaned using equivalent methods within the previous 6 months, all areas of a school building where friable ACBM, damaged or significantly damaged thermal system insulation ACM, or friable suspected ACBM assumed to be ACM are present shall be cleaned at least once after the completion of the inspection ... and before the initiation of any response action, other than O & M activities or repair, according to the following procedures:

(i) HEPA-vacuum or steam-clean all carpets. (ii) HEPA-vacuum or wet-clean all other horizontal surfaces. (iii) Dispose of all debris, filters, mopheads, and cloths in sealed, leak-tight containers.

CLEANING

REPAIR

Date of cleaning/repair: 8/16/91

Person performing the cleaning/repair: Mike Fender

Location of cleaning/repair: Chico Senior High School Home Ec-Boiler Room workorder #30469

Method of cleaning/repair: removal of pipe wrap

  
\_\_\_\_\_  
Signature, Title of Authorizing Person

40 CFR 763.91(c)(2) (ADDITIONAL CLEANING) The accredited management planner shall make a written recommendation to the local education agency whether additional cleaning is needed, and if so, the method and frequency of such cleaning.

Date of cleaning/repair:

Person performing the cleaning/repair:

Location of cleaning/repair:

Method of cleaning/repair:

\_\_\_\_\_  
Signature, Title of Authorizing Person

DISTRICT Chico Unified School District DATE December 30, 1991

SCHOOL Chico Senior High INSPECTOR Robert Peters R.P.

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Mud Jnt	5-10	Darkroom - Attic	1-4
A	Mesh wrap	15-20	Darkroom - Attic	1-4
A	Tran panl	Assumed	Red painted panels along walkways, janitor closets, rr, stairwells	1-4
B	12" VFT	1-5	All rooms	1-4
C	12" VFT	1-5	Room 10	1-4
C	12" VFT	1-5	All rooms	1-4
400	Mud jnt	5-10	Library Attic	1-4
500	Tran panl	Assumed	2 - Kilns	1-4
500	Mud jnts	5-10	Fine Arts	1-4
500	Mud jnts	5-10	Room F-1	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE December 30, 1991

SCHOOL Chico Senior High INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
S	Heat Shld paper	75-80	Rm S-3	2-7
S	Bl countr	Assumed	Science Rooms	1-4
S	Mud jnts	5-10	All Rooms	1-4
S	9" VFT Bg	1-5	All Rooms	1-4
S	PW Str	65-70	Rm S-5 Storeroom	2-4
H 700	Bir Ins	25-35	Home Ec Boiler Room	2-4
700	TOC	1-5	Music wing hall ceiling	7
700	TOC	1-5	Instrument storage room	1-4
700	9" VFT y1	5-10	Music Wing Hall	7
700	Tran Peg Board	15-20	Custodial & Band Room	1-4
700	Hold tank	Assumed	Home Ec Heater Room	2-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 30, 1991

SCHOOL Chico Senior High INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
700	PW Str	75-80	Home Ec Storage Closet	1-4
700	PW Str	75-80	2nd Home Ec Storage Closet	1-4
700	PW Cnr	75-80	Home Ec Storage Closet	1-4
700	Door Fill	25-35	Home Ec Heater Room	1-4
700	PW Str	5-10	Home Ec Heater Room	4
700	Tran pipe	Assumed	Home Ec Heater Room	1-4
700	PW Aircel	Assumed	Under Choral Room Risers	2-4
700	PW Debris	Assumed	Under Choral Room Risers	1-4
1000	PW Str	35-40	Auto Shop, Loft, Woodshop	1-3 Wood shop 12" missing (4)
1100	Wall plas	1-5	Ag Classroom 2 (space 3)	1-4
1100	Tran panl	15-20	Ag Shop Welding Booth	2-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 30, 1991  
 SCHOOL Chico Senior High INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
1100	Tran pipe	Assumed	Ag Shop (two pipes)	1-4
900	PW Str	50-55	Girls/Boys Locker Room	1-4
900	PW Str	50-55	Girls/Boys Boil rm crawl sp	3-4
900	Tank Wrap	1-5	Gym Boiler Room	2-4
900	Mud Jnt	5-10	Gym Boiler Room	2-4
900	Boiler rm gasket	85-90	Gym Boiler Room	1-4
900	Wall & ceil plas	1-5	All rooms except Boiler Room	5-6
800	9" VFT Gy	1-5	Kitchen	5-2
800	TOC	1-5	All Rooms	2-4
800	Tran panl	Assumed	Snack Bar	1-4
800	Tran panl	Assumed	Stage & Cafe	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE December 30, 1991

SCHOOL Chico Senior High INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
800	Mud Jnts	5-10	Under stage	1-4
800	9" VFT		Under stage	

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 8, 1991

SCHOOL Chico Senior High INSPECTOR Robert Peters R.P.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Mud Jnt	5-10	Darkroom - Attic	1-4
A	Mesh wrap	15-20	Darkroom - Attic	1-4
A	Tran panl	Assumed	Red painted panels along walkways, janitor closets, rr, stairwells	1-4
B	12" VFT	1-5	All rooms	1-4
C	12" VFT	1-5	Room 10	1-4
C	12" VFT	1-5	All rooms	1-4
400	Mud jnt	5-10	Library Attic	1-4
500	Tran panl	Assumed	2 - Kilns	1-4
500	Mud jnts	5-10	Fine Arts	1-4
500	Mud jnts	5-10	Room F-1	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 8, 1991

SCHOOL Chico Senior High INSPECTOR Robert Peters

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS  
 MAT.#

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
S		75-80	Rm S-3	2-7
S		Assumed	Science Rooms	1-4
S		5-10	All Rooms	1-4
S		1-5	All Rooms	1-4
S		65-70	Rm S-5 Storeroom	2-4
H 700		25-35	Home Ec Boiler Room	2-4
700		1-5	Music wing hall ceiling	7
700		1-5	Instrument storage room	1-4
700		5-10	Music Wing Hall	7
700		15-20	Custodial & Band Room	1-4
700		Assumed	Home Ec Heater Room	2-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)



SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 8, 1991

SCHOOL Chico Senior High INSPECTOR Robert Peters

BLDG.	HOMOG. MAT. #	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
700	PW Str	75-80	Home Ec Storage Closet	1-4
700	PW Str	75-80	2nd Home Ec Storage Closet	1-4
700	PW Cnr	75-80	Home Ec Storage Closet	1-4
700	Door Fill	25-35	Home Ec Heater Room	1-4
700	PW Str	5-10	Home Ec Heater Room	4
700	Tran pipe	Assumed	Home Ec Heater Room	1-4
700	PW Aircel	Assumed	Under Choral Room Risers	2-4
700	PW Debris	Assumed	Under Choral Room Risers	1-4
1000	PW Str	35-40	Auto Shop, Loft, Woodshop	1-3 Wood shop 12" missing
1100	Wall plas	1-5	Ag Classroom 2 (space 3)	1-4
1100	Tran panl	15-20	Ag Shop Welding Booth	2-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 8, 1991

SCHOOL Chico Senior High INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
1100	Tran pipe	Assumed	Ag Shop (two pipes)	1-4
900	PW Str	50-55	Girls/Boys Locker Room	1-4
900	PW Str	50-55	Girls/Boys Boil rm crawl sp	3-4
900	Tank Wrap	1-5	Gym Boiler Room	2-4
900	Mud Jnt	5-10	Gym Boiler Room	2-4
900	Boiler rm gasket	85-90	Gym Boiler Room	1-4
900	Wall & ceill plas	1-5	All rooms except Boiler Room	5-2 wt rm, chair rm, dance rm hallway girls side door 2' sq hole + other damage
800	9" VFT Gy	1-5	Kitchen	1-4
800	TOC	1-5	All Rooms	2-4
800	Tran panl	Assumed	Snack Bar	1-4
800	Tran panl	Assumed	Stage & Cafe	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 8, 1991

SCHOOL Chico Senior High INSPECTOR Robert Peters

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS  
 BLDG. MAT.#

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
800	Mud Jnts	5-10	Under stage	1-4

CONDITION CODES

- GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
- CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
- ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
- MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)