



CLIENT NAME & ADDRESS:

2921 Chico Unified School District
2455 Carmichael Drive
Chico, CA 95926

PHONE: Phone 895-4179
FAX 891-3190

DATE:
7-3-96

Circle the Method and Turn Around Time

Results Needed:

hr/12hr/24hr/48hr/Ext

7-8-96
Nong Fay

PLM: Standard / Point Count

Gravimetry Prep

CONTACT: Kim C. Hrosen AR-12261

TEM: QUAL / QUANT. / WATER

P.O.# 97-404

JOB # C-15

AA/Flame AA/Furnace ICP

SITE: C H S

METALS:

SAMPLE NUMBER

DATE COLLECTED

SAMPLE LOCATION/DESCRIPTION	
1	...
2	...
3	...
4	...
5	...
6	...
7	...
8	...
9	...
10	...
11	...
12	...
13	...
14	...
15	...
16	...
17	...
18	...
19	...
20	...
21	...
22	...
23	...
24	...
25	...
26	...
27	...
28	...
29	...
30	...
31	...
32	...
33	...
34	...
35	...
36	...
37	...
38	...
39	...
40	...
41	...
42	...
43	...
44	...
45	...
46	...
47	...
48	...
49	...
50	...
51	...
52	...
53	...
54	...
55	...
56	...
57	...
58	...
59	...
60	...
61	...
62	...
63	...
64	...
65	...
66	...
67	...
68	...
69	...
70	...
71	...
72	...
73	...
74	...
75	...
76	...
77	...
78	...
79	...
80	...
81	...
82	...
83	...
84	...
85	...
86	...
87	...
88	...
89	...
90	...
91	...
92	...
93	...
94	...
95	...
96	...
97	...
98	...
99	...
100	...

001

7-3-96

L11 400 wing Floor tile / MASTIC.

002

7-3-96

L11 Laying Floor tile / Mastic.

03

7-3-96

L11 400 wing Floor tile / Mastic.

Stop at 001 if +

Sampled by:

Date:

Time:

Relinquished by:

Received By:

Date/Time:

Date/Time:

Sealed Condition (circle one) YES / NO

Relinquished by:

Received By:

Date/Time:

Date/Time:

Sealed Condition (circle one) YES / NO

FORENSIC ANALYTICAL

Page 1 of 2FAX TRANSMISSION
Summary of Results
Polarized Light MicroscopyTo: Chico Unified School DistrictDate/Time: 7/8/96Project : CHS
Report #: 256073Attn: KIP HansenSender: C. Wall

If you do not receive all pages, please contact Sender at (510) 887-8828

C: Chrysotile
A: AmositeCr: Crocidolite
ND: No Asbestos detected
P: Preliminary; subject to review

Sample Number	Asbestos %	Asb. Type(s)	Notes
001	<u>1-5</u>	<u>C</u>	<u>Tile (1-5) master (10-5)</u>
002	<u>*</u>	<u> </u>	<u> </u>
003	<u>*</u>	<u> </u>	<u> </u>

* Prior Positive

FAXED TO: _____

A hard copy report will follow in the mail. Thank you.

Supervisor Approval: _____



Forensic Analytical

BULK SAMPLE REQUEST FORM

CLIENT NAME & ADDRESS: 2921 Chico Unified School District 2455 Carmichael Drive Chico, CA . 95928	PHONE: Phone 895-4179 FAX 891-3190	DATE: 7-3-96
	Circle the Method and Turn Around Time	Results Needed: 7-8-96 Noon By Fax
	hr/12hr/24hr/48hr/Ext	
	☒ PLM) Standard / Point Count	Gravimetry Prep
CONTACT: Kip C. Hansen	TEM: QUAL / QUANT. / WATER	
P.O.# 97-404	JOB # CHS	AA/Flame AA/Furnace ICP
SITE: CHS	METALS:	

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
001	7-3-96	L11 400 wing Floor tile / MASTIC.
002	7-3-96	L11 400 wing Floor tile / MASTIC.
003	7-3-96	L11 400 wing Floor tile / MASTIC.

Sampled by:	Date:	Time:
Relinquished by:	Received By:	
Date/Time:	Date/Time: Sealed Condition (circle one) YES / NO	
Relinquished by:	Received By:	
Date/Time:	Date/Time: Sealed Condition (circle one) YES / NO	





Forensic Analytical

Analytical Report

San Francisco • 3777 Depot Road, Suite 409, Hayward, CA 94545 • Phone 510/887-8828 • Fax 510/887-4218
Los Angeles • 2959 Pacific Commerce Drive, Rancho Dominguez, CA 90221 • Phone 310/763-2374 • Fax 310/763-8684

Bulk Material Analysis

Method: 40 CFR 763, Subpart F, Appendix A (AHERA)

Client:

Chico Unified School District
Mr. Ron Jones
2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: 257262
Date Received: 08/06/96

P.O. Num: 97-404

Job ID:

Site: CSHS B Wing Overhang

Sample Number	Lab Number	Total Asbestos	Total Fibrous Non-Asbestos	(Breakdown by type)
CHS-B-001 Black multilayer fibrous tar. Bulk complex sample.	19654049	Non-Det. %	40-45%	Cellulose (40-45%)

David Kahane, C.I.H., Laboratory Director, Hayward Laboratory

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full with approval from Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Samples submitted to Forensic Analytical are retained for a period of six months and then disposed of according to all state and federal guidelines.



Forensic Analytical

BULK SAMPLE REQUEST FORM

CLIENT NAME & ADDRESS:

2921 Chico Unified School District
2455 Carmichael Drive
Chico, CA 95928

PHONE: 916-891-3194
FAX 916-891-3190

DATE: 8-5-96

Circle the Method and
Turn Around Time

Results Needed:
8-6-96 3:00pm

2 hr/12hr/24hr/48hr/Ext

By Fax

PLM Standard Point Count

Gravimetry Prep

CONTACT: Ron Jones

TEM: QUAL / QUANT. / WATER

P.O.# 97-404

JOB #

AA/Flame AA/Furnace ICP

SITE: CSHS B Wing Overhang

METALS:

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
CHS-B-001	8-5-96	Roofing from B wing overhang/NW Corner
		Please analyse each laver separatelv and report
		by layer.

Sampled by: Kip Hansen

Date: 8-5-96

Time: 3:00 pm

Relinquished by: Kip Hansen

Received By: *[Signature]*

Date/Time: 8-5-96 4:40pm

Date/Time:

Sealed Condition (circle one) YES / NO

Relinquished by:

Received By:

Date/Time:

Date/Time:

Sealed Condition (circle one) YES / NO



Forensic Analytical

Analytical Report

San Francisco • 3777 Depot Road, Suite 409, Hayward, CA 94545 • Phone 510/887-8828 • Fax 510/887-4218

Los Angeles • 2959 Pacific Commerce Drive, Rancho Dominguez, CA 90221 • Phone 310/763-2374 • Fax 310/763-8684

Bulk Material Analysis

Method: 40 CFR 763, Subpart F, Appendix A (AHERA)

Client:

Chico Unified School District
Mr. Ron Jones
2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: 256073
Date Received: 07/05/96

P.O. Num: 97-404

Job ID: CHS

Site: CHS

Sample Number	Lab Number	Total Asbestos	Total Fibrous Non-Asbestos	(Breakdown by type)
Gross Description/Comments				
001 Tan tile and black mastic. Asbestos in tile (1-5%) and in mastic (10-15%). Composite reported.	19647949	1-5%	Trace%	Chrysotile (1-5%) Cellulose (Trace%)
002 Sample not analyzed due to prior positive result in series.	19647950	N/A	N/A	
003 Sample not analyzed due to prior positive result in series.	19647951	N/A	N/A	

David Kahane, C.I.H., Laboratory Director, Hayward Laboratory

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full with approval from Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Samples submitted to Forensic Analytical are retained for a period of six months and then disposed of according to all state and federal guidelines.



Forensic Analytical

BULK SAMPLE REQUEST FORM

CLIENT NAME & ADDRESS:

2921 Chico Unified School District
2455 Carmichael Drive
Chico, CA 95928

PHONE: Phone 895-4179
FAX 891-3190

DATE:
7-3-96

Circle the Method and
Turn Around Time

Results Needed:

____ hr/12hr/24hr/48hr/Ext

7-8-96
Mon
By Fay

☒ PLM ☐ Standard / Point Count

Gravimetry Prep

CONTACT: Kip C. Hansen AC-12261

TEM: QUAL / QUANT. / WATER

P.O.# 97-404

JOB # CHS

AA/Flame AA/Furnace ICP

SITE: CHS

METALS:

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
001	7-3-96	L11 400 wing Floor tile / MASTIC.
002	7-3-96	L11 400 wing Floor tile / MASTIC.
003	7-3-96	L11 400 wing Floor tile / MASTIC.
		Stop at 001 if +

Sampled by:

Date:

Time:

Relinquished by:

Received By:

Date/Time:

Date/Time:

Sealed Condition (circle one) YES / NO

Relinquished by:

Received By:

Date/Time:

Date/Time:

Sealed Condition (circle one) YES / NO

SIX-MONTH SURVEILLANCE

Page 1 of 5

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Senior High INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Mud Jnt	5-10	Darkroom - Attic	1-4
A	Mesh wrap	15-20	Darkroom - Attic	11
A,B,C	Tran panl	Assumed	Red painted panels along walkways, janitor closets, rr, stairwells	1-4
B	12" VFT	1-5	All rooms	1-4
C	12" VFT	1-5	All rooms	1-4
400	12' VFTs	1-5	Library Entry & Office Area	1-4
400	Mud jnt	5-10	Library Attic	1-4 Repaired Inv. 95-235L
500	Tran panl	Assumed	2 - Kilns	1-4
500	Mud jnts	5-10	Fine Arts	1-4
500	Mud jnts	5-10	Room F-1	1-4

CONDITION CODES

GENERAL CONDITION:

(1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION:

(4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 2 of 5

DISTRICT Chico Unified School District DATE July 5, 1996SCHOOL Chico Senior High INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
-------	-----------------	----------------------	----------	----------------------------

S	Heat Shld paper	75-80	Rm S-3	11
S	Bl countr	Assumed	Science Rooms	1-4
S	Mud jnts	5-10	All Rooms	1-4
S	9" VFT Bg	1-5	All Rooms	1-4
S	PW Str	65-70	Rm S-5 Storeroom	2-7 - WO issued
H 700	Bir Ins	25-35	Home Ec Boiler Room	1-4
700	TOC	1-5	Music wing hall ceiling	7
700	TOC	1-5	Instrument storage room	1-4 - WO issued
700	9" VFT yl	5-10	Music Wing Hall	7
700	Tran Peg Board	15-20	Custodial & Band Practice Rooms	(broken & missing) 2-4 WO issued
700	Hold tank	Assumed	Home Ec Heater Room	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 3 of 5

DISTRICT Chico Unified School District DATE September 11, 1995SCHOOL Chico Senior High INSPECTOR Ron JonesHOMOG. ASBESTOS
MAT.# MATERIAL

LOCATION

CONDITION: CODE & COMMENTS

700	PW Str	75-80	Home Ec Storage Closet	1-4
700	PW Str	75-80	2nd Home Ec Storage Closet	1-4
700	PW Cnr	75-80	Home Ec Storage Closet	1-4
700	Door Fill	25-35	Home Ec Heater Room	1-4
700	PW Str	5-10	Home Ec Heater Room	1-4
700	Tran pipe	Assumed	Home Ec Heater Room	1-4
700	PW Aircel	Assumed	Under Choral Room Risers	10
700	PW Debris	Assumed	Under Choral Room Risers	7
700	T-O-C	1-5	Band Rm Off., Choral Rm Stor	1-4
700	9" VFTs	5-10	Choral Rm under Risers, Band Rm Off, Choral Rm Stor	1-4
1000	PW Str	35-40	Auto Shop, Loft, Woodshop	2-4 (1) -Tee (2) End WO issued

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 4 of 5

DISTRICT Chico Unified School District DATE July 5, 1996SCHOOL Chico Senior High INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
1000	Breeching	Assumed	Woodshop Finishing Room	1-4
900	PW Str	50-55	Girls/Boys Locker Room	1-4
900	PW Str	50-55	Girls/Boys Boil rm crawl sp	1-4
900	Tank Wrap	1-5	Gym Boiler Room	1-4
900	Mud Jnt	5-10	Gym Boiler Room	1-4
900	Boiler rm gasket	85-90	Gym Boiler Room	1-4
900	Wall & ceil plas	1-5	All rooms except Boiler Room	Retested - no asbestos
800	9" VFT Gy	1-5	Kitchen & MPR	5-7 tiles missing/broken
800	TOC	1-5	All Rooms	2-4 - water stains
800	Tran panl	Assumed	Snack Bar	1-4
800	Tran panl	Assumed	Stage & Cafe	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 5 of 5

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Senior High INSPECTOR Rob Jones

BLDG.	HOMOG.	ASBESTOS	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
800	Mud Jnts	5-10		Under stage	1-4
800	9" VFT			Under stage	1-4
800	PW Str	35-40		Custodial Room	1-4
800	Mud Jnts	5-10		Restroom Teacher's Lounge	1-4
800	Tran Pipe	Assumed		Water Heater Rm (2 pipes)	1-4
1100	Wall Plas	1-5		Ag Classroom 2 (space 3)	1-4
1100	Tran Panl	15-20		Ag Shop Welding Booth	2-4
1100	12" VFTs	Assumed		Classroom	1-4
1100	Tran Pipe	Assumed		Ag Shop (2 pipes)	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE January 3, 1996SCHOOL Chico Senior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Mud Jnt	5-10	Darkroom - Attic	1-4
A	Mesh wrap	15-20	Darkroom - Attic	11
A,B,C	Tran panl	Assumed	Red painted panels along walkways, janitor closets, rr, stairwells	1-4
B	12" VFT	1-5	All rooms	1-4
C	12" VFT	1-5	All rooms	1-4
400	12' VFTs	1-5	Library Entry & Office Area	1-4
400	Mud jnt	5-10	Library Attic	1-4 Repaired Inv. 95-235L
500	Tran panl	Assumed	2 - Kilns	1-4
500	Mud jnts	5-10	Fine Arts	1-4
500	Mud jnts	5-10	Room F-1	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE January 3, 1996SCHOOL Chico Senior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
S	Heat Shld paper	75-80	Rm S-3	11
S	Bl countr	Assumed	Science Rooms	1-4
S	Mud jnts	5-10	All Rooms	1-4
S	9" VFT Bg	1-5	All Rooms	1-4
S	PW Str	65-70	Rm S-5 Storeroom	2-4
H 700	Bir Ins	25-35	Home Ec Boiler Room	1-4
700	TOC	1-5	Music wing hall ceiling	7
700	TOC	1-5	Instrument storage room	1-4
700	9" VFT y1	5-10	Music Wing Hall	7
700	Tran Peg Board	15-20	Custodial & Band Practice Rooms	(broken & missing) 2-4
700	Hold tank	Assumed	Home Ec Heater Room	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE; NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 3 of 5

DISTRICT Chico Unified School District DATE January 3, 1996SCHOOL Chico Senior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
700	PW Str	75-80	Home Ec Storage Closet	1-4
700	PW Str	75-80	2nd Home Ec Storage Closet	1-4
700	PW Cnr	75-80	Home Ec Storage Closet	1-4
700	Door Fill	25-35	Home Ec Heater Room	1-4
700	PW Str	5-10	Home Ec Heater Room	1-4
700	Tran pipe	Assumed	Home Ec Heater Room	1-4
700	PW Aircel	Assumed	Under Choral Room Risers	10
700	PW Debris	Assumed	Under Choral Room Risers	7
700	T-O-C	1-5	Band Rm Off., Choral Rm Stor	1-4
700	9" VFTs	5-10	Choral Rm under Risers, Band Rm Off, Choral Rm Stor	1-4
1000	PW Str	35-40	Auto Shop, Loft, Woodshop	2-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 4 of 5

DISTRICT Chico Unified School District DATE January 3, 1996

SCHOOL Chico Senior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
1000	Breaching	Assumed	Woodshop Finishing Room	1-4
900	PW Str	50-55	Girls/Boys Locker Room	7
900	PW Str	50-55	Girls/Boys Boil rm crawl sp	10
900	Tank Wrap	1-5	Gym Boiler Room	7
900	Mud Jnt	5-10	Gym Boiler Room	7
900	Boiler rm gasket	85-90	Gym Boiler Room	7
900	Wall & ceil plas	1-5	All rooms except Boiler Room	Retested - no asbestos
800	9" VFT Gy	1-5	Kitchen & MPR	1-5-6 70 tiles missing/Broken
800	TOC	1-5	All Rooms	2-4
800	Tran panl	Assumed	Snack Bar	1-4
800	Tran panl	Assumed	Stage & Cafe	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 5 of 5

DISTRICT Chico Unified School District DATE January 3, 1996SCHOOL Chico Senior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
800	Mud Jnts	5-10	Under stage	1-4
800	9" VFT		Under stage	1-4
800	PW Str	35-40	Custodial Room	1-4
800	Mud Jnts	5-10	Restroom Teacher's Lounge	1-4
800	Tran Pipe	Assumed	Water Heater Rm (2 pipes)	1-4
1100	Wall Plas	1-5	Ag Classroom 2 (space 3)	1-4
1100	Tran Panl	15-20	Ag Shop Welding Booth	2-4
1100	12" VFTs	Assumed	Classroom	1-4
1100	Tran Pipe	Assumed	Ag Shop (2 pipes)	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)