

DISTRICT Chico Unified School District DATE January 1, 1998

SCHOOL Chico Senior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Mud Jnt	5-10	Darkroom - Attic	1-4
A	Mesh wrap	15-20	Darkroom - Attic	1-4
A, B, C	Tran panl	Assumed	Red painted panels along walkways, janitor closets, rr, stairwells	1-4
B	12" VFT	1-5	All rooms	1-4
C	12" VFT	1-5	All rooms	1-4
400	12' VFTs	1-5	Library Entry & Office Area	1-4
400	Mud jnt	5-10	Library Attic	1-4 Repaired Inv. 95-235L
500	Tran panl	Assumed	2 - Kilns	1-4
500	Mud jnts	5-10	Fine Arts	1-4
500	Mud jnts	5-10	Room F-1	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE January 2, 1996

7-10-97

SCHOOL Chico Senior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
S	Heat Shld paper	75-80	Rm S-3	11
S	Bl countr	Assumed	Science Rooms	1-4
S	Mud jnts	5-10	All Rooms	1-4
S	9" VFT Bg	1-5	All Rooms	1-4
S	PW Str	65-70	Rm S-5 Storeroom	2-4
H 700	Bir Ins	25-35	Home Ec Boiler Room	1-4
700	TOC	1-5	Music wing hall ceiling	7
700	TOC	1-5	Instrument storage room	1-4
700	9" VFT y1	5-10	Music Wing Hall	7
700	Tran Peg Board	15-20	Custodial & Band Practice Rooms	(broken & missing) 2-4
700	Hold tank	Assumed	Home Ec Heater Room	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE Page 3 of 5

DISTRICT Chico Unified School District DATE ~~January 1, 1996~~ 7-10-97

SCHOOL Chico Senior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
700	PW Str	75-80	Home Ec Storage Closet	1-4
700	PW Str	75-80	2nd Home Ec Storage Closet	1-4
700	PW Cnr	75-80	Home Ec Storage Closet	1-4
700	Door Fill	25-35	Home Ec Heater Room	1-4
700	PW Str	5-10	Home Ec Heater Room	1-4
700	Tran pipe	Assumed	Home Ec Heater Room	1-4
700	PW Aircel	Assumed	Under Choral Room Risers	10
700	PW Debris	Assumed	Under Choral Room Risers	7
700	T-Q-C	1-5	Band Rm Off., Choral Rm Stor	1-4
700	9" VFTS	5-10	Choral Rm under Risers, Band Rm Off, Choral Rm Stor	1-4
1000	PW Str	35-40	Auto Shop, Loft, Woodshop	2-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE January 3, 1996 7-10-97

SCHOOL Chico Senior High INSPECTOR Ron Jones

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
1000	Breeching	Assumed	Woodshop Finishing Room	1-4
900	PW Str	50-55	Girls/Boys Locker Room	7
900	PW Str	50-55	Girls/Boys Boil rm crawl sp	10
900	Tank Wrap	1-5	Gym Boiler Room	7
900	Mud Jnt	5-10	Gym Boiler Room	7
900	Boiler rm gasket	85-90	Gym Boiler Room	7
900	Wall & ceil plas	1-5	All rooms except Boiler Room	Retested - no asbestos
800	9" VFT Gy	1-5	Kitchen & MPR	1-5-6, 70 tiles missing/Broken
800	TOC	1-5	All Rooms	2-4
800	Tran panl	Assumed	Snack Bar	1-4
800	Tran panl	Assumed	Stage & Cafe	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE February 2, 1996 7-10-97

SCHOOL Chico Senior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
800	Mud Jnts	5-10	Under stage	1-4
800	9" VFT		Under stage	1-4
800	PW Str	35-40	Custodial Room	1-4
800	Mud Jnts	5-10	Restroom Teacher's Lounge	1-4
800	Tran Pipe	Assumed	Water Heater Rm (2 pipes)	1-4
1100	Wall Plas	1-5	Ag Classroom 2 (space 3)	1-4
1100	Tran Panl	15-20	Ag Shop Welding Booth	2-4
1100	12" VFTs	Assumed	Classroom	1-4
1100	Tran Pipe	Assumed	Ag Shop (2 pipes)	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)