

K:\MANIFEST\Manifest 2003\11031804\2 dec. 042903

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
		C A D 9 8 1 4 1 5 2 2 7 1 9 3		5 7				103165	
3. Generator's Name and Mailing Address CHICO UNIFIED SCHOOL DIST. 1163 EAST 4 TH ST. CHICO, CA 95926 4. Generator's Phone (530 891-3195				SITE: 901 THE ESPLANADE CHICO, CA				A. State Manifest Document Number 22019357	
5. Transporter 1 Company Name JANUS CORPORATION				6. US EPA ID Number C A L 0 0 0 1 9 0 7 5 8				B. State Generator's ID	
7. Transporter 2 Company Name				8. US EPA ID Number				C. State Transporter's ID [Reserved.]	
9. Designated Facility Name and Site Address BAJ LANDFILL 6426 HAY ROAD VACAVILLE, CA 95687				10. US EPA ID Number C A D 9 8 2 0 4 2 4 7 5				D. Transporter's Phone 925 969-9200	
								E. State Transporter's ID [Reserved.]	
								F. Transporter's Phone	
								G. State Facility's ID	
								H. Facility's Phone 707 451-3276	
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number):				12. Containers		13. Total Quantity		14. Unit Wt/Vol	
				No. Type					
a. R.Q. ASBESTOS, 9, NA2212, PGIII				001 CM 000035 Y				I. Waste Number State 151 EPA/Other	
b.								State EPA/Other	
c.								State EPA/Other	
d.								State EPA/Other	
J. Additional Descriptions for Materials Listed Above				K. Handling Codes for Wastes Listed Above					
				a.		b.			
				c.		d.			
15. Special Handling Instructions and Additional Information JANUS CORP., 1091 Shary Circle, Concord, CA 94510-2407, 24-HR EMERGENCY 925 969-9200 EPA Region IX - BAAQMD, 939 Ellis St., San Francisco, CA 94109 Asbestos Removal Requirement 40 CFR 61 (bagged, sealed and labeled)									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name ROBERT PETERS				Signature Robert Peters				Month Day Year 05/12/03	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Gary Morgan				Signature Gary Morgan				Month Day Year 05/12/03	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name				Signature				Month Day Year	
19. Discrepancy Indication Space									
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name Alfred Cortez									
				Signature Alfred Cortez				Month Day Year 05/13/03	

RECEIVED

DO NOT WRITE BELOW THIS LINE.

JUN 18 2003

MANIFEST NUMBER 2003103105-2HAZ DEC 06/12/03

22019362

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550

GENERATOR

FACILITY

TRANSPORTER

UNIFORM HAZARDOUS
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest Document No.

2. Page 1

Information in the shaded areas
is not required by Federal law.

C A D 9 8 1 4 1 5 2 2 7 1 9 3 6 2

of 1

103163-2

3. Generator's Name and Mailing Address

CHICO UNIFIED SCHOOL DIST.
1153 EAST 4TH ST.
CHICO, CA 95926

SITE: 901 THE ESPLANADE
CHICO, CA

A. State Manifest Document Number

22019362

B. State Generator's ID

C. State Transporter's ID [Reserved.]

D. Transporter's Phone

925 969-9200

E. State Transporter's ID [Reserved.]

F. Transporter's Phone

G. State Facility's ID

H. Facility's Phone

707 451-3276

5. Transporter 1 Company Name

JANUS CORPORATION

6. US EPA ID Number

C A L 0 0 0 1 9 0 7 5 8

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

B&S LANDFILL
6426 HAY ROAD
VACAVILLE, CA 95687

10. US EPA ID Number

C A D 9 8 2 0 4 2 4 7 5

11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)

R.O. ASBESTOS, 9, NA2212, PGIII

12. Containers
No. Type

13. Total
Quantity

14. Unit
Wt/Vol

I. Waste Number

State 151

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

a.

b.

c.

d.

15. Special Handling Instructions and Additional Information

JANUS CORP., 1081 Shary Circle, Concord, CA 94518-2407, 24-HR EMERGENCY #925 969-9200
EPA Region IX - BAZOND, 919 Ellis St., San Francisco, CA 94109
Asbestos Removal Requirement 40 CFR 61 (bagged, sealed and labeled)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

ROBERT PETERS CUSID

Signature

Robert Peters

Month

Day

Year

06 09 03

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Gregory Maysa

Signature

Gregory Maysa

Month

Day

Year

06 09 03

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month

Day

Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19

Printed/Typed Name

Signature

Month

Day

Year

06 09 03

JUN 27 2003

DO NOT WRITE BELOW THIS LINE.

Yellow:

TSDF SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS
(Generators who submit hazardous waste for transport by rail or water must produce completed copy of this copy and send to DTSC within 30 days.)

ICWAMFESTWentwood 2003103105HAZ.doc, 06/06/03

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.					
		C A D 9 8 1 4 1 5 2 2 7		1 9 3 7 9				103163					
3. Generator's Name and Mailing Address CHICO UNIFIED SCHOOL DIST. SITE: 901 THE ESPLANADE 1163 EAST 4TH ST. CHICO, CA 95926						A. State Manifest Document Number 22019379							
4. Generator's Phone (530) 891-3195						B. State Generator's ID							
5. Transporter 1 Company Name JANUS CORPORATION						6. US EPA ID Number C A L 0 0 0 1 9 0 7 5 8		C. State Transporter's ID [Reserved.]					
7. Transporter 2 Company Name						8. US EPA ID Number		D. Transporter's Phone 925 969-9200					
9. Designated Facility Name and Site Address B&S LANDFILL 5426 HAY ROAD VACAVILLE, CA 95687						10. US EPA ID Number C A D 9 8 2 0 4 2 4 7 5		E. State Transporter's ID [Reserved.]					
								F. Transporter's Phone					
								G. State Facility's ID					
								H. Facility's Phone 707 451-3276					
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)						12. Containers No. Type		13. Total Quantity		14. Unit Wt/Vol		I. Waste Number	
a. R.Q. ASBESTOS, 9, NA2212, PGIII						001 CM00025 Y						State 151	
b.												EPA/Other	
c.												State	
d.												EPA/Other	
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above							
						a. b.							
						c. d.							
15. Special Handling Instructions and Additional Information JANUS CORP., 1001 Shary Circle, Concord, CA 94518-2407, 24-HR EMERGENCY #925 969-9200 EPA Region IX - BAAQMD, 939 Ellis St., San Francisco, CA 94109 Asbestos Removal Requirement 40 CFR 61 (bagged, sealed and labeled)													
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.													
Printed/Typed Name ROBERT PETERZS CUSO						Signature Robert Peterzs				Month Day Year 06 11 03			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name GERD MORGAN						Signature Gerd Morgan				Month Day Year 06 11 03			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name						Signature				Month Day Year			
19. Discrepancy Indication Space													
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19 Printed/Typed Name						Signature [Signature]				Month Day Year 06 11 03			

DO NOT WRITE BELOW THIS LINE.

Yellow: TSDf SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS.
(Generators who submit hazardous waste for transport out-of-state, produce completed copy of this copy and send to DTSC within 30 days.)

C. Binden

K'WANT ESTIMATED 200310310514Z dec. 05/1003

22019381

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802. WITHIN CALIFORNIA, CALL 1-800-852-7550

GENERATOR

FACILITY

TRANSPORTER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law. 103165	
3. Generator's Name and Mailing Address CHICO UNIFIED SCHOOL DIST. 1163 EAST 4 TH ST. CHICO, CA 95926		SITE: 901 THE ESPLANADE CHICO, CA		A. State Manifest Document Number 22019381		B. State Generator's ID	
4. Generator's Phone 530 891-1195		6. US EPA ID Number C A L 0 0 0 1 9 0 7 5 8		C. State Transporter's ID [Reserved]		D. Transporter's Phone 925 969-9200	
5. Transporter 1 Company Name JANUS CORPORATION		8. US EPA ID Number		E. State Transporter's ID [Reserved]		F. Transporter's Phone	
9. Designated Facility Name and Site Address HAY ROAD LANDFILL 6426 HAY ROAD VACAVILLE, CA 95687		10. US EPA ID Number C A D 9 8 2 0 4 2 4 7 5		G. State Facility's ID		H. Facility's Phone 707 451-3276	
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type		13. Total Quantity		14. Unit Wt/Vol	
a. R.O. ASBESTOS, 9, NA2212, PGIII		PS1 EA 258333 Y				I. Waste Number State 151 EPA/Other	
b.						State EPA/Other	
c.						State EPA/Other	
d.						State EPA/Other	
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above		a.		b.	
				c.		d.	
15. Special Handling Instructions and Additional Information JANUS CORP., 1081 Shary Circle, Concord, CA 94510-2407, 24-HR EMERGENCY 925 969-9200 EPA Region IX - BAAQMD, 939 Ellis St., San Francisco, CA 94109 Asbestos Removal Requirement 40 CFR 61 (bagged, sealed and labeled)							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.							
Printed/Typed Name ROBERT PETERSON		Signature Robert Peterson		Month 06		Day 20	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Gary Morgan		Signature Gary Morgan		Month 06		Day 20	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month		Day	
19. Discrepancy Indication Space							
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 11		Signature Mireia Cortez		Month 06		Day 20	

DO NOT WRITE BELOW THIS LINE.

Yellow: TSDS SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS.
(Generators who submit hazardous waste for transport out-of-state, produce completed copy of this copy and send to DTSC within 30 days.)

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11-19-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Senior High School

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	1	NONE DETECTED	5,735 S	ADMINISTRATION AREA	(13) SAMPLE HMS-CHS-01 COLLECTED ON 3-28-88. SAME 11/19/03	N/A
M	12" VFT BEIGE	2	TRACE	5,700 S	RECEPTION AREA	(1) (4) SAME 11/19/03	N
M	12" ACT	3	NONE DETECTED	3,550 S	PRINCIPLES OFFICE, COMPTROLLER, DW, & ROOMS 102-107	(13) SAMPLE HMS-CHS-03 COLLECTED ON 3-28-88. SAME 11/19/03	N/A
T	MUD JOINTS	7	5-10%	20 JOINTS	DARK ROOM ATTIC (ROOM 111)	(1) (4) SAME SAME 11/19/03	N
T	MESH WRAP	8	12-20%	1/2 L	DARK ROOM ATTIC (ROOM 111)	(11) INACCESSIBLE. SAME 11/19/03	N
M	TRANSITE PANELS	95	ASSUMED	1,300 S	ALONG WALKWAYS, JANITORS CLOSETS, RESTROOMS, & STAIRWELLS	(1) (5) PANELS PAINTED WHITE 11/19/03.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11-19-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Senior High School

Building: A (Unit 200) Upstairs

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
M	12" VFT BEIGE	2	TRACE	5,800 S	UPSTAIRS CLASSROOMS	(1) (4) SAMPLE SAME 11/19/03	N
M	2' X 4' FCP	6	NONE DETECTED	10,000 S	UPSTAIRS CLASSROOMS	(13) SAMPLE HMS-CHS-06 COLLECTED ON 3-28-88. SAME 11/19/03	N/A

School: Chico Senior High School

Building: B (Unit 100)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
M	2' X 4' FCP	13	NONE DETECTED	10,000 S	ALL CLASSROOMS	(13) SAMPLE HMS-CHS-13 COLLECTED ON 3-28-88. SAME 11/19/03	N/A
M	12" VFT	14	1-5%	9,430 S	ALL CLASSROOMS	(7) ABATED JUNE 2003	N
M	TRANSITE PANELS	95	ASSUMED	1,300 S	ALONG WALKWAYS, JANITORS CLOSETS, RESTROOMS, & STAIRWAYS	(1) (5) PANELS PAINTED WHITE. SAME 11/19/03	N

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

(4) No (5) Yes (If Yes, explain under comments)

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11-19-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Senior High School Building: C (Unit 300)

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	14	1-5%	9,513 S	ALL CLASSROOMS	(7) ABATED JUNE 2003	N
M	TRANSITE PANELS	95	ASSUMED	1,300 S	EXTERIOR OF BUILDING	(1) (5) PANELS PAINTED WHITE. SAME 11/19/03	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11-19-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Senior High School

Building: D & H (Unit 700 Music & Home EC)

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
T	BOILER INSULATION	37	25-35%	48 S ***	HOME EC & BOILER ROOM	(1) (6) REPAIRED 1-4 SAME 11/19/03	N
S	TROWELED ON CEILING	38	1-5%	300 S	INSTRUMENT STORAGE ROOM & BAND ROOM OFFICE	(1) (4) SAME 11/19/03	N
M	9" VFT YELLOW	39	5-10%	1,410 S ***	MUSIC WING HALL, CHORAL ROOM UNDER RISERS, BAND ROOM OFFICE, & CHORAL ROOM STORAGE	(7) (1) (4) REPLACED WITH 12" VFT GREY. 9" VFT UNDER CARPET IN BAND ROOM OFFICE. SAME 11/19/03	N/A N
M	TRANSITE PEG BOARD	41	15-20%	1,000 S	BAND PRACTICE ROOM & CUSTODIAL ROOM	(2) PIECES BROKEN & MISSING. 12/27/01 (2) (4) 11/5/02 (5) (9) TAG BOARD SAME 11/19/03	N
T	PIPEWRAP STRAIGHT	80	75-80%	58 L ***	HOME EC STORAGE CLOSET	(7) ABATED JUNE 2003	N
T	PIPEWRAP STRAIGHT	81	75-80%	120 L ***	2 ND HOME EC STORAGE CLOSET	(7) ABATED JUNE 2003	N
T	PIPEWRAP CORNER	82	75-80%	>1 EACH ***	HOME EC STORAGE CLOSET	(7) ABATED JUNE 2003	N
M	FIRE DOOR	83	25-35%	1 EACH	HOME EC HEATER ROOM	(7) ABATED JUNE 2003	N
M	HOLDING TANK	94	ASSUMED	72 S ***	HOME EC HEATER ROOM	(7) ABATED JUNE 2003	N
M	12" VFT GREY	100	ASSUMED	810 S	MUSIC WING HALL	(7) ABATED JUNE 2003	N

*** TO BE ABATED JUNE 2003

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

- (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 (4) No (5) Yes (If Yes, explain under comments)
 (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11-19-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Senior High School

Building: F (Unit 500)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	MUD JOINTS	52	5-10%	125 JOINTS	FINE ARTS	(1) (4) ←	N
M	2' X 4' FCP	59	NONE DETECTED	4,500 S	ALL CLASSROOMS	(13) SAMPLE HMS-CHS-59 COLLECTED ON 3-28-88.	N/A
T	MUD JOINTS	60	5-10%	12 L	ROOM F-1	(1) (4) SAME 11/19/03	N
M	9" VFT	61	TRACE	4,500 S	ALL CLASSROOMS	(1) (4) ↓	N
M	TRANSITE PANELS	95	ASSUMED	150 S	2 KILNS	(1) (4)	N

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

- (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 (4) No (5) Yes (If Yes, explain under comments)
 (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11-19-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Senior High School

Building: S (Unit 600 Science)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
M	2' X 4' FCP	22	NONE DETECTED	8,000 S	ALL ROOMS	(13) SAMPLE HMS-CHS-22 COLLECTED ON 3-28-88.	N/A
T	MUD JOINTS	23	5-10%	40 JOINTS	ALL ROOMS	(1) (4)	N
M	9" VFT	24	1-5%	8,100 S	ALL ROOMS	(1) (4)	N
T	PIPE WRAP STRAIGHT	26	65-70%	12 L	ROOM 5 (STORE ROOM)	(1) (6) SAME 11/19/03	N
M	BLACK COUNTER TOPS	99	ASSUMED	UNDETERMINED	IN ALL SCIENCE ROOMS	(1) (4)	N

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

- (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 (4) No (5) Yes (If Yes, explain under comments)
 (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11-19-2003

District: Chico Unified School District

Inspector: Robert Baughman

Building: LH-800

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPEWRAP STRAIGHT	45	35-40%	3 L	CUSTODIAL ROOM	(1) (4) SAME 11/19/03	N
T	MUD JOINTS	52	5-10%	10 EACH	UNDER STAGE	(1) (4) SAME 11/19/03	N
M	9" VFT GREY	55	1-5%	6,800 S	KITCHEN & MPR	(3) (5) 11/19/03 - GM @ SITE TO REPAIR	N
S	TROWELED ON CEILING	57	1-5%	900 S	ALL ROOMS	(1) (6) PAINTED. SAME 11/19/03	N
M	TRANSITE PANELS	95	ASSUMED	364 S	SNACK BAR, STAGE, & CAFE	(1) (4)	N
M	9" VFT	101	ASSUMED	250 S	UNDER STAGE	(1) (7) STAGE REMOVED	N
T	MUD JOINTS	102	5-10%	10 EACH	TEACHER'S LOUNGE RESTROOMS	(1) (4)	N
M	TRANSITE PIPE	103	ASSUMED	12 L	WATER HEATER ROOM (2 PIPES)	(1) (4)	N

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

- (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 (4) No (5) Yes (If Yes, explain under comments)
 (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11-19-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Senior High School

Building: 900 GYM

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALLS & CEILING PLASTER	46	NONE DETECTED	2,000 S	ALL ROOMS EXCEPT BOILER	(13) SAMPLE HMS-CHS-46A-C COLLECTED ON 3-28-88. ADDITIONAL SAMPLES HMS-93103-03A-C COLLECTED ON 7-8-93.	N/A
T	PIPEWRAP STRAIGHT	50	50-55%	2,700 S	GIRL'S & BOY'S LOCKER ROOM & BOILER ROOM CRAWL SPACE	(10) ISOLATED & RESTRICTED	N

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

(1) Good

(4) No

(6) Repaired

(11) Inaccessible, no inspection data

(2) Damaged

(5) Yes (If Yes, explain under comments)

(7) Removed

(8) Encapsulated

(3) Significantly Damaged (25% or more)

(9) Enclosed

(10) Isolated & Restricted

(12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11-19-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Senior High School

Building: IT-1000

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPEWRAP STRAIGHT	45	35-40%	700 L	AUTO SHOP, LOFT, & WOOD SHOP	(1) (4) Same 11/19/03	N
T	BREECHING	90	ASSUMED	100 S	WOOD FINISHING ROOM	(1) (4)	N

School: Chico Senior High School

Building: AG-1100

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALL PLASTER	46	1-5%	950 S	AG CLASSROOM 2 (SPACE 3)	(1) (4) Same 11/19/03	N
M	TRANSITE PANELS	48	15-20%	200 S	AG SHOP WELD BOOTHS & TABLES	(1) (4)	N
M	12" VFT	89	ASSUMED	400 S	CLASSROOM	(1) (4)	N
M	TRANSITE PIPES	96	ASSUMED	12 L	AG SHOP (2 PIPES)	(1) (4)	N

CONDITION CODE

General Condition:
Change in Condition:
Abated:
Miscellaneous:

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)
(4) No (5) Yes (If Yes, explain under comments)
(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11-19-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Senior High School Building: 17 Portable Classrooms and 2 Portable Restrooms on West Campus

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					17 PORTABLE CLASSROOM AND 2 PORTABLE RESTROOMS	DISTRICT CERTIFICATION REQUIRED.	

Letters on File

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

- (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 (4) No (5) Yes (If Yes, explain under comments)
 (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	1	NONE DETECTED	5,735 S	ADMINISTRATION AREA	(13) SAMPLE HMS-CHS-01 COLLECTED ON 3-28-88. SAME 5/9/03	N/A
M	12" VFT BEIGE	2	TRACE	5,700 S	RECEPTION AREA	(1) (4) SAME 5/9/03	N
M	12" ACT	3	NONE DETECTED	3,550 S	PRINCIPLES OFFICE, COMPTROLLER, DW, & ROOMS 102-107	(13) SAMPLE HMS-CHS-03 COLLECTED ON 3-28-88. SAME 5/9/03	N/A
T	MUD JOINTS	7	5-10%	20 JOINTS	DARK ROOM ATTIC (ROOM 111)	(1) (4) SAME 5/9/03	N
T	MESH WRAP	8	12-20%	1/2 L	DARK ROOM ATTIC (ROOM 111)	(11) INACCESSIBLE.	N
M	TRANSITE PANELS	95	ASSUMED	1,300 S	ALONG WALKWAYS, JANITORS CLOSETS, RESTROOMS, & STAIRWELLS	(1) (5) PANELS PAINTED RED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: A (Unit 200) Upstairs

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT BEIGE	2	TRACE	5,800 S	UPSTAIRS CLASSROOMS	(1) (4) SAMPLE SAME 5/9/03	N
M	2' X 4' FCP	6	NONE DETECTED	10,000 S	UPSTAIRS CLASSROOMS	(13) SAMPLE HMS-CHS-06 COLLECTED ON 3-28-88. SAME 5/9/03	N/A

School: Chico Senior High School

Building: B (Unit 100)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	13	NONE DETECTED	10,000 S	ALL CLASSROOMS	(13) SAMPLE HMS-CHS-13 COLLECTED ON 3-28-88. SAME 5/9/03	N/A
M	12" VFT	14	1-5%	9,430 S	ALL CLASSROOMS	(1) (4) SAME 5/9/03	N
M	TRANSITE PANELS	95	ASSUMED	1,300 S	ALONG WALLWAYS, JANITORS CLOSETS, RESTROOMS, & STAIRWAYS	(1) (5) PANELS PAINTED WHITE. SAME 5/9/03	N

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

(4) No (5) Yes (If Yes, explain under comments)

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: C (Unit 300)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	14	1-5%	9,513 S	ALL CLASS ROOMS 10th FLOOR OF BUILDING Abated June 2003	(1) (4) SAME 5/9/03	N
M	TRANSITE PANELS	95	ASSUMED	1,300 S		(1) (5) PANELS PAINTED WHITE. SAME 5/9/03	N

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

- (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 (4) No (5) Yes (If Yes, explain under comments)
 (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: D & H (Unit 700 Music & Home EC)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
T	BOILER INSULATION	37	25-35%	48 S ***	HOME EC & BOILER ROOM	(1) (6) REPAIRED 1-4 SAME 5/9/03	N
S	TROWELED ON CEILING	38	1-5%	300 S	INSTRUMENT STORAGE ROOM & BAND ROOM OFFICE	(1) (4) SAME 5/9/03	N
M	9" VFT YELLOW	39	5-10%	1,410 S ***	MUSIC WING HALL, CHORAL ROOM UNDER RISERS, BAND ROOM OFFICE, & CHORAL ROOM STORAGE	(7) (1) (4) REPLACED WITH 12" VFT GREY. 9" VFT UNDER CARPET IN BAND ROOM OFFICE. SAME 5/9/03	N/A N
M	TRANSITE PEG BOARD	41	15-20%	1,000 S	BAND PRACTICE ROOM & CUSTODIAL ROOM	(2) 12/27/01 (2) (4) 11/5/02 (5) (9) TAG BOARD SAME 5/9/03	N
T	PIPEWRAP STRAIGHT	80	75-80%	58 L ***	HOME EC STORAGE CLOSET	(1) (4) SAME 5/9/03	N
T	PIPEWRAP STRAIGHT	81	75-80%	120 L ***	2 ND HOME EC STORAGE CLOSET	(1) (4) SAME 5/9/03	N
T	PIPEWRAP CORNER	82	75-80%	>1 EACH ***	HOME EC STORAGE CLOSET	(1) (4) SAME 5/9/03	N
M	FIRE DOOR	83	25-35%	1 EACH	HOME EC HEATER ROOM	(1) (4) SAME 5/9/03	N
M	HOLDING TANK	94	ASSUMED	72 S ***	HOME EC HEATER ROOM	(1) (4) SAME 5/9/03	N
M	12" VFT GREY	100	ASSUMED	810 S	MUSIC WING HALL	(1) SAME 5/9/03	N

*** TO BE ABATED JUNE 2003

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

(4) No (5) Yes (If Yes, explain under comments)

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: 700 (Music)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
T	PIPEWRAP STRAIGHT	84	5-10%	58 L	HOME EC HEATER ROOM	(1) (4) SAME 5/9/03	N
T	PIPEWRAP AIRCELL	97	ASSUMED	70 L	UNIDENTIFIED	(10)	N
M	TRANSITE PIPE	98	ASSUMED	8 L	HOME EC HEATER ROOM	(1) (4) TO BE ABATED June 2003	N

School: Chico Senior High School

Building: L (Unit 400 Library)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
M	12" VFT	14	1-5%	1,000 S	LIBRARY ENTRY & OFFICE AREA	(1) (4) SAME 5/9/03 (TO BE ABATED JUNE 2003)	N
M	2' X 4' FCP	17	NONE DETECTED	11,155 S	ALL ROOMS	(13) SAMPLE HMS-CHS-17 COLLECTED ON 3-28-88. SAME 5/9/03	N/A
T	MUD JOINTS	19	5-10%	20 JOINTS	LIBRARY ATTIC	(1) (6) REPAIRED 1/27/01 (1) (4) SAME 5/9/03	N

CONDITION CODE

General Condition:

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:

(4) No (5) Yes (If Yes, explain under comments)

Abated:

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: F (Unit 500)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	MUD JOINTS	52	5-10%	125 JOINTS	FINE ARTS	(1) (4) ←	N
M	2' X 4' FCP	59	NONE DETECTED	4,500 S	ALL CLASSROOMS	(13) SAMPLE HMS-CHS-59 COLLECTED ON 3-28-88.	N/A
T	MUD JOINTS	60	5-10%	12 L	ROOM F-1	(1) (4) SAME 5/9/03	N
M	9" VFT	61	TRACE	4,500 S	ALL CLASSROOMS	(1) (4) →	N
M	TRANSITE PANELS	95	ASSUMED	150 S	2 KILNS	(1) (4)	N

CONDITION CODE

General Condition:
Change in Condition:
Abated:
Miscellaneous:

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 (4) No (5) Yes (if Yes, explain under comments)
 (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: S (Unit 600 Science)

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
M	2' X 4' FCP	22	NONE DETECTED	8,000 S	ALL ROOMS	(13) SAMPLE HMS-CHS-22 COLLECTED ON 3-28-88.	N/A
T	MUD JOINTS	23	5-10%	40 JOINTS	ALL ROOMS	(1) (4)	N
M	9" VFT	24	1-5%	8,100 S	ALL ROOMS	(1) (4)	N
T	PIPE WRAP STRAIGHT	26	65-70%	12 L	ROOM 5 (STORE ROOM)	(1) (6) SAME 5/9/03	N
M	BLACK COUNTER TOPS	99	ASSUMED	UNDETERMINED	IN ALL SCIENCE ROOMS	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: LH-800

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
T	PIPEWRAP STRAIGHT	45	35-40%	3 L	CUSTODIAL ROOM	(1) (4) ↗	N
T	MUD JOINTS	52	5-10%	10 EACH	UNDER STAGE	(1) (4)	N
M	9" VFT GREY	55	1-5%	6,800 S	KITCHEN & MPR	(1) (6) REPAIRED.	N
S	TROWELED ON CEILING	57	1-5%	900 S	ALL ROOMS	(1) (6) PAINTED.	N
M	TRANSITE PANELS	95	ASSUMED	364 S	SNACK BAR, STAGE, & CAFE	(1) (4) SAME 5/9/03	N
M	9" VFT	101	ASSUMED	250 S	UNDER STAGE	(1) (7) STAGE REMOVED	N
T	MUD JOINTS	102	5-10%	10 EACH	TEACHER'S LOUNGE RESTROOMS	(1) (4)	N
M	TRANSITE PIPE	103	ASSUMED	12 L	WATER HEATER ROOM (2 PIPES)	(1) (4) ↘	N

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

- (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 (4) No (5) Yes (If Yes, explain under comments)
 (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: 900 GYM

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALLS & CEILING PLASTER	46	NONE DETECTED	2,000 S	ALL ROOMS EXCEPT BOILER SAME 5/9/03	(13) SAMPLE HMS-CHS-46A-C COLLECTED ON 3-28-88. ADDITIONAL SAMPLES HMS-93103-03A-C COLLECTED ON 7-8-93.	N/A
T	PIPEWRAP STRAIGHT	50	50-55%	2,700 S	GIRL'S & BOY'S LOCKER ROOM & BOILER ROOM CRAWL SPACE	(10) ISOLATED & RESTRICTED	N

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

(4) No (5) Yes (If Yes, explain under comments)

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: IT-1000

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPEWRAP STRAIGHT	45	35-40%	700 L	AUTO SHOP, LOFT, & WOOD SHOP	(1) (4)	N
T	BREECHING	90	ASSUMED	100 S	WOOD FINISHING ROOM	(1) (4)	N

School: Chico Senior High School

Building: AG-1100

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALL PLASTER	46	1-5%	950 S	AG CLASSROOM 2 (SPACE 3)	(1) (4)	N
M	TRANSITE PANELS	48	15-20%	200 S	AG SHOP WELD BOOTHS & TABLES	(1) (4)	N
M	12" V/FT	89	ASSUMED	400 S	CLASSROOM	(1) (4)	N
M	TRANSITE PIPES	96	ASSUMED	12 L	AG SHOP (2 PIPES)	(1) (4)	N

CONDITION CODE

General Condition:
Change in Condition:
Abated:
Miscellaneous:

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)
(4) No (5) Yes (If Yes, explain under comments)
(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School Building: 17 Portable Classrooms and 2 Portable Restrooms on West Campus

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					17 PORTABLE CLASSROOM AND 2 PORTABLE RESTROOMS	DISTRICT CERTIFICATION REQUIRED.	
						5/9/03	

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

(4) No (5) Yes (If Yes, explain under comments)

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS