

CLEANING/REPAIR REPORT - AHERA

40 CFR 763.91(c) (INITIAL CLEANING) Unless the building has been cleaned using equivalent methods within the previous 6 months, all areas of a school building where friable ACBM, damaged or significantly damaged thermal system insulation ACM, or friable suspected ACBM assumed to be ACM are present shall be cleaned at least once after the completion of the inspection ... and before the initiation of any response action, other than O & M activities or repair, according to the following procedures:

(i) HEPA-vacuum or steam-clean all carpets. (ii) HEPA-vacuum or wet-clean all other horizontal surfaces. (iii) Dispose of all debris, filters, mopheads, and cloths in sealed, leak-tight containers.

CLEANING

REPAIR

Date of cleaning/repair: 1/15/91

Person performing the cleaning/repair: Mike Fender

Location of cleaning/repair: McManus Elementary School crawl space attic above mens restroom work order #29047

Method of cleaning/repair: wettable cloth, HEPA vacuum

  
Signature, Title of Authorizing Person

40 CFR 763.91(c)(2) (ADDITIONAL CLEANING) The accredited management planner shall make a written recommendation to the local education agency whether additional cleaning is needed, and if so, the method and frequency of such cleaning.

Date of cleaning/repair:

Person performing the cleaning/repair:

Location of cleaning/repair:

Method of cleaning/repair:

\_\_\_\_\_  
Signature, Title of Authorizing Person

CLEANING/REPAIR REPORT - AHERA

40 CFR 763.91(c) **(INITIAL CLEANING)** Unless the building has been cleaned using equivalent methods within the previous 6 months, all areas of a school building where friable ACBM, damaged or significantly damaged thermal system insulation ACM, or friable suspected ACBM assumed to be ACM are present shall be cleaned at least once after the completion of the inspection ... and before the initiation of any response action, other than O & M activities or repair, according to the following procedures:

(i) HEPA-vacuum or steam-clean all carpets. (ii) HEPA-vacuum or wet-clean all other horizontal surfaces. (iii) Dispose of all debris, filters, mopheads, and cloths in sealed, leak-tight containers.

CLEANING


REPAIR

Date of cleaning/repair: 1/10/91

Person performing the cleaning/repair: Mike Fender

Location of cleaning/repair: McManus Elementary School unit A custodial room work order #29046

Method of cleaning/repair: wettable cloth, HEPA vacuum

  
\_\_\_\_\_  
Signature, Title of Authorizing Person

40 CFR 763.91(c)(2) **(ADDITIONAL CLEANING)** The accredited management planner shall make a written recommendation to the local education agency whether additional cleaning is needed, and if so, the method and frequency of such cleaning.

Date of cleaning/repair:

Person performing the cleaning/repair:

Location of cleaning/repair:

Method of cleaning/repair:

\_\_\_\_\_  
Signature, Title of Authorizing Person

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802. WITHIN CALIFORNIA, CALL 1-800-852-2550

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. CA D 9 8 1 4 1 5 4 5 8	Manifest Document No. 8 9 1 1 3	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address CHICO UNIFIED SCHOOL DISTRICT 1163 East Seventh Street Chico, CA 95928		LOCATION John Thomas School 989 East Avenue Chico, CA 95926		A. State Manifest Document Number <b>92789113</b>	
4. Generator's Phone 916 891-3004		402-9304		F. State Generator ID 401201	
5. Transporter 1 Company Name BDC SERVICES, INC.		6. US EPA ID Number CA D 9 8 1 4 5 5 5 2 0		D. Transporter's Phone 818-966-1101	
7. Transporter 2 Company Name		8. US EPA ID Number		E. State Transporter's ID	
9. Designated Facility Name and Site Address B & J LANDFILL 6426 HAY ROAD VACAVILLE, CA 95687		10. US EPA ID Number CA D 9 8 2 0 4 2 4 7 5		G. State Facility ID CA D 9 8 2 0 4 2 4 7 5	
				H. Facility's Phone (800) 794-2768	
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
a. "R.Q." HAZARDOUS SUBSTANCE SOLID N.O.S. ORH-E HA 9188 (ASBESTOS)		992011	999687	Y	State 151 EPA/Other
b.					State EPA/Other
c.					State EPA/Other
d.					State EPA/Other
J. Additional Information to FOR CHEMISTS DURING TRANSPORT CALL INSTITUTE 24 HOURS PER ALABAMA REGULATED 714-528-8163		K. Handling Codes for Wastes Listed Above a. 03 b. c. d.			
15. Special Handling Instructions and Additional Information BDC SERVICES, INC. 766 SO. AYON AZUSA, CA 91702  ASBESTOS REMOVAL REQUIREMENT 40 CFR 61 (BAGGED, SEALED & LABELED)					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of the consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable federal, state and international laws.  If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name ROBERT FEIGERS		Signature <i>Robert Feigers</i>		Month Day Year 01/06/93	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name David Aniss		Signature <i>David Aniss</i>		Month Day Year 01/06/93	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name Mary Korden					
Signature <i>Mary Korden</i>		Month Day Year 01/06/93			

DO NOT WRITE BELOW THIS LINE.

Yellow: TSDF SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS.  
 (Generators who submit hazardous waste for transport out-of-state, produce completed copy of this copy and send to DTSC within 30 days.)

92640038  
 IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802. WITHIN CALIFORNIA, CALL 1-800-852-GENRATOR  
 FACILITY

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. CA090141949	Manifest Document No. 41010318	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address CHICO UNIFIED SCHOOL DISTRICT 1103 East Seventh Street Chico, CA 95928		LOCATION John DeLamater Linn. 288 East Avenue Chico, CA 95928		92640038	
4. Generator's Phone (910) 891-3004		702-9304		92640038	
5. Transporter 1 Company Name S.O.C. Services, Inc. 700 S. Ayon Avenue Azusa, CA 91702		6. US EPA ID Number CA0901455520		92640038	
7. Transporter 2 Company Name		8. US EPA ID Number		92640038	
9. Designated Facility Name and Site Address S. J. Landfill 6126 Hwy Road Vacaville, CA 95687		10. US EPA ID Number CA0901912042475		92640038	
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	Weight
a. "A.S." Hazardous Substance, Solid, N.O.S. ORM-R, NA 9188 (Asbestos)		078	BA	0.0025	Y
b. "A.S." HAZARDOUS SUBSTANCE SOLID M.O.S. ORM-R, NA 9188 (Asbestos)		076	DT	0.0045	Y
c.					
d.					
15. Special Handling Instructions and Additional Information Asbestos Removal Requirements per 40 CFR 61 - Hazardous, Sealed & Labeled <i>This Load Has Two Cans #50 #58</i> <i>REMITT</i>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of the consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable federal, state and international laws.  If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name <i>YORBERT V. KERS</i>		Signature <i>Kobert Kers</i>		Month Day Year 06 30 73	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <i>Paul BERRY</i>		Signature <i>Paul Berry</i>		Month Day Year 06 30 73	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name <i>MARY BORDEN</i>		Signature <i>Mary Borden</i>		Month Day Year 06 30 73	

DO NOT WRITE BELOW THIS LINE.

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 28, 1992

SCHOOL McManus Elementary INSPECTOR Michael Fender

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Wall plas	5-10	Kitchen, Admin., halls	1-4
A	9" VFT	5-10	Hall, Kitchen, MPR	1-4
A	TOC	1-5	Admin. office, hall, kitchen, attic	1-4
A	PW & Debr	10-15	Admin attic above men's rr	2-4 PW good - Debris slight
A	PW Str	40-45	Kitchen attic	2-4
A	Air cell	Assumed	Custodial closet	5-2 20%
A	Tran pipe	Assumed	Custodial closet & attic	1-4
B	Wall plas	5-10	RR, hall area, boiler room	1-4 Hall slight damage <1%
B	TOC	1-5	Custodial room & hall	1-4
B	Mud Jnt	25-30	Main boiler room	1-4
B	Counter-top lino	1-5	Classroom areas	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 28, 1992

SCHOOL McManus Elementary INSPECTOR Michael Fender *M*

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
B	9" VFT	1-5	Rm 9 & rest of wing	1-4
B	Air Cell	Assumed	Main B/R room, custodial room attic	1-4
B	Tank Wrap	Assumed	Main B/R room	1-4
B	B/R air cell	Assumed	Main B/R room	1-4
C	Duct wrap	70-75	Sm B/R room, attic	6-4
C	Wall plas	5-10	Old RR, B/R room	1-4
C	9" VFT	5-10	Rm 2 and rest of wing	1-4
D	Wall plas	5-10	Cust. rm, hall, RR area	1-4
D	9" VFT	5-10	Hall, classroom areas	1-4
D	TOC	1-5	Hall & custodial room	1-4
D	PW	20-25	Custodial room	1-4 PW Str-fiber., PW Cnr-ACM

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 26, 1991

SCHOOL McManus Elementary INSPECTOR Robert Peters R.P.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Wall plas	5-10	Kitchen, Admin., halls	1-4
A	9" VFT	5-10	Hall, Kitchen, MPR	1-4
A	TOC	1-5	Admin. office, hall, kitchen, attic	1-4
A	PW & Debr	10-15	Admin attic above men's rr	2-4 PW good - Debris slight
A	PW Str	40-45	Kitchen attic	2-4
A	Air cell	Assumed	Custodial closet	5-2 20%
A	Tran pipe	Assumed	Custodial closet & attic	1-4
B	Wall plas	5-10	RR, hall area, boiler room	1-4 Hall slight damage <1%
B	TOC	1-5	Custodial room & hall	1-4
B	Mud Jnt	25-30	Main boiler room	1-4
B	Counter-top lino	1-5	Classroom areas	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 26, 1991

SCHOOL McManus Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
B	9" VFT	1-5	Rm 9 & rest of wing	1-4
B	Air Cell	Assumed	Main B/R room, custodial room attic	1-4
B	Tank Wrap	Assumed	Main B/R room	1-4
B	B/R air cell	Assumed	Main B/R room	1-4
C	Duct wrap	70-75	Sm B/R room, attic	6-4
C	Wall plas	5-10	Old RR, B/R room	1-4
C	9" VFT	5-10	Rm 2 and rest of wing	1-4
D	Wall plas	5-10	Cust. rm, hall, RR area	1-4
D	9" VFT	5-10	Hall, classroom areas	1-4
D	TOC	1-5	Hall & custodial room	1-4
D	PW	20-25	Custodial room	1-4 PW str-fiber., PW Cnr-ACM

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)



SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 9, 1991

SCHOOL McManus Elementary INSPECTOR Robert Peters R.P.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Wall plas	5-10	Kitchen, Admin., halls	1-4
A	9" VFT	5-10	Hall, Kitchen, MPR	1-4
A	TOC	1-5	Admin. office, hall, kitchen, attic	1-4 (9) hall covered with plywood
A	PW & Debr	10-15	Admin attic above men's rr	2-4 PW good - Debris slight
A	PW Str	40-45	Kitchen attic	2-4
A	Air cell	Assumed	Custodial closet	5-2 20%
A	Tran pipe	Assumed	Custodial closet & attic	1-4
B	Wall plas	5-10	RR, hall area, boiler room	1-4 Hall slight damage <1%
B	TOC	1-5	Custodial room & hall	1-4
B	Mud Jnt	25-30	Main boiler room	1-4
B	Counter- top lino	1-5	Classroom areas	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE July 9, 1991

SCHOOL McManus Elementary INSPECTOR Robert Peters

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
B	9" VFT	1-5	Rm 9 & rest of wing	1-4
B	Air Cell	Assumed	Main B/R room, custodial room attic	1-4
B	Tank Wrap	Assumed	Main B/R room	1-4
B	B/R air cell	Assumed	Main B/R room	1-4
C	Duct wrap	70-75	Sm B/R room, attic	5-6
C	Wall plas	5-10	Old RR, B/R room	1-4
C	9" VFT	5-10	Rm 2 and rest of wing	1-4
D	Wall plas	5-10	Cust. rm, hall, RR area	1-4
D	9" VFT	5-10	Hall, classroom areas	1-4
D	TOC	1-5	Hall & custodial room	1-4
D	PW	20-25	Custodial room	1-4 PW Str-fiber., PW Cnr-ACM

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)