

SIX-MONTH SURVEILLANCE

DISTRICT CHICO UNIFIED SCHOOL DISTRICT DATE 12/27/89

SCHOOL Neal Dow Elementary School INSPECTOR Robert Peters

Robert Peters

BLDG. HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	1 - 5	Admin. area <i>900-905</i>	1
			Classrooms & Hallway	1
A	Lino	5 - 10	Nurses office RR <i>702</i>	1
A	TSI	25 - 30	Admin. attic <i>900-905</i>	1 (needs label)
A	PW Cnr	25 - 30	Admin. attic hallway <i>900-905</i>	1
A	P.W. Str	35 - 40	Admin. attic hallway	1
A	Large P.W. Str	35 - 40	Boiler room <i>913</i>	1
A	Small P.W. Str	30 - 55	Boiler room	1
A	Breeching	20 - 30	Boiler room	1
A	Fire door	Assumed	Boiler room	1

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (DAMAGED 2 * OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES [IF YES, EXPLAIN UNDER COMMENTS]
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

SIX-MONTH SURVEILLANCE

DISTRICT CHICO UNIFIED SCHOOL DISTRICT DATE 12/27/89

SCHOOL Neal Dow Elementary School INSPECTOR Robert Peters

BLDG. HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	2 X 4 FCP	5 - 10	Round house quad <i>all</i>	5 water damaged/ (2) 4 missing/broken in half
B	T-0-C	1 - 5	Round house quad center <i>all</i>	(1)
B	Mud Jnt	25 - 30	Attic <i>all</i>	(1)
A	9" VFT	1 - 5	Kindergarten	(1)
C	T-0-C	1 - 5	Center of building <i>all</i>	(1)
All buildings	Transite panels	Assumed	Above windows	(1)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (DAMAGED 2 & OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES [IF YES, EXPLAIN UNDER COMMENTS]
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED