

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 21, 1994

SCHOOL Neal Dow Elementary INSPECTOR Ron Jones *RJ*

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	1-5	Admin. area	1 - 4 carpeted
			Classrooms & Hallway	1 - 4
A	Lino	5-10	Nurses Office RR	1 - 4
A	TSI	25-30	Admin. Attic	1 (needs label) 4
A	PW Cnr	25-30	Admin. Attic Hallway	1 - 4
A	PW Str	35-40	Admin. Attic Hallway	1 - 4
A	Large PW Str	35-40	Boiler Room	1 - 4
A	Small PW Str	30-55	Boiler Room	1 - 4
A	Breeching	20-30	Boiler Room	1 - 4
A	Fire Door	Assumed	Boiler Room	1 - 4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 21, 1994

SCHOOL Neal Dow Elementary INSPECTOR Ron Jones *RJ*

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
B	2x4 FCP	5-10	Round House Quad	2 - 4 water damage
B	T-O-C	1-5	Round House Quad Center	1 - 4
B	Mud Jnt	25-30	Attic	1 - 4
C	9" VFT	1-5	Kindergarten	1 - 4
C	T-O-C	1-5	Center of Building	1 - 4
All	Tran panl	Assumed	Above Windows	1 - 4

CONDITION CODES

- GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 6, 1994

SCHOOL Neal Dow Elementary INSPECTOR Ron Jones *RJ*

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS  
 MAT.#

A	9" VFT	1-5	Admin. area	1 - 4	carpeted
			Classrooms & Hallway	1 - 4	
A	Lino	5-10	Nurses Office RR	1 - 4	
A	TSI	25-30	Admin. Attic	1	(needs label) 4
A	PW Cnr	25-30	Admin. Attic Hallway	1 - 4	
A	PW Str	35-40	Admin. Attic Hallway	1 - 4	
A	Large PW Str	35-40	Boiler Room	1 - 4	
A	Small PW Str	30-55	Boiler Room	1 - 4	
A	Breeching	20-30	Boiler Room	1 - 4	
A	Fire Door	Assumed	Boiler Room	1 - 4	


CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 6, 1994

SCHOOL Neal Dow Elementary INSPECTOR Ron Jones



HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
B	2x4 FCP	5-10		Round House Quad	2 - 4 water damage
B	T-O-C	1-5		Round House Quad Center	1 - 4
B	Mud Jnt	25-30		Attic	1 - 4
C	9" VFT	1-5		Kindergarten	1 - 4
C	T-O-C	1-5		Center of Building	1 - 4
All	Tran panl	Assumed		Above Windows	1 - 4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)