

DISTRICT Chico Unified School District DATE August 11, 1999

SCHOOL Neal Dow Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	1-5	Admin. area	1 - 4 carpeted
A	9" VFT	1-5	Classrooms & Hallway	1 - 4
A	Lino	5-10	Nurses Office RR	1 - 4
A	TSI	25-30	Admin. Attic	1 (needs label) 4 WO issued
A	PW Cnr	25-30	Admin. Attic Hallway	1 - 4
A	PW Str	35-40	Admin. Attic Hallway	1 - 4
A	Large PW Str	35-40	Boiler Room	1 - 4
A	Small PW Str	30-55	Boiler Room	1 - 4
A	Breeching	20-30	Boiler Room	1 - 4
A	Fire Door	Assumed	Boiler Room	1 - 4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE August 11, 1999

SCHOOL Neal Dow Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
B	2x4 FCP	5-10	Round House Quad	5-7 (Just the damaged ones) (2/99) 5-1 (8/99) 5-2 18 Damaged Tiles w/o issued
B	T-O-C	1-5	Round House Quad Center	1 - 4
B	Mud Jnt	25-30	Attic	1 - 4
C	9" VFT	1-5	Kindergarten	1 - 4
C	T-O-C	1-5	Center of Building	1 - 4
All	Tran panl	Assumed	Above Windows	1 - 4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE 2/25/99

SCHOOL Neal Dow Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	1-5	Admin. area	1 - 4 carpeted ✓
A	9" VFT	1-5	Classrooms & Hallway	1 - 4 ✓
A	Lino	5-10	Nurses Office RR	1 - 4 ✓
A	TSI	25-30	Admin. Attic	1 (needs label) 4 WO issued ✓
A	PW Cnr	25-30	Admin. Attic Hallway	1 - 4 ✓
A	PW Str	35-40	Admin. Attic Hallway	1 - 4 ✓
A	Large PW Str	35-40	Boiler Room	1 - 4 ✓
A	Small PW Str	30-55	Boiler Room	1 - 4 ✓
A	Breeching	20-30	Boiler Room	1 - 4 ✓
A	Fire Door	Assumed	Boiler Room	1 - 4 ✓

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

POSTED
David J. ...

DISTRICT Chico Unified School District DATE 2/25/99

SCHOOL Neal Dow Elementary

INSPECTOR Rob Peters

CONDITION: CODE & COMMENTS

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
B	2x4 FCP	5-10	Round House Quad	5 - 7 Just the damaged ones
B	T-O-C	1-5	Round House Quad Center	1 - 4
B	Mud Jnt	25-30	Attic	1 - 4
C	9" VFT	1-5	Kindergarten	1 - 4
C	T-O-C	1-5	Center of Building	1 - 4
All	Tran panl	Assumed	Above Windows	1 - 4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

5-1