



Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist
Rob Peters

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B024480
Date Received: 11/09/00
Date Analyzed: 11/10/00
Date Printed: 11/10/00
First Reported: 11/10/00

Job ID / Site: Neal Dow

FASI Job ID: 2921-29

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
ND1	10057286						
		Layer: Black Tar	ND				
		Layer: Black Felt	ND				
		Layer: Black Tar	ND				
		Layer: Black Felt	ND				
		Layer: Black Tar	ND				
		Layer: Black Felt	ND				


Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (40%)

ND2	10057287						
		Layer: Black Tar	ND				
		Layer: Black Felt	ND				
		Layer: Black Tar	ND				
		Layer: Black Felt	ND				
		Layer: Black Tar	ND				
		Layer: Black Felt	ND				
		Layer: Black Tar	ND				
		Layer: Black Felt	ND				

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (45%)

ND3	10057288						
		Layer: Black Tar	ND				
		Layer: Black Felt	ND				
		Layer: Black Tar	ND				
		Layer: Black Felt	ND				
		Layer: Black Tar	ND				
		Layer: Black Felt	ND				
		Layer: Black Tar	ND				
		Layer: Black Felt	ND				

Total Composite Values of Fibrous Components: Asbestos:(ND) Cellulose (Trace%) Fibrous Glass (45%)



c: asbestos binders



Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist
Rob Peters

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B024480
Date Received: 11/09/00
Date Analyzed: 11/10/00
Date Printed: 11/10/00
First Reported: 11/10/00

Job ID / Site: Neal Dow

FASI Job ID: 2921-29

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
---------------	------------	---------------	------------------	---------------	------------------	---------------	------------------

Jim Flores

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from the client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

29

Maintenance and Operations
2455 Carmichael Drive
Chico, CA 95928
Phone: (530) 891-3095
Fax: (530) 891-3190

Chico Unified School District

November 7, 2000

Forensic Analytical Specialties, Inc.
3777 Depot Road, Suite 409
San Francisco, CA 94545

Re: Roof Samples

To Whom It May Concern:

Please test the enclosed roof samples for asbestos. Please fax the results to me. My fax number is (530) 891-3190.

Site Sampled:	Neal Dow
Date Sampled:	November 7, 2000
Number of Samples:	Three
Sample #1:	Unit B Roof
Sample #2:	Unit B Roof
Sample #3:	Unit B Roof
Samples Taken by:	Rob Peters

Thank you for your prompt response to this request.

Sincerely,



Rob Peters
Maintenance/Operations Supervisor

RP:dlg
Enclosures



BULK SAMPLE REQUEST FORM

IT NAME & ADDRESS: 2921 Chico Unified School District 2455 Carmichael Drive Chico, CA 95928		PHONE: (916) 891- FAX: (916) 891-3190	DATE:	
		Circle the Method and Turn Around Time 24 hr/12hr/24hr/48hr/Ext		Results Needed:
		<input checked="" type="checkbox"/> PLM: Standard / Point Count		
		CONTACT:		TEM: QUAL. / QUANT. / WATER
P.O.#	JOB #	AA/Flame AA/Furnace ICP		
SITE:		METALS:		

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
NID 1	11/7	UNIT B ROOF
NID 2	11/7	UNIT B ROOF
NID 3	11/7	UNIT B ROOF

Sampled by: ROB PETERS	Date: 11/7/00 Time: 2:30 PM
Relinquished by:	Received By: <i>[Signature]</i>
Date/Time:	Date/Time: 11/9/00 11:34
Relinquished by:	Received By:
Date/Time:	Date/Time:
Relinquished by:	Received By:
Date/Time:	Date/Time:
Relinquished by:	Received By:
Date/Time:	Date/Time:
Relinquished by:	Received By:
Date/Time:	Date/Time:
Relinquished by:	Received By:
Date/Time:	Date/Time:
Relinquished by:	Received By:
Date/Time:	Date/Time:

DISTRICT Chico Unified School District

DATE 8/10/00

SURVEILLANCE
ON SITE

SCHOOL Neal Dow Elementary

INSPECTOR Robert Peters

HOMOG. ASBESTOS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	1-5	Admin. area	1 - 4 carpeted
A	9" VFT	1-5	Classrooms & Hallway	1 - 4
A	Lino	5-10	Nurses Office RR	1 - 4
A	TSI	25-30	Admin. Attic	1 (needs label) 4 WO issued
A	PW Cnr	25-30	Admin. Attic Hallway	1 - 4
A	PW Str	35-40	Admin. Attic Hallway	1 - 4
A	Large PW Str	35-40	Boiler Room	1 - 4
A	Small PW Str	30-55	Boiler Room	1 - 4
A	Breeching	20-30	Boiler Room	1 - 4
A	Fire Door	Assumed	Boiler Room	1 - 4

LABELS
ON

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District

DATE 8/10/00

SCHOOL Neal Dow Elementary

INSPECTOR Robert Peters

HOMOG. ASBESTOS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
B	2x4 FCP	5-10	Round House Quad	5-7 (Just the damaged ones) (2/99) 5-1 (8/99) 5-2 18 Damaged Tiles w/o issued
B	T-O-C	1-5	Round House Quad Center	1 - 4
B	Mud Jnt	25-30	Attic	1 - 4
C	9" VFT	1-5	Kindergarten	1 - 4
C	T-O-C	1-5	Center of Building	1 - 4
All	Tran panl	Assumed	Above Windows	1 - 4

CONDITION CODES

- GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
- CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
- ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
- MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE February 4, 2000

SCHOOL Neal Dow Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	1-5	Admin. area	1 - 4 carpeted
A	9" VFT	1-5	Classrooms & Hallway	1 - 4
A	Lino	5-10	Nurses Office RR	1 - 4
A	TSI	25-30	Admin. Attic	1 (needs label) 4 WO issued
A	PW Cnr	25-30	Admin. Attic Hallway	1 - 4
A	PW Str	35-40	Admin. Attic Hallway	1 - 4
A	Large PW Str	35-40	Boiler Room	1 - 4
A	Small PW Str	30-55	Boiler Room	1 - 4
A	Breeching	20-30	Boiler Room	1 - 4
A	Fire Door	Assumed	Boiler Room	1 - 4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE February 4, 2000

SCHOOL Neal Dow Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
B	2x4 FCP	5-10	Round House Quad	5-7 (Just the damaged ones) (2/99) 5-1 (8/99) 5-2 18 Damaged Tiles w/o issued
B	T-O-C	1-5	Round House Quad Center	1 - 4
B	Mud Jnt	25-30	Attic	1 - 4
C	9" VFT	1-5	Kindergarten	1 - 4
C	T-O-C	1-5	Center of Building	1 - 4
All	Tran panl	Assumed	Above Windows	1 - 4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)