

SIX MONTH SURVEILLANCE
HOMOGENEOUS BM RECORDS

Date of Inspection: 12-02-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Neal Dow Elementary School

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	7	NONE DETECTED	18,500 S	THROUGHOUT ENTIRE BUILDING	(13) SAMPLE HMS-DOW-07 COLLECTED IN 1988.	N/A
M	9" VFT	8	1-5%	19,500 S	ADMINISTRATION AREA, ALL CLASSROOMS, & HALLWAY	Same 12/02/03	N
M	LINOLEUM	10	5-10%	36 S	NURSE'S OFFICE RESTROOM	(2) (5) Pulling Up 12/03/03	N
T	TSI	11	25-30%	2 L	ADMINISTRATION ATTIC	(1) (4) Same 12/02/03	N
T	PIPE WRAP CORNER	12	25-30%	4 JOINTS	ADMINISTRATION ATTIC HALLWAY	(1) (4)	N
T	PIPE WRAP STRAIGHT	13	35-40%	310 L	ADMINISTRATION ATTIC HALLWAY	(1) (4)	N
T	LARGE PIPE WRAP	14	35-40%	105 L	BOILER ROOM	(1) (4)	N
T	SMALL PIPE WRAP	15	30-35%	70 L	BOILER ROOM	(1) (4)	N
T	BREECHING	16	20-30%	65 L	BOILER ROOM	(1) (4)	N
S	TROWELED ON CEILING	17	TRACE	540 S	RESTROOMS	(1) (4)	N
M	DRYWALL & JOINT	97	ASSUMED	2,800 S	OFFICE, STAFF ROOM, AND GIRLS & BOYS RESTROOM	(1)	N
M	FIRE DOOR	98	ASSUMED	2 DOORS	BOILER ROOMS	(1) (4) →	N

CONDIT CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12-02-2003

Inspector: Robert Baughman

District: Chico Unified School District

School: Neal Dow Elementary School							Building: B
Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	4	5-10%	9,350 S	ROUND HOUSE QUAD	(7)	N
S	TROWELED ON CEILING	5	1-5%	260 S	ROUND HOUSE QUAD CENTER	(7)	N
T	MUD JOINTS	6	25-30%	10 JOINTS	ATTIC	(7)	N
M	9" VFT CREAM	96	ASSUMED	150 S	ENTRY OF LIBRARY & STORAGE ROOM	(11) 9" VFT COULD BE UNDER THE CARPET. SAME 12/02/03	N

School: Neal Dow Elementary School							Building: C
Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	TROWELED ON CEILING	2	1-5%	700 S	CENTER OF BUILDING	(1) (4) SAME 12/02/03	N
M	9" VFT	3	1-5%	3,700 S	KINDERGARTEN	(1) 9" VFT COVERED WITH CARPET. SAME 12/02/03	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (if Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACM RECORDS**

Date of Inspection: 12-02-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Neal Dow Elementary School

Building: All Building Exteriors

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	TRANSITE PANELS	99	ASSUMED	5,000 F	ABOVE WINDOWS	(1) (4) SAME 12/02/03	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS BM RECORDS

Date of Inspection: 5/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Neal Dow Elementary School

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Frivable Yes/No
M	12" ACT	7	NONE DETECTED	18,500 S	THROUGHOUT ENTIRE BUILDING	(13) SAMPLE HMS-DOW-07 COLLECTED IN 1988.	N/A
M	9" VFT	8	1-5%	19,500 S	ADMINISTRATION AREA, ALL CLASSROOMS, & HALLWAY	(1) (4) Same 5/9/03	N
M	LINOLEUM	10	5-10%	36 S	NURSE'S OFFICE RESTROOM	(1) (4)	N
T	TSI	11	25-30%	2 L	ADMINISTRATION ATTIC	(1) (4)	N
T	PIPE WRAP CORNER	12	25-30%	4 JOINTS	ADMINISTRATION ATTIC HALLWAY	(1) (4)	N
T	PIPE WRAP STRAIGHT	13	35-40%	310 L	ADMINISTRATION ATTIC HALLWAY	(1) (4)	N
T	LARGE PIPE WRAP	14	35-40%	105 L	BOILER ROOM	(1) (4)	N
T	SMALL PIPE WRAP	15	30-35%	70 L	BOILER ROOM	(1) (4)	N
T	BREECHING	16	20-30%	65 L	BOILER ROOM	(1) (4)	N
S	TROWELED ON CEILING	17	TRACE	540 S	RESTROOMS	(1) (4)	N
M	DRYWALL & JOINT	97	ASSUMED	2,800 S	OFFICE, STAFF ROOM, AND GIRLS & BOYS RESTROOM	(1)	N
M	FIRE DOOR	98	ASSUMED	2 DOORS	BOILER ROOMS	(1) (4) →	N

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS BM RECORDS**

Date of Inspection: 5/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Neal Dow Elementary School

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	4	5-10%	9,350 S	ROUND HOUSE QUAD	(7)	N
S	TROWELED ON CEILING	5	1-5%	260 S	ROUND HOUSE QUAD CENTER	(7)	N
T	MUD JOINTS	6	25-30%	10 JOINTS	ATTIC	(7)	N
M	9" VFT CREAM	96	ASSUMED	150 S	ENTRY OF LIBRARY & STORAGE ROOM	(11) 9" VFT COULD BE UNDER THE CARPET.	N

School: Neal Dow Elementary School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	TROWELED ON CEILING	2	1-5%	700 S	CENTER OF BUILDING	(1) (4) SAME 5/9/03	N
M	9" VFT	3	1-5%	3,700 S	KINDERGARTEN	(1) 9" VFT COVERED WITH CARPET. SAME 5/9/03	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 5/09/2003
Inspector: Robert Peters

District: Chico Unified School District

School: Neal Dow Elementary School

Building: All Building Exteriors

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	TRANSITE PANELS	99	ASSUMED	5,000 F	ABOVE WINDOWS	(1) (4) SAME 5/9/03	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

22231372


IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550

GENERATOR

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CAC002563564	Manifest Document No. 31372	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Chico Unified School Dist 2455 Carmichael Dr Chico, CA 95928			A. State Manifest Document Number 22231372		B. State Generator's ID	
4. Generator's Phone (530) 891-3195		5. Transporter 1 Company Name World Environmental Energy Inc.		6. US EPA ID Number CAR099037483		C. State Transporter's ID [Reserved.]
7. Transporter 2 Company Name		B. US EPA ID Number		D. Transporter's Phone 800-482-5232		E. State Transporter's ID [Reserved.]
9. Designated Facility Name and Site Address B&J Landfill, 6426 Hay Road Vacaville, CA 95687		10. US EPA ID Number CAD982042475		F. Transporter's Phone		G. State Facility's ID
H. Facility's Phone (707) 451-3276		11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol
a. R.Q. ASBESTOS, 9, NA 2212, PGHL, (NAERG #171)				901	CM	00035
b.						Y
c.						
d.						
I. Waste Number State 151						EPA/Other
J. Additional Descriptions for Materials Listed Above FRIABLE ASBESTOS CONTAINING WASTE - Neal Dru		K. Handling Codes for Wastes Listed Above a. 03		b.		
15. Special Handling Instructions and Additional Information 24 HOUR EMERGENCY (530) 676-0599. EPA REGION IX, SMAQMD, 777 12TH ST., SACRAMENTO, CA 95814 ASBESTOS REMOVAL REQUIREMENT 40CFR61, (BAGGED, SEALED, LABELED)						App # 2335
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name ROBERT PETERS		Signature <i>Robert Peters</i>		Month 04		Day 14
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature <i>Randy Miller</i>		Month 04		Day 15
Printed/Typed Name RANDY MILLER		Signature		Month		Day 14
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Month		Day
Printed/Typed Name		Signature		Month		Day
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name <i>[Signature]</i>		Signature <i>[Signature]</i>		Month 04		Day 21

DO NOT WRITE BELOW THIS LINE.



Yellow: TSDf SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS.
 (Generators who submit hazardous waste for transport out-of-state, produce completed copy of this copy and send to DTSC within 30 days.)