

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Nord Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT Bn	1-5	Rooms 3 & 4	(7) Removed
A	PW Cnrs TS1	35-45	Boiler room	(7) Removed
A	Pipewrap	35-45	Boiler room	(7) Removed
B	9" VFT Dark Grey	1-5	MPR & room 3	(1) (4)
B	PW. Str	50-60	Boiler/Storage #2	(7) Removed
B	Mud Jnt	35-45	Boiler/Storage #2	(7) Removed
B	Wall plas	1-5	Boiler/Storage #2	(1) (4)
B	Wall plas	1-5	Kitchen	(2) (4) around door casing
(P)			Portable	No letter

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE December 17, 1996

SCHOOL Nord Elementary INSPECTOR Rob Peters *R.P.*

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT Bn	1-5	Rooms 3 & 4	(7) Removed
A	PW Cnrs T51	35-45	Boiler room	(7) Removed
A	Pipewrap	35-45	Boiler room	(7) Removed
B	9" VFT Dark Grey	1-5	MPR & room 3	(1) (4)
B	PW. Str	50-60	Boiler/Storage #2	(7) Removed
B	Mud Jnt	35-45	Boiler/Storage #2	(7) Removed
B	Wall plas	1-5	Boiler/Storage #2	(1) (4)
B	Wall plas	1-5	Kitchen	(2) (4) around door casing
(P)			Portable	No letter

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Nord Elementary INSPECTOR Rob Peters

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	ASBESTOS	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT Bn	1-5		Rooms 3 & 4	(7) Removed
A	PW Cnrs TS1	35-45		Boiler room	(7) Removed
A	Pipewrap	35-45		Boiler room	(7) Removed
B	9" VFT Dark Grey	1-5		MPR & room 3	(1) (4)
B	PW. Str	50-60		Boiler/Storage #2	(7) Removed
B	Mud Jnt	35-45		Boiler/Storage #2	(7) Removed
B	Wall plas	1-5		Boiler/Storage #2	(1) (4)
B	Wall plas	1-5		Kitchen	(2) (4) around door casing
(P)				Portable	No letter

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

Chico Unified School District
1163 East Seventh Street
Chico, CA 95928-5999
(916) 891-3210

SHORT-TERM WORKER NOTIFICATION UNDER AHERA

40 CFR PART 763.84(d) Requires that the local education agency shall ensure that shortterm workers (e.g. telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations of ACBM and suspected ACBM assumed to be ACM.

SECTION I (to be completed by contractor)

Date: 9/10/96

Contractor organization: Stan Carman, CUSD

Address: 1163 East Seventh St.

Chico CA 95928


Description of work to be performed: Attach wire mold to south wall in classroom #1. Nord


Location(s) of work: Room #1, UNIT A.

SECTION II (to be completed by school district)

Type, amount and location of ACBM in work area: ASBESTOS MANAGEMENT PLAN INDICATES ASBESTOS has been abated.

It is the explicit condition of the performance of this work that no asbestos be disturbed.

 Date: 9/13/96
LEA Designee (school district)

 Date: 9/11/96
(Worker/Contractor Signature)