

FORENSIC ANALYTICAL

Page _____ of _____

FAX TRANSMISSION
Summary of Results
Polarized Light Microscopy

To: Nurd Date/Time: _____
Chico Unified School District

Project :
Report #: 264003

Attn: ROM Sender: Alme

If you do not receive all pages, please contact Sender at (510) 887-8828

C: Chrysotile Cr: Crocidolite
A: Amosite ND: No Asbestos detected
P : Preliminary; subject to review

Sample Number	Asbestos %	Asb. Type(s)	Notes
NO-B-040-P/A	ND		

FAXED TO: 916-891-3190

A hard copy report will follow in the mail. Thank you.

Supervisor Approval: [Signature]

C: Go Kostas Binder



CLIENT NAME & ADDRESS: Chico Unified School District 2455 Carmichael Dr. Chico, CA 95928	PHONE: 916-891-3195 FAX: 916-891-3190	DATE: 2-6-97
	Circle the Method and Turn Around Time _____hr/12hr/24hr/48hr/Ext	Results Needed: Standard Turn-around
	PLM: Standard / Point Count	Gravimetry Prep

CONTACT: Rob Peters		TEM: QUAL / QUANT. / WATER
P.O.# 97-404	JOB #	AA/Flame AA/Fumaco ICP METALS: _____
SITE: Nord School Multipurpose Room		


SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
NO-B-040-P/A	2-6-97	Paint chips from fascia of multipurpose room.
		Please analyse for Asbestos by layer.

Sampled by: Rob Peters		Date: 2-6-97	Time: 10:15am
Relinquished by: Rob Peters		Received By: Ron Jones	
Date/Time: 2-6-97 10:45am		Date/Time: 2-6-97 10:45am Sealed Condition (circle one) YES / NO	
Relinquished by: Ron Jones		Received By: Airborne Express	
Date/Time: 2-6-97 NOON		Date/Time: 2-6-97 NOON Sealed Condition (circle one) YES / NO	

DATE. 2/6/97 10:05 AM.

PAINT SAMPLE TAKEN FROM PAINT OF
MP. ROOM.

Robert Peters



CALIFORNIA STREET

NORD SCHOOL

Scale 0 10 20 30 40

TOTAL BLDG. AREA = 5684.30 SQ. FT.

Phone & Fax (916) 894-2360
Pager (916) 892-3656

Sept 10, 1997

Thomson & Hendricks
60 Declaration Dr. Suite A
Chico, CA 95972

RE: HVAC Project at the Chico Senior
High School Ag Building and the Nord
Elementary School Multi-use Building

To Chico Unified School District,

There was no asbestos used on this HVAC Projects stated above.

Sincerely,

Kim S. Azevedo
Azevedo Construction

SHOP DRAWING REVIEW	
THIS REVIEW IS OF A GENERAL NATURE ONLY. IT IN NO WAY RELIEVES THE CONTRACTOR OF RESPONSIBILITY FOR QUANTITIES, DIMENSIONS, DETAILS AND COMPLIANCE WITH CONTRACT DOCUMENTS.	
<input type="checkbox"/>	NO EXCEPTIONS TAKEN
<input checked="" type="checkbox"/>	MAKE CORRECTIONS NOTED
<input type="checkbox"/>	AMEND AND RESUBMIT
<input type="checkbox"/>	REJECTED - RESUBMIT
<input type="checkbox"/>	SUBMIT SPECIFIED ITEM
THOMSON & HENDRICKS ARCHITECTS & PLANNERS	
10-7-97	DATE <i>ACE</i>

*Guarantees, Lien Releases
O & M manuals, As-Builts*

RECEIVED

OCT - 1 1997

*Need 2 copies of all MSDS
Material Safety Data Sheets
Completed 10-10-97*



Forensic Analytical
Analytical Report

San Francisco • 3777 Depot Road, Suite 409, Hayward, CA 94545 • Phone 510/887-8828 • Fax 510/887-4218
Los Angeles • 2959 Pacific Commerce Dr., Rancho Dominguez, CA 90221 • Phone 310/763-2374 • Fax 310/763-8684

Bulk Material Analysis
Method: 40 CFR 763, Subpart F, Appendix A (AHERA)

Client:

Chico Unified School District
Mr. Ron Jones
2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: 264290
Date Received: 02/14/97
Date Analyzed: 02/14/97

P.O. Num: 97-404

Job ID:

Site: Nord School - Multipurpose Room

Sample Number	Lab Number	Total Asbestos	Total Fibrous Non-Asbestos	(Breakdown by type)
NO-B-050-R Black fibrous tar felts.	19709575	Non-Det. %	25-30%	Fibrous Glass (25-30%)
NO-B-051-R Black fibrous tar felts.	19709576	Non-Det. %	35-40%	Cellulose (15-20%) Fibrous Glass (15-20%)
52-R Black fibrous tar felts.	19709577	Non-Det. %	35-40%	Cellulose (15-20%) Fibrous Glass (15-20%)

David Kahane

David Kahane, C.I.H., Laboratory Director, Hayward Laboratory

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full with approval from Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.



BULK SAMPLE REQUEST FORM

CLIENT NAME & ADDRESS: 2921 Chico Unified School District 2455 Carmichael Drive Chico, CA 95928	PHONE: (916) 891-3195 FAX: (916) 891-3190	DATE: 2/13/97
	Circle the Method and Turn Around Time _____hr/12hr/24hr/48hr/Ext	Results Needed: ASAP
	PLM: Standard / Point Count	Gravimetry Prep
	CONTACT: Rob Peters	
P.O.# 97-404	JOB #	AA/Flame AA/Furnace ICP
SITE: NORD SCHOOL MULTI-PURPOSE ROOM		METALS:

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
NO-B-050-R	2-12-97	Roofing Material from west end of kitchen
NO-B-051-R	2-12-97	Roofing material from N/West end of MP Room
NO-B-052-R	2-12-97	Roofing material from East end of MP Room
		NOTE: Please analyze all above samples for asbestos by layer. Stop at first positive result.

Sampled by: Rob Peters	Date: 2-12-97	Time: 10:00am
Relinquished by: Rob Peters Date/Time: 2-12-97 NOON	Received By: Ron Jones Date/Time: 2-12-97 NOON Sealed Condition (circle one) YES / NO	
Relinquished by: Ron Jones Date/Time: 2-13-97 1:00pm	Received By: Airborne Express Date/Time: 2-13-97 1:00pm Sealed Condition (circle one) YES / NO	

LOW 2/14/97 MAF

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE June 4, 1997

~~December 6, 1995~~

SCHOOL Nord Elementary

INSPECTOR Ron Jones

HOMOG. ASBESTOS MATERIAL

BLDG.	MAT.#	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT Bn	Rooms 3 & 4	(7) Removed
A	PW Cnrs TS1	Boiler room	(7) Removed
A	Pipewrap	Boiler room	(7) Removed
B	9" VFT Dark Grey	MPR & room 3	(1) (4)
B	PW. Str	Boiler/Storage #2	(7) Removed
B	Mud Jnt	Boiler/Storage #2	(7) Removed
B	Wall plas	Boiler/Storage #2	(1) (4)
B	Wall plas	Kitchen	1-5-6 around door casing
(P)		Portable	No letter

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)