

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802. WITHIN CALIFORNIA, CALL 1-800-852-9278.

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CAD 981416050	Manifest Document No. 8 9 1 2 1	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address CHICO UNIFIED SCHOOL DISTRICT 1163 East Seventh Street Chico, CA 95928		Location Parkview Elementary 1770 East Eighth St. Chico, CA. 95928 02-9305		4. State Manifest Document No. 92788121	
4. Generator's Phone (916) 891-3004		6. US EPA ID Number CAD 981455520		5. State Generator ID 92788121	
5. Transporter 1 Company Name BDC SERVICES, INC. REMECH RESTOR. CORP		7. US EPA ID Number CAD 000027703		6. State Transporter ID 92788121	
7. Transporter 2 Company Name BDC Services Inc.		8. US EPA ID Number CAD 981455520		7. State Transporter ID 92788121	
9. Designated Facility Name and Site Address B & J LANDFILL 6426 HAY ROAD VACAVILLE, CA 95687		10. US EPA ID Number CAD 982042475		8. State Facility ID 92788121	

11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers		13. Total Quantity	14. Unit Wt/Vol	15. Waste Number
	No.	Type			
a. "R.O." HAZARDOUS SUBSTANCE SOLID N.O.S. ORM-E NA 9188 (ASBESTOS)	030	D,F	00026	Y	EPA/Other
b.					State
c.					EPA/Other
d.					State

15. Special Handling Instructions and Additional Information
 BDC SERVICES, INC. 766 SO. AYON AZUSA, CA 91702
 ASBESTOS REMOVAL REQUIREMENT 40 CFR 61 (BAGGED, SEALED & LABELED)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of the consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable federal, state and international laws.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: ROBERT PETERS Signature: Robert Peters Month: 07 Day: 20 Year: 93

17. Transporter 1 Acknowledgement of Receipt of Materials
 Printed/Typed Name: UMBRELLA WITT Signature: Umbrella Witt Month: 07 Day: 20 Year: 93

18. Transporter 2 Acknowledgement of Receipt of Materials
 Printed/Typed Name: PAUL BERRY Signature: Paul Berry Month: 07 Day: 22 Year: 93

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
 Printed/Typed Name: Jill A Fisher Signature: Jill A Fisher Month: 07 Day: 28 Year: 93

DO NOT WRITE BELOW THIS LINE.

Yellow: TSDf SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS.
 (Generators who submit hazardous waste for transport out-of-state, produce completed copy of this copy and send to DTSC within 30 days.)

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-9264

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CAAD981141160510401033	Manifest Document No. 1 of 1	2. Page 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address CHICO UNIFIED SCHOOL DISTRICT 1163 East Seventh Street Chico, CA 95928		LOCATION Parkview Elementary 1770 East Eighth St Chico, CA 95928		11. State Manifest Document Number 92640039	
4. Generator's Phone (916) 391-3004		702-9395		12. Date of Manifest 01/07/93	
5. Transporter 1 Company Name B.D.C. Services, Inc. 755 S. Ayon Avenue Azusa, CA 91702		6. US EPA ID Number CAAD981141555210		13. Date of Transport 01/07/93	
7. Transporter 2 Company Name		8. US EPA ID Number		14. Date of Receipt 01/07/93	
9. Designated Facility Name and Site Address P. J. Lamhill 6426 Hay Road Vacaville, CA 95687		10. US EPA ID Number CAAD981210424715		15. Date of Disposal 01/07/93	
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers	13. Total Quantity	14. Unit	
a. "R.O." Hazardous Substance, Solid, N.O.S. ORM-B, NA 9188 (Asbestos)		No. Type		Wt/Vol	
		142 DF	90067	Y	
b. "R.O." HAZARDOUS SUBSTANCE SOLID N.O.S. OR H.S. NA 9188 ASBESTOS		936 BH	90013	Y	
c.					
d.					
15. Special Handling Instructions and Additional Information Asbestos Removal Requirements per 40 CFR 61 - Bagged, Sealed & Labeled REATCH					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of the consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable federal, state and international laws. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name Kobal Peter		Signature Kobal Peter		Month	Day Year
				01	07 93
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name Paul Berry		Signature Paul Berry		Month	Day Year
				01	07 93
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name		Signature		Month	Day Year
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19/					
Printed/Typed Name ANILKA HALI		Signature Anilka Hali		Month	Day Year
				01	07 93

DO NOT WRITE BELOW THIS LINE.

Yellow: TSDf SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS.
 (Generators who submit hazardous waste for transport out-of-state, produce completed copy of this copy and send to DTSC within 30 days.)

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802. WITHIN CALIFORNIA, CALL 1-800-852-9264.

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. **CA1D19181411605104010319** Manifest Document No. _____ 2. Page 1 of 1
 Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
CHICO UNIFIED SCHOOL DISTRICT **LOCATION**
1163 East Seventh Street **Parkview Elementary**
Chico, CA 95928 **1770 East Eighth St**
Chico, CA 95928

4. Generator's Phone **(916) 891-3004** **#02-9395**

5. Transporter 1 Company Name **E.D.C. Services, Inc.** 6. US EPA ID Number
766 S. Ayon Avenue **CA1D191811415151210**
AZUSA, CA 91702

7. Transporter 2 Company Name _____ 8. US EPA ID Number _____

9. Designated Facility Name and Site Address **E & J Landfill** 10. US EPA ID Number
6426 Hay Road
Vacaville, CA 95687 **CA1D19182101412141715**

11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers		13. Total Quantity	14. Unit Wt/Vol
	No.	Type		
a. "B.S." Hazardous Substance, Solid, H.O.S. ORH-E, NA 9189 (Asbestos)	142	DF	99967	Y
b. <i>Asbestos</i>	936	BH	90913	Y
c.				
d.				

15. Special Handling Instructions and Additional Information
Asbestos Removal Requirements per 40 CFR 61 - Bagged, Sealed & Labeled

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of the consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable federal, state and international laws.
Removal
 If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name *Kobal* Signature *Kobal* Month *01* Day *17* Year *1993*

17. Transporter 1 Acknowledgement of Receipt of Materials
 Printed/Typed Name *Paul Berry* Signature *Paul Berry* Month *01* Day *17* Year *1993*

18. Transporter 2 Acknowledgement of Receipt of Materials
 Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.
 Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____

DO NOT WRITE BELOW THIS LINE.

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 27, 1993
 SCHOOL Parkview Elementary INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill Plas	1-5	Admin. area & corridor	(7)
B	9" VFT Gn	1-5	All rooms (white/brown)	(7)
B	Tran panl	Assumed	Under Windows	(1) Good 4
C	9" VFT Gn	1-5	Room 8 & rest of wing	(7)
C	Tran panl	Assumed	Under Windows	(1) Good 4
D	PW Cnr lg	20-25	Boiler Room	(7)
D	Ceill Plas	1-5	Boys & Girls restrooms	(7)
E	PW Cnr sm	15-20	Boiler Room	Couldn't find
E	Ceill Plas	1-5	Staff Room	(1) Good 4
E	Tran panl	Assumed	Under Windows	(1) Good 4
E*	VFT blue		Staff room (storage)	No Test

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 27, 1993
 SCHOOL Parkview Elementary INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
E*	Lino		Classrooms	(1) (4)
E*	VFT gn,wh		Office & Hall	(1) (4)
F	9" VFT bg	1-5	Library work room	(1) Good 4
F	PW Cnr	1-5	RR attic	(1) Good 4
G	PW Cnr	5-10	Rm 18	Nothing found
H	PW Cnr sm	15-20	Rooms off stage	(7)
H	Ceill Plas	1-5	MPR	(7)
H	12" VFT r	1-5	Kitchen	(1) Good 4
H	PW Str	10-15	MPR Stage West	(7)
H	Vent Duct connector	Assumed	Rooms off stage	(7)
H	Tran pipe	Assumed	MPR Kitchen	(1) Good 4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 15, 1993

SCHOOL Parkview Elementary INSPECTOR Ron Jones *RJ*

BLDG.	HOMOG.	ASBESTOS MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill Plas	1-5		Admin. area & corridor	(5) (7) July '93
B	9" VFT Gn	1-5		All rooms (white/brown)	(5) (7) July '93
B	Tran panl	Assumed		Under Windows	(1) Good 4
C	9" VFT Gn	1-5		Room 8 & rest of wing	(5) (7) July '93
C	Tran panl	Assumed		Under Windows	(1) Good 4
D	PW Cnr lg	20-25		Boiler Room	(5) (7) July '93
D	Ceill Plas	1-5		Boys & Girls restrooms	(5) (7) July '93
E	PW Cnr sm	15-20		Boiler Room	Couldn't find
E	Ceill Plas	1-5		Staff Room	(1) Good 4
E	Tran panl	Assumed		Under Windows	(1) Good 4
E*	VFT blue			Staff room (storage)	No Test

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 15, 1993

SCHOOL Parkview Elementary INSPECTOR Ron Jones

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
E*	Lino		Classrooms	(1) (4)
E*	VFT gn, wh		Office & Hall	(1) (4)
F	9" VFT bg	1-5	Library work room	(1) Good 4
F	PW Cnr	1-5	RR attic	(1) Good 4
G	PW Cnr	5-10	Rm 18	Nothing found
H	PW Cnr sm	15-20	Rooms off stage	(5) (7) July '93
H	Ceill Plas	1-5	MPR	(5) (7) July '93
H	12" VFT r	1-5	Kitchen	(1) Good 4
H	PW Str	10-15	MPR Stage West	(5) (7) July '93
H	Vent Duct connector	Assumed	Rooms off stage	(5) (7) July '93
H	Tran pipe	Assumed	MPR Kitchen	(1) Good 4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 15, 1993

SCHOOL Parkview Elementary INSPECTOR Ron Jones

BLDG.	HOMOG.	ASBESTOS	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
H	PW Str	10-15		MPR Stage West	(5) (7) July '93
H	Vent Duct connector	Assumed		Rooms off stage	(5) (7) July '93
H	Tran pipe	Assumed		MPR kitchen	(1) Good 4
H*	VFT Beige			MPR	(5) (7) July '93

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)