

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 26, 1996

SCHOOL Pleasant Valley High INSPECTOR Rob Peters *R.P.*

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	PW Cnr	10-15	Attic area (west end)	7
A	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
B	PW Cnr	10-15	Attic area	7
B	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
C	PW Cnr	1-5	Attic area	1-4
C	Molded blk tabletops	Assumed	Room 20	1-4
C	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
D	PW Cnr	1-10	Attic area	1-4
D	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
E	PW Cnr	1-10	Attic over radio station	1-4
E	Plaster	1-5	Covered walk (outside)	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 26, 1996

SCHOOL Pleasant Valley Senior INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
F/G	Plaster	1-5	Covered walk (outdoors)	1-4
F	PW Str	40-60	Rm 55 B/R room	7 07/29/94
F	PW Str	40-60	Rm 54 storeroom	7
F	Tank wrap	35-45	B/R room	7 07/29/94
F	Debris & PW Cnr	15-20	Attic	1-4
F	Mud jnt	1-10	Room 54 storage	7 07/29/94
F	12 jnts	1-10	Small gym	7 07/29/94
G	Mud Jnt	1-10	Gym	7 07/29/94
H	Plaster	1-5	Covered Walk (outdoors)	1-4
I	Plaster	1-5	Covered Walk (outside)	5 - Fine cracks
I	Trans Wallboard	Assumed	Room 1 - Metal Shop	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE Page 3 of 3

DISTRICT Chico Unified School District DATE December 26, 1996

SCHOOL Pleasant Valley High INSPECTOR Rob Peters

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS
 BLDG. MAT.#

I	12" VFT	1-5	Drafting room	1-4
J	Lino Yell	30-35	Room 1 Snack Bar	1-4
J	Lino Brn	25-30	Room 1 Activities room	1-4
J	Lino Brn	25-30	Stereo storeroom	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Senior High INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Mud Jnt	5-10	Darkroom - Attic	1-4
A	Mesh wrap	15-20	Darkroom - Attic	11
A,B,C	Tran panl	Assumed	Red painted panels along walkways, janitor closets, rr, stairwells	1-4
B	12" VFT	1-5	All rooms	1-4
C	12" VFT	1-5	All rooms	1-4
400	12' VFTS	1-5	Library Entry & Office Area	1-4
400	Mud jnt	5-10	Library Attic	1-4 Repaired Inv. 95-235L
500	Tran panl	Assumed	2 - Kilns	1-4
500	Mud jnts	5-10	Fine Arts	1-4
500	Mud jnts	5-10	Room F-1	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Senior High INSPECTOR Rob Peters

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
S	Heat Shld paper	75-80	Rm S-3	11
S	Bl countr	Assumed	Science Rooms	1-4
S	Mud jnts	5-10	All Rooms	1-4
S	9" VFT Bg	1-5	All Rooms	1-4
S	PW Str	65-70	Rm S-5 Storeroom	2-7 - WO issued
H 700	Bir Ins	25-35	Home Ec Boiler Room	1-4
700	TOC	1-5	Music wing hall ceiling	7
700	TOC	1-5	Instrument storage room	1-4 - WO issued
700	9" VFT y1	5-10	Music Wing Hall	7
700	Tran Peg Board	15-20	Custodial & Band Practice Rooms	(broken & missing) 2-4 WO issued
700	Hold tank	Assumed	Home Ec Heater Room	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Senior High INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
1000	Breeching	Assumed	Woodshop Finishing Room	1-4
900	PW Str	50-55	Girls/Boys Locker Room	1-4
900	PW Str	50-55	Girls/Boys Boil rm crawl sp	1-4
900	Tank Wrap	1-5	Gym Boiler Room	1-4
900	Mud Jnt	5-10	Gym Boiler Room	1-4
900	Boiler rm gasket	85-90	Gym Boiler Room	1-4
900	Wall & ceiling plas	1-5	All rooms except Boiler Room	Retested - no asbestos
800	9" VFT Gy	1-5	Kitchen & MPR	5-7 tiles missing/broken
800	TOC	1-5	All Rooms	2-4 - water stains
800	Tran panl	Assumed	Snack Bar	1-4
800	Tran panl	Assumed	Stage & Cafe	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chico Senior High INSPECTOR Kub Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
800	Mud Jnts	5-10	Under stage	1-4
800	9" VFT		Under stage	1-4
800	PW Str	35-40	Custodial Room	1-4
800	Mud Jnts	5-10	Restroom Teacher's Lounge	1-4
800	Tran Pipe	Assumed	Water Heater Rm (2 pipes)	1-4
1100	Wall Plas	1-5	Ag Classroom 2 (space 3)	1-4
1100	Tran Panl	15-20	Ag Shop Welding Booth	2-4
1100	12" VFTs	Assumed	Classroom	1-4
1100	Tran Pipe	Assumed	Ag Shop (2 pipes)	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Pleasant Valley High INSPECTOR Rob Peters R.P.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	PW Cnr	10-15	Attic area (west end)	7
A	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
B	PW Cnr	10-15	Attic area	7
B	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
C	PW Cnr	1-5	Attic area	1-4
C	Molded blk tabletops	Assumed	Room 20	1-4
C	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
D	PW Cnr	1-10	Attic area	1-4
D	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
E	PW Cnr	1-10	Attic over radio station	1-4
E	Plaster	1-5	Covered walk (outside)	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Pleasant Valley Senior INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
F/G	Plaster	1-5	Covered walk (outdoors)	1-4
F	PW Str	40-60	Rm 55 B/R room	7 07/29/94
F	PW Str	40-60	Rm 54 storeroom	7
F	Tank wrap	35-45	B/R room	7 07/29/94
F	Debris & PW Chr	15-20	Attic	1-4
F	Mud jnt	1-10	Room 54 storage	7 07/29/94
F	12 jnts	1-10	Small gym	7 07/29/94
G	Mud Jnt	1-10	Gym	7 07/29/94
H	Plaster	1-5	Covered walk (outdoors)	1-4
I	Plaster	1-5	Covered Walk (outside)	5 - Fine cracks
I	Trans Wallboard	Assumed	Room 1 - Metal Shop	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Pleasant Valley High INSPECTOR Rob Peters

BLDG.	HOMOG.	ASBESTOS	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
I	12" VFT	1-5		Drafting room	1-4
J	Lino Yell	30-35		Room 1 Snack Bar	1-4
J	Lino Brn	25-30		Room 1 Activities room	1-4
J	Lino Brn	25-30		Stereo storeroom	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)