

9897#2

CERTIFICATION OF COMPLIANCE FOR BUILDING MATERIALS

This is to certify, in accordance with the Environmental Protection Agency requirements, that the materials and equipment used in the construction of the: Relocation of Relocatable Building for the CHICO Unified School District of BUTTE County, California, are asbestos free and are, therefore, not subject to monitoring for asbestos contamination.

Project Name: SITE WORK FOR RELOCATION OF RELOCATABLE BLDGS

Address: PLEASANT VALLEY HEIGHT SCHOOL
CHICO, CA

Contractor: DML CONSTRUCTION

Address: P.O. BOX 862
SUSANVILLE, CA 96130

Signature: [Handwritten Signature]

Title: President

SEPARATE CERTIFICATE IS REQUIRED FOR EACH SITE

RECEIVED
OCT 19 1999
THOMSON & HENDRICK'S



Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist
Rob Peters

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B024533
Date Received: 11/10/00
Date Analyzed: 11/13/00
Date Printed: 11/13/00
First Reported: 11/13/00

Job ID / Site: Pleasant Valley High School

FASI Job ID: 2921-34

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
PU-1	10057660						
		Layer: Black Tar		ND			
		Layer: Black Felt		ND			

Total Composite Values of Fibrous Components: **Asbestos:(ND)** Cellulose (40%) Fibrous Glass (ND)
Comment: Collected on 11/09/2000

PU-2	10057661						
		Layer: Black Tar		ND			
		Layer: Black Felt		ND			


Total Composite Values of Fibrous Components: **Asbestos:(ND)** Cellulose (40%) Fibrous Glass (ND)
Comment: Collected on 11/09/2000

PU-3	10057662						
		Layer: Black Tar		ND			
		Layer: Black Felt		ND			

Total Composite Values of Fibrous Components: **Asbestos:(ND)** Cellulose (40%) Fibrous Glass (ND)
Comment: Collected on 11/09/2000

C: Asbestos binders

Jim Flores



James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

2921-34

Maintenance and Operations
2455 Carmichael Drive
Chico, CA 95928
Phone: (530) 891-3095
Fax: (530) 891-3190

Chico Unified School District

November 9, 200

Forensic Analytical Specialties, Inc.
3777 Depot Road, Suite 409
Hayward, CA 94545

Re: Roof Samples, Pleasant Valley High (PV)

To Whom It May Concern:


Please test the enclosed roof samples for asbestos. Please fax the results to me. My fax number is (530) 891-3190.

Site Sampled:	Pleasant Valley High School
Date Sampled:	November 9, 2000
Number of Samples:	Three
Sample #1:	Unit J Roof
Sample #2:	Unit J Roof
Sample #3:	Unit J Roof

Samples Taken by: Rob Peters

Please provide results within the 24 hour turn around time. Thank you for your prompt response to this request.

Sincerely,



Rob Peters
Maintenance/Operations Supervisor

RP:dlg
Enclosures



BULK SAMPLE REQUEST FORM

IT NAME & ADDRESS:

2921 Chlco Unified School District
2455 Carmichael Drive
Chlco, CA 95928

PHONE: (916) 891-
FAX: (916) 891-3190

DATE:

Circle the Method and
Turn Around Time

Results Needed:

24 hr/12hr/24hr/48hr/Ext

PLM: Standard / Point Count

Gravimetry Prep

CONTACT:

TEM: QUAL. / QUANT. / WATER

P.O.#

JOB #

AA/Flame AA/Furnace ICP

SITE:

METALS:

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
PU 1	11/9/00	ROOF UNITS PVHS
PU 2	↓	ROOF UNITS PVHS
PU 3	↓	ROOF UNITS PVHS
1	11/9/00	UNIT 10 WALKWAY ROOF JAY P
2	↓	UNIT 10 WALKWAY ROOF JAY P
3	↓	UNIT 10 WALKWAY ROOF JAY P
1	11/9/00	PARKVIEW UNIT H
2	↓	PARKVIEW UNIT H
3	↓	PARKVIEW UNIT H

Sampled by: Rob P.

Date: 11-09-00 Time:

Relinquished by:

Received By: [Signature]

Date/Time:

Date/Time: 11/10/00
Sealed Condition (circle one) YES / NO

Inquished by:

Received By:

Date/Time:

Date/Time:
Sealed Condition (circle one) YES / NO

DISTRICT Chico Unified School District DATE 8/10/00

SCHOOL Pleasant Valley High INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	PW Cnr	10-15	Attic area (west end)	7
A	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
B	PW Cnr	10-15	Attic area	7
B	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
C	PW Cnr	1-5	Attic area	1-4
C	Molded blk tabletops	Assumed	Room 20	1-4
C	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
D	PW Cnr	1-10	Attic area	1-4
D	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
E	PW Cnr	1-10	Attic over radio station	1-4
E	Plaster	1-5	Covered walk (outside)	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE _____

SCHOOL Pleasant Valley High INSPECTOR Robert Peters

BLDG.	HOMOG.	ASBESTOS	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
F/G	MAT.#				
F	Plaster	1-5		Covered walk (outdoors)	1-4
F	PW Str	40-60		Rm 55 B/R room	7 07/29/94
F	PW Str	40-60		Rm 54 storeroom	7
F	Tank wrap	35-45		B/R room	7 07/29/94
F	Debris & PW Cnr	15-20		Attic	1-4
F	Mud jnt	1-10		Room 54 storage	7 07/29/94
F	12 jnts	1-10		Small gym	7 07/29/94
G	Mud Jnt	1-10		Gym	7 07/29/94
H	Plaster	1-5		Covered Walk (outdoors)	1-4
I	Plaster	1-5		Covered Walk (outside)	5 - Fine cracks
I	Trans Wallboard	Assumed		Room 1 - Metal Shop	1-4

CONDITION CODES

- GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE 8/10/00

SCHOOL Pleasant Valley High INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
I	12" VFT	1-5	Drafting room	1-4
J	Lino Yell	30-35	Room 1 Snack Bar	1-4
J	Lino Brn	25-30	Room 1 Activities room	1-4
J	Lino Brn	25-30	Stereo storeroom	1-4

CONDITION CODES

- GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
- CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
- ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
- MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE February 4, 2000

SCHOOL Pleasant Valley High INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	PW Cnr	10-15	Attic area (west end)	7
A	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
B	PW Cnr	10-15	Attic area	7
B	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
C	PW Cnr	1-5	Attic area	1-4
C	Molded blk tabletops	Assumed	Room 20	1-4
C	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
D	PW Cnr	1-10	Attic area	1-4
D	Plaster	1-5	Covered walk (outdoors)	Retested - no asbestos
E	PW Cnr	1-10	Attic over radio station	1-4
E	Plaster	1-5	Covered walk (outside)	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE February 4, 2000

SCHOOL Pleasant Valley High INSPECTOR Robert Peters

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
F/G	MAT.#			
	Plaster	1-5	Covered walk (outdoors)	1-4
F	PW Str	40-60	Rm 55 B/R room	7 07/29/94
F	PW Str	40-60	Rm 54 storeroom	7
F	Tank wrap	35-45	B/R room	7 07/29/94
F	Debris & PW Cnr	15-20	Attic	1-4
F	Mud jnt	1-10	Room 54 storage	7 07/29/94
F	12 jnts	1-10	Small gym	7 07/29/94
G	Mud Jnt	1-10	Gym	7 07/29/94
H	Plaster	1-5	Covered Walk (outdoors)	1-4
I	Plaster	1-5	Covered Walk (outside)	5 - Fine cracks
I	Trans Wallboard	Assumed	Room 1 - Metal Shop	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE February 4, 2000

SCHOOL Pleasant Valley High INSPECTOR Robert Peters

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
I	12" VFT	1-5	Drafting room	1-4
J	Lino Yell	30-35	Room 1 Snack Bar	1-4
J	Lino Brn	25-30	Room 1 Activities room	1-4
J	Lino Brn	25-30	Stereo storeroom	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)