

NON-HAZARDOUS
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest Doc. No.

2. Page 1

1 of

02-219

Generator's Name and Mailing Address
CHICO UNIFIED SCHOOL DISTRICT **SITE: PLEASANT VALLEY HIGH**
1163 EAST 4TH ST, CHICO, CA 95928 **1475 EAST AVE, CHICO**

4. Generator's Phone (925-299-3515)

5. Transporter 1 Company Name
JANUS CORPORATION6. US EPA ID Number
CAL 050190758A. Transporter's Phone
925 969-9200

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address
B & J LANDFILL
8428 HAY ROAD
VACAVILLE, CA 95687

10. US EPA ID Number

CAD 982042475

C. Facility's Phone

707 451-327611. Waste Shipping Name and Description
NON FRIABLE WASTE:

12. Containers

No.

Type

13. Total Quantity

14. Unit Wt/Vol

a.

001 CM 00025 Y

b.

c.

d.

Additional Descriptions for Materials Listed Above

E. Handling Codes for Wastes Listed Above

JANUS CORPORATION, 1081 SHARY CIRCLE, CONCORD, CA 94518 24 HR EMER 925-969-9200
EPA REGION IX
BAAQMD, 939 ELLIS STREET, S.F., CA

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name

Signature

Month Day Year

ROBERT PETERS**06/22/02**

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

Gary Morgan**06/23/02**

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

Month Day Year

Bill A Fisher**06/24/02**

TRANSPORTER #1

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Doc. No.	2. Page 1 of 1
3. Generator's Name and Mailing Address Chico Unified School Dist. 1163 E. 4th St. Chico, Ca. 95928		Site: Pleasant Valley HS 1475 E. Ave. Chico, Ca. 95926		
4. Generator's Phone (530) 891-3195				
6. Transporter 1 Company Name Janns Corp.		6. US EPA ID Number CA L000190758	A. Transporter's Phone (925) 969-9200	
7. Transporter 2 Company Name		8. US EPA ID Number	B. Transporter's Phone	
9. Designated Facility Name and Site Address B+J Landfill 6426 Hwy Rd. Ca. 95687		10. US EPA ID Number CA D982042475	C. Facility's Phone (707) 451-3276	
11. Waste Shipping Name and Description		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol
a. Non Friable Asbestos waste:		001 CM	002 Y	
b.				
c.				
d.				
D. Additional Descriptions for Materials Listed Above		E. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Janns Corp., 1081 Shary Circle, Concord, Ca. 94518 - 24 Hr. Emergency EPA Region IX BHAARD, 939 Ellis St., S.F., Ca. (925) 969-9200				
16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting, proper disposal of hazardous waste.				
Printed/Typed Name GARY MORGAN		Signature Gary Morgan Month Day Year 08 02 07		
17. Transporter 1 Acknowledgement of Receipt of Materials				
Printed/Typed Name Gary Morgan		Signature Gary Morgan Month Day Year 08 02 07		
18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature Month Day Year		
19. Discrepancy Indication Space				
20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 16				
Printed/Typed Name J.A. Fisher		Signature J.A. Fisher Month Day Year 08 05 02		

TRANSPORTER #1



Department of Toxic Substances Control



Winston H. Hickox
Agency Secretary
California Environmental
Protection Agency

Edwin F. Lowry, Director
8800 Cal Center Drive
Sacramento, California 95826-3200

Gray Davis
Governor

HAZARDOUS WASTE TRANSPORTER REGISTRATION

NAME AND ADDRESS OF REGISTERED TRANSPORTER:

JANUS CORPORATION
1081 SHARY CIRCLE
CONCORD, CA 94518-2407


TRANSPORTER REGISTRATION NO: 2698

EXPIRATION DATE: 05/31/2003

THIS IS TO CERTIFY THAT THE FIRM NAMED ABOVE IS DULY REGISTERED TO TRANSPORT HAZARDOUS WASTE IN THE STATE OF CALIFORNIA IN ACCORDANCE WITH THE PROVISIONS OF CHAPTER 6.5, DIVISION 20 OF THE HEALTH AND SAFETY CODE AND TITLE 22 OF THE CALIFORNIA CODE OF REGULATIONS, DIVISION 4.5.

THIS REGISTRATION CERTIFICATE MUST BE CARRIED WITH EACH SHIPMENT OF HAZARDOUS WASTE.

FOR REGISTRATION INFORMATION, PLEASE CALL (916) 255-4368.


(AUTHORIZED SIGNATURE)

APR 19 2002
(DATE)

The energy challenge facing California is real. Every Californian needs to take immediate action to reduce energy consumption. For a list of simple ways you can reduce demand and cut your energy costs, see our Web-site at www.dtsc.ca.gov.

♻ Printed on Recycled Paper

**UNITED STATES OF AMERICA
DEPARTMENT OF TRANSPORTATION
RESEARCH AND SPECIAL PROGRAMS ADMINISTRATION**



**HAZARDOUS MATERIALS
CERTIFICATE OF REGISTRATION
FOR REGISTRATION YEAR 2001-2002**

Registrant: **BDC SPECIAL WASTE SERVICES**
Attn: Steve Amromin
766 So Ayon Avenue
Azusa, CA 91702-5123

This certifies that the registrant is registered with the U.S. Department of Transportation as required by 49 CFR Part 107, Subpart G.

This certificate is issued under the authority of 49 U.S.C. 5108. It is unlawful to alter or falsify this document.

Reg. No: 053101 703 014J

Issued: 06/04/01

Expires: 06/30/02

Record keeping Requirements for the Registration Program

The following must be maintained at the principal place of business for a period of three years from the date of issuance of this Certificate of Registration:


- (1) A copy of the registration statement filed with RSPA; and
- (2) This Certificate of Registration

Each person subject to the registration requirement must furnish that person's Certificate of Registration (or a copy) and all other records and information pertaining to the information contained in the registration statement to an authorized representative or special agent of the U. S. Department of Transportation upon request.

Each motor carrier (private or for-hire) and each vessel operator subject to the registration requirement must keep a copy of the current Certificate of Registration or another document bearing the registration number identified as the "U.S. DOT Hazmat Reg. No." in each truck and truck tractor or vessel (trailers and semi-trailers not included) used to transport hazardous materials subject to the registration requirement. The Certificate of Registration or document bearing the registration number must be made available, upon request, to enforcement personnel.

For information, contact the Hazardous Materials Registration Manager, DHM-60 Research and Special Programs Administration, U.S. Department of Transportation, 400 Seventh Street, SW, Washington, DC 20590, telephone (202) 366-4109.

SOLID WASTE FACILITY PERMIT**48-AA-0002**


1. Name and Street Address of Facility: B&J Drop Box Sanitary Landfill 6426 Hay Road Vacaville, CA 95687		2. Name and Mailing Address of Operator: B&J Drop Box Corporation 6426 Hay Road Vacaville, CA 95687 Contact: Mr. Chris Choate		3. Name and Mailing Address of Owner: B&J Drop Box Corporation 6426 Hay Road Vacaville, CA 95687	
4. Specifications:					
a. Permitted Operations:		☒ Solid Waste Disposal Site		☐ Transformation Facility	
		☐ Transfer/Processing Facility (MRF)		☐ Composting Facility	
b. Permitted Hours of Operation:		7 days/week, 24 hours/day. Public tipping area open 8:00 am to 4:00 pm, 7 days a week, except New Year's Day, Easter, Thanksgiving and Christmas Day. Arrangements are made with commercial haulers to bring waste in earlier or later than general hours of 8:00 am to 4:00 pm. Asbestos Containing Waste and other designated wastes receipt from 7:00 am to 4:00 pm, Monday to Friday.			
c. Permitted Maximum Tonnage: (includes all the aggregate waste that enters the landfill for disposal) Hazardous: Asbestos		<u>1,200 tpd/7</u> <u>Total Daily tonnage averaged over 7-day week</u> <u>2,500 tpm</u> <u>Daily Peak tonnage: 2,400 tons</u> <u>Total Tons per month of friable asbestos (See Section 17.16).</u>			
d. Permitted Traffic Volume:		<u>500 vpd</u> <u>Total Vehicles per Day (Averaged over 7-day week)</u> <u>Peak traffic: 650 Vehicles/Day</u>			
e. Key Design Parameters (Detailed parameters are shown on site plans bearing EA and CIWMB validations):					
	Total	Disposal	Transfer/Processing	Composting	Transformation
Permitted Area (in acres)	640 acres	256 acres			
Design Capacity (yd ³ /tons)		28,240,000 cubic yards		Separate Permit	
Max. Elevation (Ft. MSL)		165 ft			
Max. Depth (Ft. BGS)		10 ft			
Estimated Closure Year		70 years (2070)			
Upon a significant change in design or operation from that described herein, this permit is subject to revocation or suspension. The attached permit findings and conditions are integral parts of this permit and supersede the conditions of any previously issued solid waste facility permit.					
5. Approval:  Birgita Corsello, Director <u>Approving Officer Signature</u>			6. Enforcement Agency Name and Address: Solano County LEA Department of Environmental Management 601 Texas Street Fairfield, CA 94533		
7. Date Received by CIWMB: APR 17 2001			8. CIWMB Concurrence Date: APR 25 2001		
9. Permit Issued Date: 5/3/01		10. Permit Review Due Date: 5/3/06		11. Owner/Operator Transfer Date: N/A	

CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD
CENTRAL VALLEY REGION3443 Rouser Road, Suite A
Sacramento, CA 95827-3098
PHONE (916) 253-3000
FAX (916) 253-3015

14 December 1995

CERTIFIED MAIL
Z 079 346 736Mr. Chris Choate
B&J Drop Box, Inc.
6426 Hay Road
Vacaville, CA 95687TRANSMITTAL OF REVISED ADOPTED WASTE DISCHARGE REQUIREMENTS
FOR B&J DROP BOX CORPORATION, B&J DROP BOX SANITARY LANDFILL,
CLASS II LANDFILLS, CLASS III LANDFILLS, SOLANO COUNTYEnclosed is an official copy of Order No. 95-269 as amended by the California Regional Water
Quality Control Board, Central Valley Region, at its last regular meeting.

Please call Patrick Morris at (916) 253-3121 if you have any questions.


GREG K. VAUGHNSenior Engineer
Waste Discharge to Land Unit

Enclosures (to Discharger only): Adopted Order & Standard Provisions

cc: Office of Drinking Water, Department of Health Services, Sacramento
Environmental Management Branch, Department of Health Services, Sacramento
Department of Fish and Game, Region II, Rancho Cordova
Ms. Sadie Galos, California Integrated Waste Management Board, Sacramento
Ms. Betsy Jennings, OCC, State Water Resources Control Board, Sacramento
Ms. Liz Haven, DCWP, State Water Resources Control Board, Sacramento
Solano County Department of Environmental Health, Fairfield
Solano County Planning Department, Fairfield



ACKNOWLEDGEMENT OF NOTIFICATION
OF HAZARDOUS WASTE ACTIVITY

This is to acknowledge that you have filed a Notification of Hazardous Waste Activity for the installation located at the address shown in the box below to comply with Section 3010 of the Resource Conservation and Recovery Act (RCRA). Your EPA Identification Number for that installation appears in the box below. The EPA Identification Number must be included on all shipping manifests for transporting hazardous wastes; on all Annual Reports that generators of hazardous waste, and owners and operators of hazardous waste treatment, storage and disposal facilities must file with EPA; on all applications for a Federal Hazardous Waste Permit; and other hazardous waste management reports and documents required under Subtitle C of RCRA.

EPA ID. NUMBER

CA0902042435

H & J LANDFILL
831 DAVIS ST
VACAVILLE

CA 95688

INSTALLATION ADDRESS

6426 HAY RD
VACAVILLE

CA 95688

EPA Form 8700-12A (4-80)



ACKNOWLEDGEMENT OF NOTIFICATION
OF HAZARDOUS WASTE ACTIVITY

This is to acknowledge that you have filed a Notification of Hazardous Waste Activity for the installation located at the address shown in the box below to comply with Section 3010 of the Resource Conservation and Recovery Act (RCRA). Your EPA Identification Number for that installation appears in the box below. The EPA Identification Number must be included on all shipping manifests for transporting hazardous wastes; on all Annual Reports that generators of hazardous waste, and owners and operators of hazardous waste treatment, storage and disposal facilities must file with EPA; on all applications for a Federal Hazardous Waste Permit; and other hazardous waste management reports and documents required under Subtitle C of RCRA.

EPA ID. NUMBER

CA0902042435

ALTA ENVIRONMENTAL SERVICES, INC.
831 DAVIS ST.
VACAVILLE,

CA 95687

INSTALLATION ADDRESS

831 DAVIS ST.
VACAVILLE,

CA 95687

EPA Form 8700-12A (4-80)

SOLID WASTE FACILITY PERMIT

48-AA-0002

2. Name and Street Address of Facility:

B&J Drop Box Sanitary Landfill
6426 Hay Road
Unincorporated Solano County
Approximately 1/2 Mile West of Highway 113

3. Name and Mailing Address of Operator:

B&J Drop Box Corporation
6426 Hay Road
Vacaville, CA 95687
Contact: Mr. Chris Choate

4. Name and Mailing Address of Owner:

B&J Drop Box Corporation
6426 Hay Road
Vacaville, CA 95687

5. Specifications:

a. Permitted Operations:

☒ Landfill Disposal Site
☐ Composting Facility

☐ Composting Facility
☐ Transfer Station

☐ Processing Facility
☐ Other:

☐ Material Recovery Facility
☐ Transformation Facility

b. Permitted Hours of Operation:

5 a.m. to 10 p.m. during daylight savings and 6:00 a.m. to 7:00 p.m. during the rest of the year for spreading and compacting waste. 8 a.m. to 4:00 p.m. 7 days per week to the general public, except for holidays.

c. Permitted Tonnage per Operating Day:

Total: 1200 tons (Daily tonnage averaged over 7-day week)
Daily Peak Tonnage: 2400 tons

Non-Hazardous - General (includes designated & inert).....1200 tons

Hazardous - Asbestos.....435 tons/month (See Section 17.10)

d. Permitted Traffic Volume:

Total: 500 Vehicles/Day (Averaged over 7-day week)
Peak Traffic: 650 Vehicles/Day

Incoming waste materials.....500 Vehicles/Day
Outgoing waste materials (for disposal).....NA
Outgoing materials from material recovery operations.....NA

e. Key Design Parameters (Detailed parameters are shown on site plans bearing LEA and CIWMB validations):

	Total	Disposal	Transfer	MRF	Composting	Transformation
Permitted Area (in acres)	640 acres	256 acres				
Remaining Refuse Capacity		20,656,000 cubic yards				
Max. Elevation (Ft. MSL)		165 ft.				
Max. Depth (Ft. BGS)		10 ft.				
Estimated Closure Date		48 Years (2044)				

This permit is granted solely to the operator named above, and is not transferable. Upon a change of operator, this permit is no longer valid. Further, upon a significant change in design or operation from the described herein, this permit is subject to revocation or suspension. The attached permit findings and conditions are integral parts of this permit and supersede the conditions of any previous issued solid waste facility permits.

6. Approval:



Approving Officer Signature

Elvina Corralle, Director

Name Title

7. Enforcement Agency Name and Address:

Solano County
Department of Environmental Management
601 Texas Street
Fairfield, CA 94533

8. Received by CIWMB:

MAR 19 1996

9. CIWMB Concurrence Date:

APR 24 1996

10. Permit Review Due Date:

MAY 1 2001

11. Permit Issue Date:

MAY 1 1996

SOLID WASTE FACILITY PERMIT

48-AA-0002

1. Name and Street Address of Facility: B&J Drop Box Sanitary Landfill 6426 Hay Road Vacaville, CA 94967		2. Name and Mailing Address of Operator: B&J Drop Box Corporation 6426 Hay Road Vacaville, CA 94967 Contact: Mr. Chris Choate		3. Name and Mailing Address of Owner: B&J Drop Box Corporation 6426 Hay Road Vacaville, CA 94967					
4. Specifications:									
a. Permitted Operations:		☒ Solid Waste Disposal Site		☐ Transformation Facility					
		☐ Transfer/Processing Facility (MRF)		☐ Composting Facility					
b. Permitted Hours of Operation:		7 days/week, 24 hours/day. Public tipping area open 8:00 am to 4:00 pm, 7 days a week, except New Year's Day, Easter, Thanksgiving and Christmas Day. Arrangements are made with commercial haulers to bring waste in earlier or later than general hours of 8:00 am to 4:00 pm. Asbestos Containing Waste and other designated wastes receipt from 7:00 am to 4:00 pm, Monday to Friday.							
c. Permitted Maximum Tonnage: (Includes all the aggregate waste that enters the landfill for disposal) Hazardous: Asbestos		<table border="1"> <tr> <td>1,200 tpd/7</td> <td>Total Daily tonnage averaged over 7-day week</td> </tr> <tr> <td>2,500 tpm</td> <td>Daily Peak tonnage: 2,400 tons Includes designated & inert Total Tons per month of friable asbestos (See Section 17.18).</td> </tr> </table>				1,200 tpd/7	Total Daily tonnage averaged over 7-day week	2,500 tpm	Daily Peak tonnage: 2,400 tons Includes designated & inert Total Tons per month of friable asbestos (See Section 17.18).
1,200 tpd/7	Total Daily tonnage averaged over 7-day week								
2,500 tpm	Daily Peak tonnage: 2,400 tons Includes designated & inert Total Tons per month of friable asbestos (See Section 17.18).								
d. Permitted Traffic Volume:		<table border="1"> <tr> <td>500 vpd</td> <td>Total Vehicles per Day (Averaged over 7-day week)</td> </tr> <tr> <td></td> <td>Peak traffic: 650 Vehicles/Day</td> </tr> </table>				500 vpd	Total Vehicles per Day (Averaged over 7-day week)		Peak traffic: 650 Vehicles/Day
500 vpd	Total Vehicles per Day (Averaged over 7-day week)								
	Peak traffic: 650 Vehicles/Day								
e. Key Design Parameters (Detailed parameters are shown on site plans bearing EA and CIWMB validations):									
	Total	Disposal	Transfer/Processing	Composting	Transformation				
Permitted Area (in acres)	640 acres	256 acres							
Design Capacity (w/4 tons)		28,240,000 cubic yards		Separate Permit					
Max. Elevation (Ft. MSL)		165 ft							
Max. Depth (Ft. BGS)		10 ft							
Estimated Closure Year		70 years (2070)							
Upon a significant change in design or operation from that described herein, this permit is subject to revocation or suspension. The attached permit findings and conditions are integral parts of this permit and supersede the conditions of any previously issued solid waste facility permit.									
5. Approval:  Birgitta Corsello, Director Approving Officer Signature			6. Enforcement Agency Name and Address: Solano County LEA Department of Environmental Management 601 Texas Street Fairfield, CA 94533						
7. Date Received by CIWMB: APR 17 2001			8. CIWMB Concurrence Date: APR 25 2001						
9. Permit Issued Date: 5/3/01		10. Permit Review Due Date: 5/3/06		11. Owner/Operator Transfer Date: N/A					

This section should contain the following items. Those that are checked (✓) must be added by the District/Owner.

VIII. SUMMARY DOCUMENTS

() Reasons for Abatement Action (LEA's only)

(N/A) Regulatory Agency Inspection Documents

() Communications

(N/A) Photographs

REASONS FOR ABATEMENT

TO BE FILLED
OUT BY THE
DISTRICT

DISTRICT:

SCHOOL:

ABATEMENT LOCATION(S): (See "Scope of Work" for details. Group areas together that fall under the same "reason for abatement".)

ACTION(S) TAKEN: (e.g., removal, encapsulation, repair and cleaning, enclosure)

REASON(S) FOR ACTION: (e.g., Protection of maintenance personnel in an on-going maintenance area; recommendation of management planner; insufficient funds for removal; required for renovation). If the action taken was less than that recommended by the management planner, be as complete as possible in your explanation of actions taken. Use reverse side if more space is needed.

Signature of LEA Designee

ABATEMENT LOCATION(S):

ACTION(S) TAKEN:

REASON(S) FOR ACTION:

Signature of LEA Designee

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: November 18, 2003

District: **Chico Unified School District**

Inspector: **Robert Baughman**

School: **Pleasant Valley High School**

Building: **A**

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	9	NONE DETECTED	1,900 S	COVERED WALK (OUTDOORS)	(13) SAMPLES HMS-PVH-09A & B COLLECTED ON 3-30-88. RETESTED AS PER CUSD - NO ASBESTOS.	N/A
M	1 X 1 FCP'S	94	ASSUMED	300 S	PRINCIPAL'S OFFICE, ASSISTANT PRINCIPAL'S OFFICE, NURSE'S STATION, AND COUNSELING ROOM	(1) SAME 11/18/03	N
M	DRYWALL JOINT COMPOUND	95	ASSUMED	250 S	STAFF RESTROOMS	(1)	N
M	3 X 3 FCP'S	96	ASSUMED	1,000 S	ATTENDANCE AREA CEILING	(1)	N
M	2 X 4 FCP'S	97	ASSUMED	650 S	STAFF ROOM CEILING	(1)	N
M	12" VFT WHITE/BLUE	100	ASSUMED	5,000 S	ATTENDANCE AREA, STAFF ROOM, A-1, AND HALLWAYS AROUND ATTENDANCE AREA	(1) Letter from Reconstruction	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: November 18, 2003

District: **Chico Unified School District**

Inspector: **Robert Baughman**

School: **Pleasant Valley High School**

Building: **B**

Material Class	Material	Homoc. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	9	NONE DETECTED	1,900 S	COVERED WALK (OUTDOORS)	(13) SAMPLES HMS-PVH-09A, B, & C, COLLECTED ON 3-30-88. RETESTED AS PER CUSD - NO ASBESTOS. SAME 11/18/03	N/A
M	9" VFT TAN/BROWN	92	ASSUMED	8,500 S	B1 - B10	(1) (4)	N
M	1 X 3 FCP'S	93	ASSUMED	4,550 S	B2 - B6, B9, & B10	(1) (4) NO ASBESTOS	N
M	1 X 1 FCP'S	94	ASSUMED	1,950 S	B1, B7, & B8	(1) (4) NO ASBESTOS	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: November 18, 2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Pleasant Valley High School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPE WRAP CORNER	5	10-15%	23 L	ATTIC AREA	(1) (4) SAME 11/18/03	N
S	PLASTER	8	NONE DETECTED	250 S	STUDENT RESTROOMS	(1) (4) STUDENT RESTROOMS FKA ROOM 18. SAMPLE HMS-PVH-08C COLLECTED ON 3-30-88.	N/A
S	PLASTER	9	NONE DETECTED	10,000 S	COVERED WALK (OUTDOORS)	(13) RETESTED AS PER CUSD - NO ASBESTOS.	N/A
(13)	9" VFT TAN/BROWN	92	(TRACE) ASSUMED	6,300 S	C1 - C7	(1) (4) SAME 11/18/03	N
M	1 X 3 FCP'S	93	ASSUMED	6,300 S	C1 - C7	(1) (4) NO ASBESTOS	N
M	MOLDED BLACK TABLE TOPS	99	ASSUMED	MULTIPLE TABLES	ROOM 3	(1) (4) ROOM 3 FKA ROOM 20. SAME 11/18/03	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: November 19, 2003

District: Chico Unified School District
School: Pleasant Valley High School

Inspector: Robert Baughman
Building: D

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPE WRAP CORNER	5	1-10%	38 JOINTS	ATTIC AREA	(1) (4) SAME 11/18/03	N
S	PLASTER	9	NONE DETECTED	1,900 S	COVERED WALK (OUTDOORS)	(13) RETESTED AS PER CUSD-NO ASBESTOS.	N/A
M	12" VFT WHITE/BLUE	14	TRACE	925 S	D4-TEACHER'S ROOM & D5	(1) (4) SAMPLE HMS-PVH-14 COLLECTED ON 3-30-88.	N
M	9" VFT BROWN/WHITE	91	ASSUMED (TRACE)	3,500 S	D1 - D3, D4-TEACHERS ROOM, & D5	(2) (5) Room D-3 G.M. @ SITE TO REPAIR	N
M	1 X 3 FCP'S	93	ASSUMED	3,500 S	D1 - D3, D4-TEACHERS ROOM, & D5	(1) NO ASBESTOS	N

School: Pleasant Valley High School

Building: E

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPEWRAP CORNER	5	1-10%	10 L	ATTIC AREA OF E3	(1) (4) SAME 11/18/03	N
S	PLASTER	9	1-5%	1,100 S	COVERED WALK (OUTSIDE)	(2) (5) Large Cracks G.M. @ SITE TO REPAIR	N
M	12" VFT WHITE/BLACK	90	ASSUMED (TRACE)	650 S	E2	(5) (6) MISSING TILES REPLACED AFTER 5/13/03 INSPECTION	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE

HOMOGENEOUS ASBESTOS RECORDS

Date of Inspection: November 19, 2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Pleasant Valley High School

Buildings: F (GIRL'S & BOY'S LOCKER ROOMS)G (EAST GYM)

Material Class	Material	Hom. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	8	NONE DETECTED	3,200 S	GIRL'S LOCKER ROOM, BOY'S LOCKER ROOM, AND RESTROOMS COVERED WALK (OUTDOORS)	(13) SAMPLES HMS-PVH-08D, 08E, & 08G COLLECTED ON 03-30-88.	N/A
S	PLASTER	9	4-6% NONE	2,500 S		(1) (4) TESTED	N
T	DEBRIS & PIPEWRAP CORNER	18	15-20%	DEBRIS 200 S 23 JOINTS	ATTIC (ACCESS IN STOREROOM)	(11) COULD NOT ACCESS THIS AREA.	N
M	DRYWALL	87	ASSUMED NONE	300 S	SNACK BAR	(1) SAME 11/18/03	N
M	12" VFT WHITE/BROWN	88	ASSUMED	600 S	BOY'S AND GIRL'S LOCKER ROOM OFFICES	(1) SAME 11/18/03	N
M	12" FCP'S	89	ASSUMED NONE	3,500 S	EAST GYM	(1) SAME 11/18/03	N

School: Pleasant Valley High School

Building: H (COVERED WALK)

Material Class	Material	Hom. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	9	1-5%	355 S	COVERED WALK (OUTDOORS)	(2) (5) Large Cracks G.M. @ SITE TO REPAIR	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: November 19, 2003

District: **Chico Unified School District**

Inspector: **Robert Baughman**

School: **Pleasant Valley High School**

Building: **E**

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
S	PLASTER	9	1-5%	1,026 S	COVERED WALK (OUTSIDE)	(2) (5) LARGE CRACKS G.M. @ SITE TO REPAIR	N
M	2 X 4 FCP'S	12	NONE DETECTED	812 S	DRAFTING ROOM	(13) SAMPLE HMS-PVH-12 COLLECTED ON 3-30-88.	N/A
M	12" VFT OFF-WHITE	15	1-5%	812 S	DRAFTING ROOM	(1) (4) SAME 11/18/03	N
M	TRANSITE WALLBOARD	98	ASSUMED	350 S	ROOM 1 - METAL SHOP	(1) (4)	N

School: **Pleasant Valley High School**

Building: **J (1-7)**

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
M	DRYWALL & JOINT COMPOUND	77	ASSUMED	3,500 S	J 1-7	(1) (12) PORTABLES J 1-7 WERE MANUFACTURED IN 1997. THE DISTRICT MUST CERTIFY.	N
M	2 X 4 FCP'S	78	ASSUMED	6,300 S	J 1-7	(1) (12) PORTABLES J 1-7 WERE MANUFACTURED IN 1997. THE DISTRICT MUST CERTIFY.	N
M	12" VFT	79	ASSUMED	6,300 S	J 1-7	(1) (12) PORTABLES J 1-7 WERE MANUFACTURED IN 1997. THE DISTRICT MUST CERTIFY.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: November 19, 2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Pleasant Valley High School

Building: M

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	75	ASSUMED	1,000 S	ELECTRICAL ROOM AND BOOKS	(1) (12) THE DISTRICT MUST CERTIFY.	N
M	2 X 4 FCP'S	76	ASSUMED	10,000 S	M1-M11 AND TEACHERS ROOM	(1) (12) THE DISTRICT MUST CERTIFY.	N
M	12" VFT WHITE/GRAY	80	ASSUMED	600 S	M1-M11, ELECTRICAL ROOM, BOOKS, AND TEACHER ROOM	(1) (12) THE DISTRICT MUST CERTIFY.	N
						Letter on file	

School: Pleasant Valley High School

Building: O

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP'S	81	ASSUMED	3,500 S	01A, 01B, AND 2 - 6	(1) (12) THE DISTRICT MUST CERTIFY.	N
						Letter on file	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: November 18, 2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Pleasant Valley High School

Building: P

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
M	2 X 4 FCP'S	81	ASSUMED	3,600	P1 - P4	(2) (5) BROKEN FCP P-1 G.M. @ SITE TO REPAIR	N

School: Pleasant Valley High School

Building: S

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
S	PLASTER	82	ASSUMED	500 S	CUSTODIAN OFFICE	(1) (12) THE DISTRICT MUST CERTIFY.	N
M	12" VFT	83	ASSUMED	500 S	CUSTODIAN OFFICE	(1) (12) THE DISTRICT MUST CERTIFY.	N
M	DRYWALL	84	ASSUMED	1,200 S	STAFF RESTROOMS AND GIRLS & BOYS RESTROOM	(1) (12) THE DISTRICT MUST CERTIFY.	N
M	2 X 4 FCP'S	85	ASSUMED	8,000 S	S1 - S8	(1) (12) THE DISTRICT MUST CERTIFY.	N
M	12" VFT WHITE/GRAY	86	ASSUMED	8,000 S	S1 - S8	(1) (12) THE DISTRICT MUST CERTIFY.	N
						NOTE: THIS BUILDING WAS NOT IDENTIFIED IN THE ORIGINAL INSPECTION BY HMS, INC. CERTIFICATION LETTERS MUST BE OBTAINED OR SAMPLING OF MATERIALS MUST OCCUR TO DETERMINE ASBESTOS CONTENT.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: November 19, 2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Pleasant Valley High School

Building: LIBRARY

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
						(12) THE LIBRARY WAS CONSTRUCTED IN 1994. THE DISTRICT MUST CERTIFY.	N
						→ LETTER ON FILE	

School: Pleasant Valley High School

Building: STUDENT STORE (Unit J) - VENDING MACHINES

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
M	DRYWALL - JOINT COMPOUND	72	ASSUMED	320 S	STUDENT STORE NO ASBESTOS - NEED TO REPAIR WALL ISSUED W/O #8526	(1) (12) THE DISTRICT MUST CERTIFY. SAME 5/12/03	N
S	PLASTER	73	ASSUMED	225 S	VENDING AREA NO ASBESTOS	(1) (12) THE DISTRICT MUST CERTIFY. SAME 5/12/03	N
	LINOLEUM YELLOW/BROWN	74	ASSUMED	550 S	VENDING AREA AND STUDENT STORE	(1) (12) THE DISTRICT MUST CERTIFY. SAME 5/12/03	N
						NOTE: THIS BUILDING WAS NOT IDENTIFIED IN THE ORIGINAL INSPECTION BY HMS, INC. CERTIFICATION LETTERS MUST BE OBTAINED OR SAMPLING OF MATERIALS MUST OCCUR TO DETERMINE ASBESTOS CONTENT.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: November 19, 2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Pleasant Valley High School

Building: VALHALLA

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	72	ASSUMED NONE	1,200 S	<i>Tested</i> NORTH & SOUTH ENDS OF VALHALLA CEILING	(1) (12) THE DISTRICT MUST CERTIFY. SAME 01/18/03	N
M	9" VFT WHITE/BROWN	73	ASSUMED (TRACE)	5,000 S	VALHALLA AREA AND MUSIC ROOM	(2) (5) MUSIC DOOR SITE G.M. TO REPAIR	N
S	PLASTER	74	ASSUMED NONE	5,800 S	GIRLS & BOYS RESTROOMS, VALHALLA CEILING, AND KITCHEN WALLS	(1) (12) THE DISTRICT MUST CERTIFY. SAME 05/12/2003	N
					<i>Tested</i>		
						NOTE: THIS BUILDING WAS NOT IDENTIFIED IN THE ORIGINAL INSPECTION BY HMS, INC. CERTIFICATION LETTERS MUST BE OBTAINED OR SAMPLING OF MATERIALS MUST OCCUR TO DETERMINE ASBESTOS CONTENT.	
						This building was there	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 5/12/03

District: Chico Unified School District

Inspector: Robert Peters

School: Pleasant Valley High School

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
S	PLASTER	9	NONE DETECTED	1,900 S	COVERED WALK (OUTDOORS)	(13) SAMPLES HMS-PVH-09A & B COLLECTED ON 3-30-88. RETESTED AS PER CUSD - NO ASBESTOS.	N/A
M	1 X 1 FCP'S	94	ASSUMED	300 S	PRINCIPAL'S OFFICE, ASSISTANT PRINCIPAL'S OFFICE, NURSE'S STATION, AND COUNSELING ROOM	(1) SAME 5/12/03	N
M	DRYWALL JOINT COMPOUND	95	ASSUMED	250 S	STAFF RESTROOMS	(1)	N
M	3 X 3 FCP'S	96	ASSUMED	1,000 S	ATTENDANCE AREA CEILING	(1)	N
M	2 X 4 FCP'S	97	ASSUMED	650 S	STAFF ROOM CEILING	(1)	N
M	12" VFT WHITE/BLUE	100	ASSUMED	5,000 S	ATTENDANCE AREA, STAFF ROOM, A-1, AND HALLWAYS AROUND ATTENDANCE AREA	(1) ▶	N

Letter from Reconstruction

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 5/12/03

District: Chico Unified School District

Inspector: Robert Peters

School: Pleasant Valley High School

Building: B

Material Class	Material	Homom. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
S	PLASTER	9	NONE DETECTED	1,900 S	COVERED WALK (OUTDOORS)	(13) SAMPLES HMS-PVH-09A, B, & C, COLLECTED ON 3-30-88. RETESTED AS PER CUSD - NO ASBESTOS.	N/A
M	9" VFT TAN/BROWN	92	ASSUMED	8,500 S	B1 - B10	(1) SAME 5/12/03	N
M	1 X 3 FCP'S	93	ASSUMED	4,550 S	B2 - B6, B9, & B10	(1) NO ASBESTOS	N
M	1 X 1 FCP'S	94	ASSUMED	1,950 S	B1, B7, & B8	(1) NO ASBESTOS	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 5/12/03

District: Chico Unified School District

Inspector: Robert Peters

School: Pleasant Valley High School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
T	PIPE WRAP CORNER	5	10-15%	23 L	ATTIC AREA	(1) (4) SAME 5/12/03	N
S	PLASTER	8	NONE DETECTED	250 S	STUDENT RESTROOMS	(1) (4) STUDENT RESTROOMS FKA ROOM 18. SAMPLE HMS-PVH-08C COLLECTED ON 3-30-88.	N/A
S	PLASTER	9	NONE DETECTED	10,000 S	COVERED WALK (OUTDOORS)	(13) RETESTED AS PER CUSD - NO ASBESTOS.	N/A
(13) M	9" VFT TAN/BROWN	92	(TRACE) ASSUMED	6,300 S	C1 - C7	(1) (4) SAME 5/12/03	N
M	1 X 3 FCP'S	93	ASSUMED	6,300 S	C1 - C7	(1) (4) NO ASBESTOS	N
M	MOLDED BLACK TABLE TOPS	99	ASSUMED	MULTIPLE TABLES	ROOM 3	(1) (4) ROOM 3 FKA ROOM 20. SAME 5/12/03	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 5/12/03

District: Chico Unified School District
School: Pleasant Valley High School

Inspector: Robert Peters

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPE WRAP CORNER	5	1-10%	38 JOINTS	ATTIC AREA	(1) (4) SAME 5/12/03	N
S	PLASTER	9	NONE DETECTED	1,900 S	COVERED WALK (OUTDOORS)	(13) RETESTED AS PER CUSD-NO ASBESTOS.	N/A
M	12" VFT WHITE/BLUE	14	TRACE	925 S	D4-TEACHER'S ROOM & D5	(1) (4) SAMPLE HMS-PVH-14 COLLECTED ON 3-30-88.	N
M	9" VFT BROWN/WHITE	91	ASSUMED (TRACE)	3,500 S	D1 - D3, D4-TEACHERS ROOM, & D5	(1) SAME 5/12/03	N
M	1 X 3 FCP'S	93	ASSUMED	3,500 S	D1 - D3, D4-TEACHERS ROOM, & D5	(1) NO ASBESTOS	N

School: Pleasant Valley High School

Building: E

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPEWRAP CORNER	5	1-10%	10 L	ATTIC AREA OF E3	(1) (4) SAME 5/12/03	N
S	PLASTER	9	1-5%	1,100 S	COVERED WALK (OUTSIDE)	(1) (4) SAME 5/12/03	N
M	12" VFT WHITE/BLACK	90	ASSUMED (TRACE)	650 S	E2	(1) 11/12/02 (2) (5) Need w/o to replace missing tiles w/o #8527 ISSUED 5/13/03	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 5/12/03
Inspector: Robert Peters

District: Chico Unified School District

School: Pleasant Valley High School

Buildings: F (GIRL'S & BOY'S LOCKER ROOMS)G (EAST GYM)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	8	NONE DETECTED	3,200 S	GIRL'S LOCKER ROOM, BOY'S LOCKER ROOM, AND RESTROOMS	(13) SAMPLES HMS-PVH-08D, 08E, & 08G COLLECTED ON 03-30-88.	N/A
S	PLASTER	9	4-5% NONE	2,500 S	COVERED WALK (OUTDOORS)	(1) (4) TESTED	N
T	DEBRIS & PIPEWRAP CORNER	18	15-20%	DEBRIS 200 S 23 JOINTS	ATTIC (ACCESS IN STOREROOM)	(11) COULD NOT ACCESS THIS AREA.	N
M	DRYWALL	87	ASSUMED NONE	300 S	SNACK BAR	(1) SAME 5/12/03	N
M	12" VFT WHITE/BROWN	88	ASSUMED	600 S	BOY'S AND GIRL'S LOCKER ROOM OFFICES	(1) SAME 5/12/03	N
M	12" FCP'S	89	ASSUMED NONE	3,500 S	EAST GYM	(1) SAME 5/12/03	N

School: Pleasant Valley High School

Building: H (COVERED WALK)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	9	1-5%	355 S	COVERED WALK (OUTDOORS)	(1) (4) TESTED	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 5/12/03
Inspector: Robert Peters

District: Chico Unified School District

School: Pleasant Valley High School

Building: I

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	9	1-5%	1,026 S	COVERED WALK (OUTSIDE)	(5) FINE CRACKS. Same 5/12/03	N
M	2 X 4 FCP'S	12	NONE DETECTED	812 S	DRAFTING ROOM	(13) SAMPLE HMS-PVH-12 COLLECTED ON 3-30-88.	N/A
M	12" VFT OFF-WHITE	15	1-5%	812 S	DRAFTING ROOM	(1) (4) SAME 5/12/03	N
M	TRANSITE WALLBOARD	98	ASSUMED	350 S	ROOM 1 - METAL SHOP	(1) (4)	N

School: Pleasant Valley High School

Building: J (1-7)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL & JOINT COMPOUND	77	ASSUMED	3,500 S	J 1-7	(1) (12) PORTABLES J 1-7 WERE MANUFACTURED IN 1997. THE DISTRICT MUST CERTIFY.	N
M	2 X 4 FCP'S	78	ASSUMED	6,300 S	J 1-7	(1) (12) PORTABLES J 1-7 WERE MANUFACTURED IN 1997. THE DISTRICT MUST CERTIFY.	N
M	12" VFT	79	ASSUMED	6,300 S	J 1-7	(1) (12) PORTABLES J 1-7 WERE MANUFACTURED IN 1997. THE DISTRICT MUST CERTIFY.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 5/12/03
Inspector: Robert Peters

District: Chico Unified School District

School: Pleasant Valley High School

Building: M

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	75	ASSUMED	1,000 S	ELECTRICAL ROOM AND BOOKS	(1) (12) THE DISTRICT MUST CERTIFY.	N
M	2 X 4 FCP'S	76	ASSUMED	10,000 S	M1-M11 AND TEACHERS ROOM	(1) (12) THE DISTRICT MUST CERTIFY.	N
M	12" VFT WHITE/GRAY	80	ASSUMED	600 S	M1-M11, ELECTRICAL ROOM, BOOKS, AND TEACHER ROOM	(1) (12) THE DISTRICT MUST CERTIFY.	N
						Letter on file	

School: Pleasant Valley High School

Building: O

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP'S	81	ASSUMED	3,500 S	01A, 01B, AND 2 - 6	(1) (12) THE DISTRICT MUST CERTIFY.	N
						Letter on file	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 5/12/03
Inspector: Robert Peters

District: Chico Unified School District

School: Pleasant Valley High School

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Building: P Friable Yes/No
M	2 X 4 FCP'S	81	ASSUMED	3,600	P1 - P4	(1) (12) THE DISTRICT MUST CERTIFY. SAME 5/12/03	N

School: Pleasant Valley High School

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Building: S Friable Yes/No
S	PLASTER	82	ASSUMED	500 S	CUSTODIAN OFFICE	(1) (12) THE DISTRICT MUST CERTIFY.	N
M	12" VFT	83	ASSUMED	500 S	CUSTODIAN OFFICE	(1) (12) THE DISTRICT MUST CERTIFY.	N
M	DRYWALL	84	ASSUMED	1,200 S	STAFF RESTROOMS AND GIRLS & BOYS RESTROOM	(1) (12) THE DISTRICT MUST CERTIFY.	N
M	2 X 4 FCP'S	85	ASSUMED	8,000 S	S1 - S8	(1) (12) THE DISTRICT MUST CERTIFY.	N
M	12" VFT WHITE/GRAY	86	ASSUMED	8,000 S	S1 - S8	(1) (12) THE DISTRICT MUST CERTIFY.	N
						NOTE: THIS BUILDING WAS NOT IDENTIFIED IN THE ORIGINAL INSPECTION BY HMS, INC. CERTIFICATION LETTERS MUST BE OBTAINED OR SAMPLING OF MATERIALS MUST OCCUR TO DETERMINE ASBESTOS CONTENT.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 5/12/03

District: Chico Unified School District

Inspector: Robert Peters

School: Pleasant Valley High School

Building: LIBRARY

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
						(12) THE LIBRARY WAS CONSTRUCTED IN 1994. THE DISTRICT MUST CERTIFY.	N
						LETTER ON FILE	

School: Pleasant Valley High School

Building: STUDENT STORE (Unit J) - VENDING MACHINES

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
M	DRYWALL - JOINT COMPOUND	72	ASSUMED	320 S	STUDENT STORE NO ASBESTOS - NEED TO REPAIR WALL ISSUED W/O #8526	(1) (12) THE DISTRICT MUST CERTIFY. SAME 5/12/03	N
S	PLASTER	73	ASSUMED	225 S	VENDING AREA NO ASBESTOS	(1) (12) THE DISTRICT MUST CERTIFY. SAME 5/12/03	N
	LINOLEUM YELLOW/BROWN	74	ASSUMED	550 S	VENDING AREA AND STUDENT STORE	(1) (12) THE DISTRICT MUST CERTIFY. SAME 5/12/03	N
						NOTE: THIS BUILDING WAS NOT IDENTIFIED IN THE ORIGINAL INSPECTION BY HMS, INC. CERTIFICATION LETTERS MUST BE OBTAINED OR SAMPLING OF MATERIALS MUST OCCUR TO DETERMINE ASBESTOS CONTENT.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS