

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 28, 1993

SCHOOL Shasta Elementary INSPECTOR Ron Jones

BLDG.	HOMOG.	ASBESTOS	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	5-10		Classrms, MPR, Kit, Storage	1-4
A	PW Cnr	1-5		Attic	2-4
A	PW Str	30-35		Attic	1-4
A	PW Str	15-20		Main boiler room	1-4
A	Lg Dia PW Cnr	Assumed		Main boiler room	1-4
A	Sm Dia PW Cnr	5-10		Main boiler room	1-4
A	Surf Plas	1-5		Storage (RR)	2-4 <5%
A	Tran pipe	Assumed		Main boiler room	1-4
B	Tran panl	Assumed		Outside building	1-4
C	Tran panl	Assumed		Outside building	1-4
D	VFT	Assumed		Old portables	None present (carpet)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 16, 1993

SCHOOL Shaata Elementary INSPECTOR Ron Jones

BIDG. HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BIDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	5-10	Classrms, MPR, Kit, Storage	1-4
A	PW Cnr	1-5	Attic	2-4
A	PW Str	30-35	Attic	1-4
A	PW Str	15-20	Main boiler room	1-4
A	Lg Dia PW Chr	Assumed	Main boiler room	1-4
A	Sm Dia PW Chr	5-10	Main boiler room	1-4
A	Surf Plas	1-5	Storage (RR)	2-5 <5%
A	Tran pipe	Assumed	Main boiler room	1-4
B	Tran panl	Assumed	Outside building	1-4
C	Tran panl	Assumed	Outside building	1-4
D	VFT	Assumed	Old portables	None present (carpet)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)