

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Shasta Elementary INSPECTOR Rob Peters

BLDG.	HOMOG.	ASBESTOS	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	5-10		Classrms,MPR,Kit,Storage	1-4
A	PW Cnr	1-5		Attic	2-4
A	PW Str	30-35		Attic	1-4
A	PW Str	15-20		Main boiler room	1-4
A	Lg Dia PW Cnr	Assumed		Main boiler room	1-4
A	Sm Dia PW Cnr	5-10		Main boiler room	1-4
A	Surf Plas	1-5		Storage (RR)	1-4
A	Tran pipe	Assumed		Main boiler room	1-4
A	Pipewrap	5-20		MPR Storage	1-4
B	Tran panl	Assumed		Outside building	1-4
C	Tran panl	Assumed		Outside building	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Shasta Elementary INSPECTOR Rob Peters

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS
 BLDG. MAT.#

C	Drywall	1-5 skim coat	All Rooms	1-4
D	VFT	Assumed	Old portables	None present (carpet)
Port	12" VFT	Assumed	Classrooms 16,17,18	1-4
Port	2x4 FCP	Assumed	Classrooms 16,17,18	1-4
Port	Drywall	Assumed	Classroom 16,17,18 behind tagboard	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE January 4, 1996
 SCHOOL Shasta Elementary INSPECTOR Ron Jones

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	5-10	Classrms,MPR,Kit,Storage	1-4
A	PW Cnr	1-5	Attic	2-4
A	PW Str	30-35	Attic	1-4
A	PW Str	15-20	Main boiler room	1-4
A	Lg Dia PW Cnr	Assumed	Main boiler room	1-4
A	Sm Dia PW Cnr	5-10	Main boiler room	1-4
A	Surf Plas	1-5	Storage (RR)	1-4
A	Tran pipe	Assumed	Main boiler room	1-4
A	Pipewrap	5-20	MPR Storage	1-4
B	Tran panl	Assumed	Outside building	1-4
C	Tran panl	Assumed	Outside building	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE January 4, 1996

SCHOOL Shasta Elementary INSPECTOR Ron Jones *RJ*

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS
 BLDG. MAT.#

C	Drywall	1-5 skim coat	All Rooms	1-4
D	VFT	Assumed	Old portables	None present (carpet)
Port	12" VFT	Assumed	Classrooms 16,17,18	1-4
Port	2x4 FCP	Assumed	Classrooms 16,17,18	1-4
Port	Drywall	Assumed	Classroom 16,17,18 behind tagboard	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)