SIX-MONTH SURVEILLANCE

Page 1 of 3

DISTRICT Chico Unified School District DATE.

SCHOOL Bidwell Junior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
100	Ceil Plas	1-5	All rooms except kitchen	1=4)
100	9" VFT	Assumed	All rooms except store	له-1
100	PW Str	30-35	Chair Store Room	(1-4)
100	PW Cnr	Assumed	Kitchen B/R Room	1-4
100	B/R Lin	60-65	Kitchen B/R Room	2-4 Bebris on floor we#22827
100	Tran pipe	Assumed	Kitchen B/R Room	1-4
100	Fan Vent Insul	Assumed	Fan Rooms	11 Could not find
200	9" VFT	Assumed	All Rooms	1-4
200	Plaster	1-5	All Rooms	1-4
300	Drywall	Assumed	Rm 250, RR, Teach. room	1-4
300	9" VFT	Assumed	Rm 250, halls, rr, teach. All Classrms except 105-6,7	(1-4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

(11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS) MISC:

SIX-MONTH SURVEILLANCE

Page 2 of 3

DISTRICT Chico Unified School District DATE January 8, 1996 7-11-97						
SCHOOL	Bidwell J	unior High		INSPECTOR Ron Jones		
BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS		
300	Ceil Plas	1-5	Rm 250, halls, rr, teach (1-4		
300	Ceil Plas	1-5	All classrms except 105-6-7	1-4		
300	Tran pipe	Assumed	Closet of Room 405	1-9		
400	Tran panl	Assumed	Panels in both locker rooms;	1-4)		
400	PW Cnr	Assumed	PE Boiler room & tunnel	1-4		
400	Tank Wrap	Assumed	PE Boiler room	1-4		
500	Drywall	1	All rooms	2-4 damage-office,practice rm		
500	9" VFT	Assumed	All rooms	1-4		
500	Duct Insl	90-95	Duct work - ceil. & walls	11 Could not find		
600	Tran panl	Assumed	Metal Shop	(1-4)		
600	9" VFT	Assumed	Room 8 and office	1-4)		

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS) MISC: Page 3 of 3 SIX-MONTH SURVEILLANCE

7-11-97 DISTRICT Chico Unified School District DATE January 8, 1996 SCHOOL Bidwell Junior High INSPECTOR Ron Jones HOMOG. ASBESTOS CONDITION: CODE & COMMENTS BLDG. MAT.# MATERIAL LOCATION 600 Asb. Curt | Assumed Metal Shop 1-4 Above FCPs Rm 208 near sink (Rm 9) 600 Mud Jnts 1-5 600 12" VFT Room 9 Assumed 1-4 9" VFT All Classrooms 700 Assumed 1-4 Above FCPs along No. wall Rooms 408 & 409 700 Mud Jnts 1-5 1-4 9" VFT 800 Assumed Library Gym, B/R, Storeroom 900 PW Str 15-20 Gym, B/R, Storeroom 5-10 1-4 900 PW Cnr

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)