HMS, INC. HAZARD MANAGEMENT SERVICES, INC.

CHICO UNIFIED SCHOOL DISTRICT CHICO JUNIOR HIGH SCHOOL AHERA THREE-YEAR REINSPECTION SUMMARY APRIL, 1992

Attached you will find a computer print-out of your original "Homogeneous Materials Record Sheets". You will find these sheets easier to read that the original copies. If additional samples were collected at this site, the results are listed at the end of the new "homogeneous" sheets. A comment on drywall sampling and lab accreditation sheets are added as appropriate.

At this site all previously or currently identified asbestos-containing materials were in good condition, i.e., non-friable.

We have given you a new index to insert into your management plan to account for new sections VIII and IX. We have added section VIII in which you should include results of your six-month inspections. We have also included a sheet on drywall sampling with recommendations on handling drywall. We also want to remind you that new buildings or portables must either be inspected or exempted by letter by your architect or builder.

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: 4 PORTABLES

Homog.

Mat. # Locations % Asb Footage Codes Material 80 BEHIND TAG BOARD 01-99 6000 S 1-4 DRYWALL (ASSUMED) 3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged

Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: A

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
Condition	1 spection Notes of Material: Condition? NO	GOOD	01-05	40 S	1-4
Condition	2 spection Notes of Material: Condition? No	GOOD	01-05	5 S	1-4
Condition	2 pection Notes of Material: Condition? YE	MAIN HLLWY CORRIDOR S Abated? REMOVED	01-05	780 S	0-Y
Condition	5 spection Notes of Material: 6 Condition? NO	GOOD	01-05	600 S	1-4
Condition	pection Notes of Material: (Condition? NO	GOOD	01-05	4992 S	1-4
Condition	5 pection Notes of Material: (Condition? NO	GOOD	01-05	300 S	1-4

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: A

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
MUD JNTS 3 Year Inspect Condition of I Change in Cond Comments:	tion Notes Material:	GOOD	01-05	3 Ј	1-4
CIELING PLAST 3 Year Inspect Condition of P Change in Condition	tion Notes (aterial:	GOOD	01-05	4992 S	1-4
CIELING PLAST 3 Year Inspect Condition of P Change in Cond Comments:	tion Notes (aterial:	GOOD	01-05	10000 s	1-4
CIELING PLAST 3 Year Inspect Condition of P Change in Cond Comments:	tion Notes Material:	: GOOD	01-05	630 S	1-4
CEILING MATER 3 Year Inspect Condition of 1 Change in Cond Comments:	tion Notes Material:	GOOD	01-05	60 S	1-4
PW STR 3 Year Inspect Condition of P Change in Cond Comments:	Material:	GOOD	25-50	40 L	1-4

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: A

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
Condition of	10 ection Notes f Material: ondition? NO		25-50	37 L	1-4
Condition of	11 ection Notes f Material: ondition? NO		50-55	10 Ј	1-4
Condition of	11 ection Notes f Material: ondition? NO		50-55	8 Ј	1-4
Condition of	14 ection Notes f Material: ondition? NO		01-05	300 S	1-4
Condition of	ection Notes f Material:		01-99 (Assumed)	50 L	1-4
Condition of		STAGE AREA : S Abated? REMOVED	40-45	115 L	0-7

Codes:

Change in Condition: (N or 4) No (Y) Yes (Please explain) Abated:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged

(R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: A

Homog.

Material Mat. # Locations % Asb Footage Codes

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old

HMRs.

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: B

Material	Homog. Mat. #	Location	s 	% Asb	Footage	Codes
CEILING PLAS 3 Year Inspe Condition of Change in Co Comments:	ction Notes Material:	GOOD	& UPPER WALL	01-05	6000 S	1-4
9" VFTs (NEW 3 Year Inspe Condition of Change in Co. Comments:	ction Notes Material:	:	REMOVED	01-05	250 S	0 - Y
12" VFTs 3 Year Inspe Condition of Change in Co Comments:	ction Notes Material:	::	REMOVED	01-05	250 S	0-Y
9" VFTs 3 Year Inspe Condition of Change in Co Comments:	ction Notes Material:		REMOVED	01-05	4000 S	0 - Y

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp
These Reports should be placed in your AHERA file. Do not throw away old
HMRs.

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: C

Material	Homog. Mat. #	Locations		Footage	
3 Year Inspe Condition of	ection Notes Material:		01-05	153 S	1-4
CEILING PLAS 3 Year Inspe Condition of Change in Co Comments:	ection Notes Material:	3:	01-05	380 S	1-4
9" VFT 3 Year Inspectondition of Change in Co	ection Notes Material:	200,2,4,6, AND 208	05-10	4160 S	0-Y
3 Year Inspe Condition of	ction Notes Material:	RM 22 (RUST)	05-10	1000 S	0-Y

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd (I) Isolated and Restricted

(I) Isolated and Restricte

Inspected By: Mike Sharp
These Reports should be placed in your AHERA file. Do not throw away old
HMRs.

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: D

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
9"VFTs 3 Year Inspection of Change in Comments:	ection Notes f Material:		01-05	153 S	1-4
CEILING PLAS 3 Year Inspection of Change in Comments:	ection Notes f Material:	3:	01-05	380 S	1-4
9" VFTs 3 Year Inspection of	ection Notes f Material:		01-05	4160 S	0-Y

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged

Comments:

Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: E

Material	Homog. Mat. #	Locations	% Asb	Footage Codes
3 Year Inspe Condition of	ction Notes Material:		01-05	153 S 1-4
CEILING PLAS 3 Year Inspe Condition of Change in Co Comments:	ction Note: Material:	3:	01-05	380 S 1-4
9" VFTs 3 Year Inspe Condition of Change in Co Comments:	ction Notes Material:	ALL ROOMS 3: ES Abated? REMOVED	05-10	4160 S 0-Y

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged Change in Condition: (N or 4) No (Y) Yes (Please explain) (R) Repaired (M) Removed (E) Enclsd Abated: (I) Isolated and Restricted

Inspected By: Mike Sharp These Reports should be placed in your AHERA file. Do not throw away old HMRs.

School Dist: Chico USD School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: F

		BUILDING: F			
Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
9" VFTs 3 Year Inspe Condition of Change in Co Comments:	ction Notes Material:		01-05	153 S	1-4
CEILING PLAS 3 Year Inspe Condition of Change in Co Comments:	ction Notes Material:		01-05	380 S	1-4
9" VFTs 3 Year Inspe Condition of Change in Co Comments:	Material:	ALL RMS EXCEPT 504	05-10	3600 S	0-Ұ
PW STR 3 Year Inspe Condition of Change in Co	ction Notes Material:		40-85	15 L	1-4
	· ·	TSI has been removed ng and roof.	d. TSI rema	ins	
9" VFTs 3 Year Inspe Condition of Change in Co Comments:	Material:	504 S: S Abated? REMOVED	05-10	900 S	0-Y
Comments: All	Material: ndition? NO accessible	RM 506 GOOD Abated? NO TSI has been removed g and roof.	01-99 (ASSUMED) d. TSI rema		1-4

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged Change in Condition: (N or 4) No (Y) Yes (Please explain)

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: F

Homog.

Mat. # Locations % Asb Footage Codes Material

Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old

HMRs.

School: CHICO JUNIOR HIGH

School Dist: Chico USD
Date Inspected: 04/14/92

BUILDING: G

Material	Homog. Mat. #	Locations	% Asb	Footage Codes
10" PW STR 3 Year Inspe Condition of Change in Co Comments:	ction Notes Material:	BLR RM 3: CS Abated? REMOVED	55-60	300 L 0-Y
8" PW STR 3 Year Inspe Condition of Change in Co Comments:	Material:	BLR RM	55~60	20 L 0-Y
10" PW STR 3 Year Inspe Condition of Change in Co Comments:	Material:	TUNNEL CHASE :: CS Abated? REMOVED	55-70	2500 L 0-Y
BLR TANK WRA 3 Year Inspe Condition of Change in Co Comments:	ction Notes Material:	BLR RM	60-70	400 S 0-Y
STRG TANKWRA 3 Year Inspe Condition of Change in Co Comments:	ction Notes Material:	BLR RM:	60-70	40 S 0-Y
PW STR 3 Year Inspe Condition of Change in Co Comments:	ction Notes Material:	BLR RM : S Abated? REMOVED	35-40	30 L 0-Y

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: G

Homog.

Mat. # Locations Material % Asb Footage Codes 31 SHOP OVERHEAD STRG 35-40 PW STR 36 L 0-Y 3 Year Inspection Notes:

Condition of Material:

Change in Condition? YES Abated? REMOVED

Comments:

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp These Reports should be placed in your AHERA file. Do not throw away old HMRs.

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: H

Material	Homog. Mat. #	Locations	% Asb	Footage Codes
3 Year Inspection of	ection Notes Material:	WOOD SHOP OFFICE S: ES Abated? REMOVED	01-05	120 S 0-Y
3 Year Inspe Condition of	ection Notes Material:	WOOD SHOP CLS RM 3: ES Abated? REMOVED	01-05	630 S 0-Y
3 Year Inspe Condition of	ection Notes Material:	WOOD SHOP OFFICES	01-05	120 S 0-Y

Codes:

Change in Condition:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged

Abated:

(N or 4) No (Y) Yes (Please explain) (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp

School Dist: Chico USD

School: CHICO JUNIOR HIGH

01-05 7276 S 1-4

Date Inspected: 04/14/92

BUILDING: J

-	α m	α	

Material Mat. # Locations % Asb Footage Codes

9" VFTs 2 AADMIN OFFICE & HALL 01-05 4900 S 1-4

3 Year Inspection Notes:
Condition of Material: GOOD
Change in Condition? NO Abated? NO
Comments:Removed from hall and most office areas, may remain

Comments:Removed from hall and most office areas, may remain under carpet. Principal's Office has some still exposed.

CEILING PLAST 8 ALL ROOMS

3 Year Inspection Notes:
Condition of Material: GOOD
Change in Condition? NO Abated? NO

Change in Condition? NO Abated? NO Comments:

PW STR 10 WORK RM CLOSET 25-50 30 L 1-4

3 Year Inspection Notes: Condition of Material: GOOD

Change in Condition? NO Abated? NO

Comments:

PW JNTs 11 WORK RM CLOSET 50-55 10 J 1-4

3 Year Inspection Notes: Condition of Material: GOOD

Change in Condition? NO Abated? NO

Comments:

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged Change in Condition: (N or 4) No (Y) Yes (Please explain)

Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: K

Material	Homog. Mat. #	Locations	% Asb	Footage Codes
3 Year Inspection of	ection Note: f Material:		01-05	4200 S 1-4
3 Year Inspection of	ection Note: f Material:		05-10	900 S 1-4
3 Year Inspection of	ection Note: f Material:		01-99 (Assumed)	400 L 1-4

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged

Change in Condition:

(N or 4) No (Y) Yes (Please explain) (R) Repaired (M) Removed (E) Enclad

Abated:

(I) Isolated and Restricted

Inspected By: Mike Sharp

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: L

Homog.

Material Mat. # Locations % Asb Footage Codes

9" VFTs 20 ALL CLS RMS 05-10 5018 S 1-4

3 Year Inspection Notes:

Condition of Material: GOOD

Change in Condition? NO Abated? NO

Comments: Some tiles have been removed and replaced with 12"

VFTs, only small patches though.

75 Under Cabinets PW Strs 01-99 400 S 1-4 (ASSUMED)

3 Year Inspection Notes:

Condition of Material: GOOD

Change in Condition? NO Abated? NO

Comments:

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged Change in Condition: (N or 4) No (Y) Yes (Please explain)

(R) Repaired (M) Removed (E) Enclsd Abated:

(I) Isolated and Restricted

Inspected By: Mike Sharp

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: M

Material	Homog. Mat. #	Locations	% Asb	Footage Codes
9" VFTs 3 Year Inspection of Change in Comments:	f Material:		05-10	5018 S 1-4
PW STRs 3 Year Inspe	75 ection Note:	UNDER CABINETS	01-99 (ASSUMED)	400 S 0-

Codes:

Comments:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged

Change in Condition? NO Abated? NO

Condition of Material: NO SURVEILLANCE DATA

Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: N

Material	Homog. Mat. #	Locations	% Asb	Footage Codes
3 Year Inspe Condition of	ction Notes Material:		01-05	632 S 1-4
PW STR 3 Year Inspectondition of Change in Concents:	ction Notes Material:	UNDER RAISED FLOOR S: CS Abated? REMOVED	25-50	35 L O-Y
9" VFTs 3 Year Inspection of Change in Comments:	ction Notes Material:	CHORAL RM	01-05	1752 S 0-Y
9" VFTs 3 Year Inspection of Change in Comments:	ction Notes Material:	OFFICES S: CS Abated? REMOVED	01-05	300 S 0-Y
9" VFTs 3 Year Inspection of Change in Comments:	Material:	RM503 & PRACTICE RMS	05-10	2900 S 0-Y

Codes:

Change in Condition:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged (N or 4) No (Y) Yes (Please explain)

Abated:

(R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: 0

Material	Homog. Mat. #	Locations	% Asb	Footage Codes
9" VFTs 3 Year Inspection of Change in Comments:	ection Note: f Material:		01-05	342 S 1-4
PWSTR 3 Year Inspection of Change in Comments:	ection Note: F Material:	FAN UNITS ENCLOSED 4 3: ES Abated? REMOVED	60-70	17 L 0-Y
PWSTR 3 Year Inspection of Change in Condition	ection Note: f Material:		60-70	40 L 0-Y

Codes:

General Condition: Change in Condition:

(1) Good (2) Damaged (3) Sig. Damaged (N or 4) No (Y) Yes (Please explain) (R) Repaired (M) Removed (E) Enclsd

Abated:

(I) Isolated and Restricted

Inspected By: Mike Sharp

School Dist: Chico USD

Date Inspected: 04/14/92

School: CHICO JUNIOR HIGH

BUILDING: P

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
9" VFTs 3 Year Inspection of 1 Change in Concomments: Coul	tion Notes Material: dition? NO	NO SURVEILLANCE DATA Abated? NO		630 S	0-
PW STR 3 Year Inspection of December of Condition Concomments:	tion Notes Material:	BLR RM 3: ES Abated? REMOVED	50-70	350 L	0 - Y
5" PW STR 3 Year Inspection of I Change in Concomments:	tion Notes Material:		45-50	350 L	0-7
3 Year Inspection of 1	tion Notes Material:	MEN'S LOCKER ROOM S: CS Abated? REMOVED	45-50	12 L	0-Y
3 Year Inspection of 1	tion Notes Material:	women's Locker RM	45-50	12 L	0-У
MUD JNT 3 Year Inspection of 1 Change in Concomments:	Material:	BLR RM 3: CS Abated? REMOVED	60-70	350 J	о-у

School Dist: Chico USD

School: CHICO JUNIOR HIGH

Date Inspected: 04/14/92

BUILDING: P

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
3 Year Inspe Condition of	ction Notes Material:	BLR RM :: S Abated? REMOVED	20-30	1000 S	0-Y
	Material:	BETWEEN LOCKER RMS S Abated? REMOVED EXTREMELY TIGHT	01-99 (Assumed)	350 L	0-Y

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp

DISTRICT		ified Scho	Chico Unified School District DATE Decem	December 21, 1992
SCHOOL	Chico Junior High	ior High	INSPECTOR Mi	Michael Fender MW
BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT W	1-5	Kitchen office	(7)
A	9" VFT R	1-5	Kitchen office	(1) Good - (4)
A	9" VFT	15	Main Hallway	(7)
А	9" VFT	1-5	MPR (Green)	(1) Good - (4)
А	9" VFT	1-5	Teacher's Lounge (Green)	(1) Good - (4)
А	9" VFT	1-5	Fan rooms (Green)	(1) Good - (4)
А	Mud Jnts	1-5	Water Tank room	(6) - (4)
A	Ceil Plas	1-5	Teacher's Lounge	(1) Good - (4)
Ą	Ceil Plas	1-5	MPR	(1) Good - (4)
Ą	Ceil Plas	1-5	Rest of Wing	(1) Good - (4)
A	Ceil Mat.	1-5	Refrigerator room	(1) Good - (4)
			CONDITION CODES	
GENERAL	SENERAL CONDITION:	(1)	GOOD (2) DAMAGED (3) SIGN	(3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE I	IN CONDITION:	(4)	NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)	N UNDER COMMENTS)
ABATED:	(6) REPAIRED	(7)	REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED &	OSED (10) ISOLATED & RESTRICTED
MISC:	(11) INACCESSIBLE,	SSIBLE, NO	SURVEILLANCE DATA	(12) OTHER (EXPLAIN UNDER COMMENTS)

(6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)			ified Scho dor High ASBESTOS MATERIAL 25-50 50-55 1-5 40-45 ASSumed ASSumed 1-5 1-5 1-5 1-5 1-5 1-5 1-5	Instrict DATE INSPECTOR LOCATION South & North Fan Rooms Teacher's Lounge Hot water closet Stage area Stage area Stage lighting Hallway & Upper wall Hallway Chapter One Office Room 11 CONDITION CODES (3)	December 21, 1992 R Michael Fender//// CONDITION: CODE & COMMENTS (1) Good - (4) (1) (2) (1) (1) (2) (1) (2) (1) (2) (3) (1) (1) (1) (2) (1) (2) (1) (1
HOMOG. ASBESTOS	1001100	01. 1 m			
HOMOG. ASBESTOS MATCH EACATION PW Str 25-50 South & North Fan Rooms 9" VFT 1-5 Teacher's Lounge Tank Wrap 40-45 Hot water closet Fight Assumed Stage area Light Assumed Stage lighting cords Ceil plas 1-5 Hallway 12" VFT R 1-5 Hallway 12" VFT R 1-5 Hallway Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Room 11 CondITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EXENTRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	SCHOOL	Chico Jun	ior High		
HOMOG.MAT.#MATERIALLOCATIONPW Str25-50South & North Fan Rooms9" VFT1-5Teacher's LoungeTank Wrap40-45Hot water closetPW StrAssumedStage areaLightAssumedStage lightingcords1-5Hallway & Upper wall9" VFT R1-5Hallway12" VFT R1-5HallwayCeil Plas1-5Room 11Coll Plas1-5Room 11AL CONDITION: E IN CONDITION: (4) NO (5) YES (IF YES, EX (4) NO (5) YES (IF YES, EX (5) REMOYED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)			100		
PW Str 25-50 South & North Fan Rooms	RIDG	HOMOG.	ASBESTOS	MOTEROOT	
Mud Jnt 50-55 South & North Fan Rooms 9" VFT 1-5 Teacher's Lounge Tank Wrap 40-45 Hot water closet PW Str Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway & Upper wall 9" VFT R 1-5 Hallway 12" VFT R 1-5 Hallway Ceil Plas 1-5 Chapter One Office Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Room 11 CondITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	· Porto	#• TUIS	FRIENIAL	DOCALLON	ш
Mud Jnt 50-55 South & North Fan Rooms 9" VFT 1-5 Teacher's Lounge Tank Wrap 40-45 Hot water closet PW Str Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway & Upper wall 9" VFT R 1-5 Hallway 12" VFT R 1-5 Hallway Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Room 11 CondITION CODES AL CONDITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX	Ą		25-50	& North Fan	- poog
Mud Jnt 50-55 South & North Fan Rooms 9" VFT 1-5 Teacher's Lounge Tank Wrap 40-45 Hot water closet PW Str Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway & Upper wall 9" VFT R 1-5 Hallway 9" VFT R 1-5 Chapter One Office Ceil Plas 1-5 Room 11 CondITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)					
Mud Jnt 50-55 South & North Fan Rooms 9" VFT 1-5 Teacher's Lounge Tank Wrap 40-45 Hot water closet PW Str Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway & Upper wall 9" VFT R 1-5 Hallway 9" VFT R 1-5 Chapter One Office Ceil Plas 1-5 Room 11 CondITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)					
Mud Jnt 50-55 South & North Fan Rooms 9" VFT 1-5 Teacher's Lounge Tank Wrap 40-45 Hot water closet Pw Str Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway & Upper wall 9" VFT R 1-5 Hallway 12" VFT R 1-5 Hallway Ceil Plas 1-5 Room 11 CondITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	4		06_67	& NOTELII FAII	2000
Mud Jnt 50-55 South & North Fan Rooms 9" VFT 1-5 Teacher's Lounge Tank Wrap 40-45 Hot water closet Dw Str Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway & Upper wall 9" VFT R 1-5 Hallway 12" VFT R 1-5 Hallway Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Room 11 CondITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)					
1-5 Teacher's Lounge	^	Mud Tn+	, U	C Mewth Ban	i
PW Str 1-5 Teacher's Lounge	_		i i		
Tank Wrap 40-45 Hot water closet Fank Wrap 40-45 Hot water closet Light Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway Upper wall 9" VFT R 1-5 Hallway 12" VFT R 1-5 Hallway Ceil Plas 1-5 Room 11 CondITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	Æ	Mud Jnt	50-55	& North Fan	i
Tank Wrap 40-45 Hot water closet Fank Wrap 40-45 Hot water closet Pw Str Assumed Stage area Light Assumed Stage lighting cords Ceil plas 1-5 Hallway Upper wall 9" VFT R 1-5 Hallway 12" VFT R 1-5 Hallway Ceil Plas 1-5 Room 11 CondITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	A	Mud Jnt	50-55	& North Fan	i
Tank Wrap 40-45 Hot water closet Fank Wrap 40-45 Hot water closet Light Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway Upper wall 9" VFT R 1-5 Hallway 12" VFT R 1-5 Hallway Ceil Plas 1-5 Room 11 CondITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	⋖	Mud Jnt	50-55	& North Fan	i
Tank Wrap 40-45 Hot water closet Fank Wrap 40-45 Hot water closet Light Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway Upper wall 9" VFT R 1-5 Hallway 12" VFT R 1-5 Hallway Ceil Plas 1-5 Room 11 CondITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	A	Mud Jnt	50-55	& North Fan	i
Tank Wrap 40-45 Hot water closet Pw Str Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway & Upper wall 9" VFT R 1-5 Hallway 9" VFT R 1-5 Ghapter One Office Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Room 11 CONDITION CODES E IN CONDITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	A	Mud Jnt	50-55	& North Fan	i
Tank Wrap 40-45 Hot water closet Pw Str Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway & Upper wall 9" VFT R 1-5 Hallway 9" VFT R 1-5 Ghapter One Office Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Room 11 CONDITION CODES E IN CONDITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	Ą	Mud Jnt	50-55	& North Fan	i
Tank Wrap 40-45 Hot water closet Pw Str Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway Upper wall 9" VFT R 1-5 Hallway Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Room 11 Condition: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	A	Mud Jnt	50-55	& North Fan	ı
Tank Wrap 40-45 Hot water closet Pw Str Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway & Upper wall 9" VFT R 1-5 Hallway 9" VFT R 1-5 Ghapter One Office Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Room 11 CONDITION CODES E IN CONDITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	Ą	Mud Jnt	50-55	& North Fan	i
Tank Wrap 40-45 Hot water closet Pw Str Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway Upper wall 9" VFT R 1-5 Hallway Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Room 11 CONDITION CODES AL CONDITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EXDITED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	Ą	Mud Jnt	50-55	& North Fan	ı
Tank Wrap 40-45 Hot water closet Pw Str Assumed Stage area Light Assumed Stage lighting cords 1-5 Hallway Upper wall 9" VFT R 1-5 Hallway 9" VFT R 1-5 Hallway Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Room 11 Condition: (1) Good (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)		2110	50	a noten tan	
Tank Wrap 40-45 Hot water closet Pw Str Assumed Stage area Light Assumed Stage lighting cords Ceil plas 1-5 Hallway & Upper wall 12" VFT R 1-5 Hallway 9" VFT R 1-5 Hallway Ceil Plas 1-5 Chapter One Office Ceil Plas 1-5 Room 11 Condition: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EXD) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)					
Tank Wrap 40-45 Hot water closet PW Str Assumed Stage area Light Assumed Stage lighting cords Ceil plas 1-5 Hallway & Upper wall 12" VFT R 1-5 Hallway 9" VFT R 1-5 Hallway Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Chapter One Office Ceil Plas 1-5 Room 11 CONDITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EXD) E IN CONDITION: (4) NO (5) YES (IF YES, EXD) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	A		1-5		Good -
Tank Wrap 40-45 Hot water closet				•	
Light Assumed Stage area Light Assumed Stage lighting Ceil plas 1-5 Hallway 12" VFT R 1-5 Hallway 9" VFT R 1-5 Hallway Ceil Plas 1-5 Chapter One Office Ceil Plas 1-5 Room 11 Ceil Plas (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX) E (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	A	Tank Wrap	40-45		find
Light Assumed Stage area cords Colds 1-5 Hallway & Upper wall 12" VFT R 1-5 Hallway Confice 9" VFT R 1-5 Hallway Condition CODES Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Room 11 Condition: (1) Good (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EXD: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)					
Light Assumed Stage lighting cords Ceil plas 1-5 Hallway & Upper wall 9" VFT R 1-5 Hallway 12" VFT R 1-5 Hallway Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Chapter One Office Ceil Plas (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EXD: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	Ą	PW Str	Assumed		(1) Good - (4)
Light Assumed Stage lighting cords Ceil plas 1-5 Hallway & Upper wall 12" VFT R 1-5 Hallway 9" VFT R 1-5 Hallway Ceil Plas 1-5 Room 11 Ceil Plas 1-5 Room 11 Condition CODES E IN CONDITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EXD: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)					
Ceil plas 1-5 Hallway & Upper wall	₩	Light	Assumed	Stage lighting	(7)
Ceil plas 1-5		cords		1	
Ceil plas 1-5					
9" VFT R 1-5 Hallway 12" VFT R 1-5 Chapter One Office Ceil Plas 1-5 Room 11 Condition Codes	В		1-5	& Upper	Cood -
9" VFT R 1-5 Hallway 12" VFT R 1-5 Hallway 9" VFT R 1-5 Chapter One Office Ceil Plas 1-5 Room 11 Condition: (1) GOOD (2) DAMAGED (3)					
12" VFT R 1-5 Hallway	Д	VFT	1-5	Hallway	(7)
12" VFT R 1-5 Hallway					
9" VFT R 1-5 Chapter One Office	æ	VFT	1-5	Hallway	(7)
Structure 1-5 Chapter One Office 1-5 Room 11	Ç	9444	i	,	Ţ,
Ceil Plas 1-5 Room 11 CONDITION CODES CONDITION CODES CONDITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EXD: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) CONDITION: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	ر	VFT	1-5	one	
AL CONDITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX D: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	ر		, L	0000	ויייט
CONDITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX D: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	ر	- li	1_0	KOOIII T.T	2000
AL CONDITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX D: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)					
AL CONDITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX D: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)					
AL CONDITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX D: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)				CONDITION CODES	
AL CONDITION: (1) GOOD (2) DAMAGED (3) E IN CONDITION: (4) NO (5) YES (IF YES, EX D: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)					
E IN CONDITION: (4) NO (5) YES (1F YES, EX D: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)		CONTINUE.		CON EM CO	
E IN CONDITION: (4) NO (5) YES (IF YES, EX D: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	- 11)	(1)	OD (2) DAMAGED	
<u>D</u> : (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) (11) INACCESSIBLE, NO SURVEILLANCE DATA (12)		N CONDITION	(4)	O (5) YES (IF YES, EX	IN UNDER COMMENTS)
(11) INACCESSIBLE, NO SURVEILLANCE DATA (12)	ABATED:	(6) REPAIRE	D (7) REMO	ED (8) ENCAPSULATED (9)	LOSED (10) ISOLATED & RESTRICTED
	MISC:	(11) INACCE	SSIBLE, NO	SURVEILLANCE DATA (12)	IER (EXPLAIN UNDER COMMENTS)
			•		

INSPECTOR Michael Fender 798 December 21, 1992 DATE DISTRICT Chico Unified School District Chico Junior High SCHOOL

CONDITION: CODE & COMMENTS	ved	ved	- (4)	- (4)	ved	- (4)	- (4)	ved	ved	- (4)	ved	
CONDITIO	(7) Removed	(7) Removed	(1) Good - (4)	(1) Good - (4)	(7) Removed	(1) Good - (4)	(1) Good - (4)	(7) Removed	(7) Removed	(1) Good - (4)	(7) Removed	
LOCATION	Rms 200,202,204,206,208	Rm 202	Rm 10 - Janitor storage	Rm 11	Rms 300,302,304,306,308	Janitor's Storage	Rm 8	Rms 400,402,404,406,408	Room 1	Room 2	Rms 500,502,504,506	
ASBESTOS MATERIAL	5-10	5-10	1-5	1-5	1-5	1-5	1-5	5-10	1-5	1-5	5-10	
HOMOG. MAT.#	9" VFT Br	9" VFT Br	9" VFT R	Ceil Plas	9" VFT Gr	9" VFT Rd	Ceil Plas	9" VFT	9" VFT Rd	Ceil Plas	9" VFT Br	
BLDG.	ပ	ပ	D	D	D	Ħ	E	ម	Ŧ	Į±ı	F	

CONDITION CODES

(3) SIGNIFICANTLY DAMAGED (25% OR MORE) (1) GOOD (2) DAMAGED GENERAL CONDITION:

(5) YES (IF YES, EXPLAIN UNDER COMMENTS)

(4) NO

CHANGE IN CONDITION:

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

(11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS) MISC:

INSPECTOR Michael Fender December 21, 1992 DATE DISTRICT Chico Unified School District Chico Junior High SCHOOL

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
ĬΞŧ	PW Str	40-45	Room 502	(7) Removed
Ēų	9" VFT BR	5-10	Room 504	(7) Removed
দ	PW Str	Assumed	Room 506	(7) Removed
ტ	PW Str	55-70	Boiler Room	(7) Removed
ტ	8" Str	02-09	Boiler Room	(7) Removed
ტ	Tank Wrap	60-70	Boiler Room	(7) Removed
Ŋ	4" Str	35-40	Boiler Room	(7) Removed
ຽ	4" Str	35-40	Shop Storage	(7) Removed
Н	Ceil Plas	1-5	Wood shop offices	(7) Removed
Н	9" VFT	1-5	Wood shop office & classrms	(7) Removed
ם	9" VFT Rd	1-5	Admin. offices	(7) Carpeted

CONDITION CODES

(3) SIGNIFICANTLY DAMAGED (25% OR MORE) (5) YES (IF YES, EXPLAIN UNDER COMMENTS) (1) GOOD (2) DAMAGED (4) NO CHANGE IN CONDITION: GENERAL CONDITION:

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

(11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS) MISC:

INSPECTOR Michael Fender December 21, 1992 DATE DISTRICT Chico Unified School District Chico Junior High SCHOOL

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
ם	9" VFT Rd	1-5	Hallway and Library	(7)
J.	Ceil Plas	1-5	All rooms in wing	(1) Good - (4)
J	PW Str	25~50	Work room closet	(1) Good - (4)
J	PW Cnr	5055	Work room closet	(4)
K	9" VFT Gn	1-5	Rms 201,203,205,207,209	(1) Good - (4)
L	9" VFT Br	5-10	301,303,305,307,309	Rm 303 5 - 2 broken tile
M	9" VFT Tn	5-10	401,403,405,407,409	Rm 403 5 - 2 broken tile
N	Ceil Plas	1-5	Office area	(7) Removed
N	Ceil Plas	1-5	Storage	(1) Good - (4)
N	9" VFT Bg	1-5	Choral Room	(7) Removed
N	9" VFT Bg	1-5	Offices	(7) Removed

CONDITION CODES

(3) SIGNIFICANTLY DAMAGED (25% OR MORE) (1) GOOD (2) DAMAGED

GENERAL CONDITION:

- ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED (5) YES (IF YES, EXPLAIN UNDER COMMENTS) (4) NO CHANGE IN CONDITION:
- (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS) MISC:

December 21, 1992 DATE DISTRICT Chico Unified School District INSPECTOR Michael Fender MM

Chico Junior High SCHOOL

5-10	Rm 503, Practice rooms	(7) Removed
25-50	Under raised floor	(7) Removed
1–5	RRS	(1) Good - (4)
02-09	Inside metal cabinets	(7) Removed
02-09	Inside metal cabinets	(7) Removed
1-5	Room 18 storage	None found
50-70	Boiler Room	(7) Removed
45-50	Boiler Room	(7) Removed
45-50	Men & Women's locker rooms	(7) Removed
20-30	Boiler Room	(7) Removed
PW Str Cn Assumed	Crawlspace between locker rooms	(7) Removed
	1-5 50-70 45-50 45-50 20-30 Assumed	

CONDITION CODES

(3) SIGNIFICANTLY DAMAGED (25% OR MORE) (5) YES (IF YES, EXPLAIN UNDER COMMENTS) (1) GOOD (2) DAMAGED (4) NO GENERAL CONDITION:

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

CHANGE IN CONDITION:

(11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS) MISC:

DISTRICT.	Chico Unified	- 1	School District DATE Dece	December 21, 1992
SCHOOL	Chico Junior High	ior High	INSPECTOR	Michael Fender MM
BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
Main Hall Tunl	PW Str	Assumed	Pipe tunnel from front to back	(7) Removed
GENERAL CC CHANGE IN ABATED: (6	CONDITION: (N CONDITION: ((6) REPAIRED (7) R (11) INACCESSIBLE,		CONDITION CODES (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATEI E, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER (SIGNIFICANTLY DAMAGED (25% OR MORE) XPLAIN UNDER COMMENTS) ENCLOSED (10) ISOLATED & RESTRICTED OTHER (EXPLAIN UNDER COMMENTS)