Maintenance and Operations 2455 Carmichael Drive Chico, CA 95928 Phone: (530) 891-3195 Fax: (530) 891-3190

Chico Unified School District

Fed Ex Airbill #8358 1795 0805

May 24, 2005

Forensic Analytical Specialties, Inc. 3777 Depot Road, Suite 409 Hayward, CA 94545

Re: Chico Junior High School Gym

To Whom It May Concern:

Please test the enclosed samples from the Chico Junior High School Gym for asbestos and lead. We would like a 48-hour turnaround on the samples. Please fax the results to us as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled: Chico Junior High School

Location: Gym - Boy's Restroom

Date Sampled: May 23, 2005 Number of Samples: One (1) – #CJH1

Location: Gym - Boy's Window
Date Sampled: May 23, 2005
Number of Samples: One (1) - #CJH2

Location: Gym - Girl's Restroom

Date Sampled: May 23, 2005 Number of Samples: One (1) - #CJH3

Location: Gym – Cage Wood
Date Sampled: May 23, 2005
Number of Samples: One (1) - #CJH4

Location: Gym – Stucco
Date Sampled: May 23, 2005
Number of Samples: One (1) - #CJH5

Location: Gym – Floor - lead
Date Sampled: May 23, 2005
Number of Samples: One (1) - #CJH6

Thank you for your prompt response to this request.

Sincerely,

Leroy Christophersen Safety & Loss Coordinator

LC:dlg Enclosures

2921

Client ID:

Final Report



Chico Unified School Dist

Cellulose (Trace)

Sellulose (95 %)

Laver: Tan Fibrous Material

Layer: Yellow Non-Fibrous Material

Total Composite Values of Fibrous Components:

CJH6

Forensic Analytical

Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Report Number: B073411 Ron Jones Date Received: 05/25/05 Date Analyzed: 05/27/05 2455 Carmichael Drive Date Printed: 05/27/05 Chico, CA 95928 First Reported: 05/27/05 Job ID/Site: Gym - Chico Jr High School FASI Job ID: 2921-78 Total Samples Submitted: 6 Date(s) Collected: 05/23/2005 Total Samples Analyzed: Asbestos Percent in Asbestos Percent in Asbestos Percent in Layer Lab Number Layer Type Layer Type Sample ID Type 10418248 СЛН1 ND Laver: White Drywall Layer: Tan Fibrous Material ND Total Composite Values of Fibrous Components: Asbestos (ND) Cellulose (20 %) 10418249 СЈҢ2 Layer: Off-White Drywall ND Layer: Beige Skimcoat/Joint Compound ND Layer: Paint ND tal Composite Values of Fibrous Components: Asbestos (ND) الداله (20 %) Fibrous Glass (10 %) CJH3 10418250 ND Laver: White Drywall Layer: Off-White Skimcoat/Joint Compound ND Layer: Paint ND Total Composite Values of Fibrous Components: Asbestos (ND) Cellulose (20 %) Fibrous Glass (10 %) С.ПН4 10418251 ND Layer: Tan Fibrous Material ND Layer: Paint Total Composite Values of Fibrous Components: Asbestos (ND) Cellulose (95 %) CJH5 10418252 Layer: Grey Cementitious Material ND Layer: Paint ND Total Composite Values of Fibrous Components: Asbestos (ND)

Asbestos (ND)

ND ND

10418253



Forensic Analytical

Report Number: B073411
Date Printed: 05/27/05

Name: Chico Unified School Dist Date Printed: 05

Asbestos Percent in Asbestos Percent in Asbestos Percent in Sample ID

Asbestos Percent in Asbestos Percen

Jin Almo

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) and Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product ascent by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

27/2005 10:26 5	1088742	2921-	FASI				PAG	Œ 03/0
Forensic Analy	/tical	2921	()		An	alysis R	equest f	=orm_
Client Name & Addres	s:		P.O. #: 0	50289		Date: ,	5123	105
Chico Unified Sc	hool Di	strict			hr/ 12hr			
2455 Carmichael	Drive	,	Due Date:			ue Time:		
Chico, CA <u>95928</u>			99-PLM: E	1-Standard	I / ☐ Point Co	ount L	D PCM: NIOS	H 7400
Contact: Lerou			TEM B	ulk: 🛭 Q	RA / 🔲 Yamat uantitative / 🗐	Qualitative /	Chatfiel	ld
Phone #: 530 - 891 -	3195		TEM W		Potable / D No	n-Potable / C] Wt %.	
Fax#: (530) 891-3			☐ Special	Project:				
Site: Chico TR		4.44.44.44.44.44.44.44.44.44.44.44.44.4	12 Metals A	nalysis: I	Viethod			
	HON		Matrix: _					
Gym			Analytes:	· · · · · · · · · · · · · · · · · · ·	···	- Arthur		
Comments: Asbest	65 an	dlead analys	; ; S					
Sample ID	Date/ Time	Sample Location/D	Description	Туре	FOR AIR SA Time On/Off	MPLES ONLY AVG. LPM	Total Time	Sample Area or Air Volume
CTH\$	5/23	Gym Boya Rest	hoon	A P C				
CTH2	5/23	Gym Boys Re	twon	P				
	5/23	Gym Girls R	estroum	PC		•		
CI43	57/	12 12	5.1	A		,		
CIHY		Gym Cage ii		P C				
CJHS	5/23	Gym exterior	stucco	PC				
CTHG	5/23	Gum woods	01	A P C				
		0		A _P				
				A P C				
	_			A P C				
Sampled by:	<u> </u>		Date	ا کا ا اص	13 145	- Time:	:	
Shipped via: 17 Fed Ex	Airbo		S Mail 🗇 C		J Drop Off			
Relinquished/by:		Relinquished by	' :		Relinqu	ished by:		
Date / Time:		Date / Time:			Date / T		·	
Received/by/	MICIL	Received by: Date / Time:			Receive Date / T			
Condition Acceptable?	Yea O	No Condition Accep	ptablo? 🛭 Ye	5 □ 1		on Acceptabl	e? 🗖 Yes	□ No

Date of Inspection: 12/28/2005

District: Chico Unified School District Inspector: Leroy Christophersen

School: Chico Junior High School

Building: MPR (AKA Building A)

Unit P

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	UNDETERMINED	TEACHER'S LOUNGE, MPR, AND REST OF THE WING	(1) (4)	N
М	DRYWALL	104	ASSUMED	UNDETERMINED	THROUGHOUT UNIT	(7) ABATED PRIOR TO 2004 INSPECTION ACCORDING TO CHICO USD RECORDS.	N/A
М	DRYWALL	106	ASSUMED	UNDETERMINED	THROUGHOUT UNIT	(1) (4) DISTRICT MUST CERTIFY.	N

Building: C – (AKA Classrooms 200, 202, 204, 206, & 208) Unit O

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	UNDETERMINED	CLASSROOM 11 (TITLE ONE OFFICE) & BOY'S RESTROOM	(1) (4)	N
М	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) (4)	N
М	12" VFT CREAM	97	ASSUMED	UNDETERMINED	CLASSROOMS 200, 202, 206, & 208	(1) (4) THE DISTRICT MUST CERTIFY.	N
М	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOM WING	(1) (4) NEW MATERIAL. THE DISTRICT MUST CERTIFY THIS MATERIAL IS NON- ASBESTOS. CONTAINING.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 12/28/2005

District: Chico Unified School District Inspector: Leroy Christophersen

School: Chico Junior High School

Building: D – (Classrooms 300, 302, 304, & 306)

						•	Officia
Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	9" VFT RED	2	1-5%	UNDETERMINED	JANITOR'S CLOSET – NEAR GIRLS RESTROOM	(1) (4)	N
S	CEILING PLASTER	8	1-5%	UNDETERMINED	CLASSROOM 311 (ROOM 11)	(12) UNABLE TO LOCATE	N
М	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) (4)	N
М	12" VFT CREAM	97	ASSUMED	UNDETERMINED	CLASSROOMS 300, 302, 304, 306, & 308	(1) (4) THE DISTRICT MUST CERTIFY THIS MATERIAL IS NON-ASBESTOS CONTAINING.	N
М	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) (4) NEW MATERIAL. THE DISTRICT MUST CERTIFY THIS MATERIAL IS NON- ASBESTOS CONTAINING.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 12/28/2005

District: Chico Unified School District Inspector: Leroy Christophersen

School: Chico Junior High School

Building: F – (AKA Classrooms 500, 502, 504, & 506)

Unit M

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	9" VFT RED	2	1-5%	UNDETERMINED	MIGRANT EDUCATION OFFICE	(2) TILES LOOSE DUE TO WATER	N
S	CEILING PLASTER	8	1-5%	UNDETERMINED	MIGRANT EDUCATION OFFICE'S & GIRL'S RESTROOM	(2) (4) WATER DAMAGE IN RESTROOM CEILING IN MIGRANT OFFICE	N
Т	PIPE WRAP STRAIGHT	26	40-45%	UNDETERMINED	CLASSROOM 502	(12) CANNOT LOCATE	N
Т	PIPER WRAP STRAIGHT	95	ASSUMED	UNDETERMINED	CLASSROOM 506	(12) CANNOT LOCATE	N
М	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) (4)	N
М	12" VFT	98	ASSUMED	UNDETERMINED	CLASSROOMS 500, 502, 504, & 506	(1) (4) THE DISTRICT MUST CERTIFY THIS IS A NON-ASBESTOS CONTAINING MATERIAL.	N

Building: G - (AKA Maintenance)

Unit Ĵ

							OTIL 3
Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
Т	BOILER REFRACTORY	100	ASSUMED	UNDETERMINED	TWO BOILER UNITS	(1) (4) NEED SIGNAGE	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: <u>12/28/2005</u>

District: Chico Unified School District Inspector: Leroy Christophersen

School: Chico Junior High School

Building: H & N – (AKA 501-Industrial Arts/Wood Shop & 503 & 505 –Durst Theater & Music Room)

Unit H & I

							OTHE TT CA
Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	12" ACT	17	NONE DETECTED	UNDETERMINED	WOOD SHOP, DURST THEATER, MUSIC CLASSROOM, & PRACTICE CLASSROOMS 1-5	(13) SAMPLE HMS-CJH-17 COLLECTED IN 1988.	N/A
М	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) (4)	N
М	12" VFT CREAM	97	ASSUMED	UNDETERMINED	COMPUTER ROOM, MATERIAL STORAGE, STORAGE, & STAFF OFFICE, DURST THEATRE, OFFICES, MUSIC CLASSROOM, AND PRACTICE CLASSROOMS 1-5	(1) (4) THE DISTRICT MUST CERTIFY THIS MATERIAL AS NON-ASBESTOS CONTAINING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: <u>12/28/2005</u>

District: Chico Unified School District Inspector: Leroy Christophersen

School: Chico Junior High School

Building: J (AKA Main Office Building)

Unit A

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	UNDETERMINED	LIBRARY	(1) (4)	N
М	12" VFT CREAM	97	ASSUMED	UNDETERMINED	ADMINISTRATION OFFICES, HALLWAY, AND LIBRARY	(1) (4) THE DISTRICT MUST CERTIFY THIS MATERIAL AS NON-ASBESTOS CONTAINING MATERIAL.	N
М	DRYWALL	101	ASSUMED	UNDETERMINED	THROUGHOUT UNIT	(1) (4) NEW DRYWALL WAS PUT INTO THIS UNIT DURING THE RENOVATION IN THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY THIS MATERIAL AS NON-ASBESTOS CONTAINING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 12/28/2005

District: Chico Unified School District Inspector: Leroy Christophersen

School: Chico Junior High School

Building: K – (AKA Classrooms 201, 203, 205, 207, 209, & 211)

Unit B

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) (4)	N
М	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N
М	12" VFT GREY	102	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N

Building: L - (AKA Classrooms 301, 303, 305, 307, 309, & 311)

Unit C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) (4)	N
М	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N
М	12" VFT GREY	103	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 12/28/2005

District: Chico Unified School District Inspector: Leroy Christophersen

School: Chico Junior High School

Building: M - (AKA Classrooms 401, 403, 405, 407, & 409)

Unit D

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) (4)	N
М	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N
M	12" VFT GREY	103	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N

Building: O – (AKA Gymnasium)

Unit É

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	9" VFT GREEN	5	1-5%	200 S	RESTROOMS	(10)	N

Building: P - (AKA PE Locker Rooms)

Unit É

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition	Code & Comments	Friable Yes / No
М	9" VFT GREEN	5	1-5%	UNDETERMINED	CLASSROOM 18 STORAGE	(12)	COULD NOT FIND DURING TIME OF INSPECTION.	N
Т	PIPE WRAP	105	ASSUMED	UNDETERMINED	IN CEILING PIPE CHASE	(10)	COULD NOT LOCATE	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 06/09/2005

Inspector: Leroy Christophersen District: Chico Unified School District

School: Chico Junior High School Building: MPR (AKA Building A)

Unit P

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	UNDETERMINED	TEACHER'S LOUNGE, MPR, AND REST OF THE WING	(1) (4)	N
М	DRYWALL	104	ASSUMED	UNDETERMINED	THROUGHOUT UNIT	(7) ABATED PRIOR TO 2004 INSPECTION ACCORDING TO CHICO USD RECORDS.	N/A
М	DRYWALL	106	ASSUMED	UNDETERMINED	THROUGHOUT UNIT	(1) DISTRICT MUST CERTIFY.	N

Building: C – (AKA Classrooms 200, 202, 204, 206, & 208) Unit O

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	UNDETERMINED	CLASSROOM 11 (TITLE ONE OFFICE) & BOY'S RESTROOM	(1) (4)	N
М	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) (4)	N
М	12" VFT CREAM	97	ASSUMED	UNDETERMINED	CLASSROOMS 200, 202, 206, & 208	(1) (4) THE DISTRICT MUST CERTIFY.	N
М	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOM WING	(1) (4) NEW MATERIAL. THE DISTRICT MUST CERTIFY THIS MATERIAL IS NON- ASBESTOS. CONTAINING.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

(7) Removed (8) Encapsulated (6) Repaired (9) Enclosed Abated: (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 06/09/2005

District: Chico Unified School District Inspector: Leroy Christophersen

School: Chico Junior High School

Building: D – (Classrooms 300, 302, 304, & 306)

							Ullitiv
Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	9" VFT RED	2	1-5%	UNDETERMINED	JANITOR'S CLOSET – NEAR GIRLS RESTROOM	(1) (4)	N
S	CEILING PLASTER	8	1-5%	UNDETERMINED	CLASSROOM 311 (ROOM 11)	(12) UNABLE TO LOCATE	N
М	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) (4)	N
М	12" VFT CREAM	97	ASSUMED	UNDETERMINED	CLASSROOMS 300, 302, 304, 306, & 308	(1) (4) THE DISTRICT MUST CERTIFY THIS MATERIAL IS NON-ASBESTOS CONTAINING.	N
М	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) (4) NEW MATERIAL. THE DISTRICT MUST CERTIFY THIS MATERIAL IS NON- ASBESTOS CONTAINING.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 06/09/2005

District: Chico Unified School District Inspector: Leroy Christophersen

School: Chico Junior High School

Building: F – (AKA Classrooms 500, 502, 504, & 506)

Unit M

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	9" VFT RED	2	1-5%	UNDETERMINED	MIGRANT EDUCATION OFFICE	(1) (4)	N
S	CEILING PLASTER	8	1-5%	UNDETERMINED	MIGRANT EDUCATION OFFICE'S & GIRL'S RESTROOM	(2) WATER DAMAGE IN RESTROOM CEILING IN MIGRANT OFFICE	N
Т	PIPE WRAP STRAIGHT	26	40-45%	UNDETERMINED	CLASSROOM 502	(12) CANNOT LOCATE	N
Т	PIPER WRAP STRAIGHT	95	ASSUMED	UNDETERMINED	CLASSROOM 506	(12) CANNOT LOCATE	N
М	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) (4)	N
М	12" VFT	98	ASSUMED	UNDETERMINED	CLASSROOMS 500, 502, 504, & 506	(1) (4) THE DISTRICT MUST CERTIFY THIS IS A NON-ASBESTOS CONTAINING MATERIAL.	N

Building: G - (AKA Maintenance)

Unit Ĵ

							O i iii o
Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
Т	BOILER REFRACTORY	100	ASSUMED	UNDETERMINED	TWO BOILER UNITS	(1) (4) NEED SIGNAGE	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: <u>06/09/2005</u>

District: Chico Unified School District Inspector: Leroy Christophersen

School: Chico Junior High School

Building: H & N – (AKA 501-Industrial Arts/Wood Shop & 503 & 505 –Durst Theater & Music Room)

Unit H & I

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	12" ACT	17	NONE DETECTEDD DDD	UNDETERMINED	WOOD SHOP, DURST THEATER, MUSIC CLASSROOM, & PRACTICE CLASSROOMS 1-5	(13) SAMPLE HMS-CJH-17 COLLECTED IN 1988.	N/A
М	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) (4)	N
М	12" VFT CREAM	97	ASSUMED	UNDETERMINED	COMPUTER ROOM, MATERIAL STORAGE, STORAGE, & STAFF OFFICE, DURST THEATRE, OFFICES, MUSIC CLASSROOM, AND PRACTICE CLASSROOMS 1-5	(1) (4) THE DISTRICT MUST CERTIFY THIS MATERIAL AS NON-ASBESTOS CONTAINING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 06/09/2005

District: Chico Unified School District Inspector: Leroy Christophersen

School: Chico Junior High School

Building: J (AKA Main Office Building)

Unit A

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	UNDETERMINED	LIBRARY	(1) (4)	N
М	12" VFT CREAM	97	ASSUMED	UNDETERMINED	ADMINISTRATION OFFICES, HALLWAY, AND LIBRARY	(1) (4) THE DISTRICT MUST CERTIFY THIS MATERIAL AS NON-ASBESTOS CONTAINING MATERIAL.	N
М	DRYWALL	101	ASSUMED	UNDETERMINED	THROUGHOUT UNIT	(1) (4) NEW DRYWALL WAS PUT INTO THIS UNIT DURING THE RENOVATION IN THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY THIS MATERIAL AS NON-ASBESTOS CONTAINING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 06/09/2005

District: Chico Unified School District Inspector: Leroy Christophersen

School: Chico Junior High School

Building: K – (AKA Classrooms 201, 203, 205, 207, 209, & 211)

Unit B

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) (4)	N
М	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N
М	12" VFT GREY	102	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N

Building: L – (AKA Classrooms 301, 303, 305, 307, 309, & 311)

Unit C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) (4)	N
М	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N
М	12" VFT GREY	103	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 06/09/2005

District: Chico Unified School District Inspector: Leroy Christophersen

School: Chico Junior High School

Building: M - (AKA Classrooms 401, 403, 405, 407, & 409)

Unit D

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) (4)	N
M	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N
М	12" VFT GREY	103	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N

Building: O – (AKA Gymnasium)

Unit É

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	9" VFT GREEN	5	1-5%	200 S	RESTROOMS	(1) (4)	N

Building: P - (AKA PE Locker Rooms)

Unit F

1	+	t	t	t				1
Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition	Condition: Code & Comments	
М	9" VFT GREEN	5	1-5%	UNDETERMINED	CLASSROOM 18 STORAGE	(12)	COULD NOT FIND DURING TIME OF INSPECTION.	N
Т	PIPE WRAP	105	ASSUMED	UNDETERMINED	IN CEILING PIPE CHASE	(10)	COULD NOT LOCATE	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Maintenance and Operations 2455 Carmichael Drive Chico, CA 95928 Phone: (530) 891-3195

Fax: (530) 891-3190

Chico Unified School District

Fed Ex Airbill #8358 1795 0849

June 9, 2005

Forensic Analytical Specialties, Inc. 3777 Depot Road, Suite 409 Hayward, CA 94545

Re: Chico Junior High School

To Whom It May Concern:

Please test the enclosed paint chip samples from the Chico Junior High School Unit F Girl's Restroom for lead. We would like a 48-hour turnaround on the samples. Please fax the results to us as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled: Chico Junior High School

Location: Unit F – Girl's Restroom

Date Sampled: June 9, 2005 Number of Samples: One (1) – #CJH01

Thank you for your prompt response to this request.

Sincerely,

Leroy Christophersen Safety & Loss Coordinator

LC:dlg Enclosures



Maintenance & Operations ♦ 2455 Carmichael Drive ♦ Chico, CA 95928 ♦ (530) 891-3195 ♦ Ichristo@chicousd.org

Date:

July 28, 2005

To:

Asbestos Binders for:

Chico Junior High School

Former Fair View High School (now Chico Country Day School)

John Mc Manus Elementary School

Shasta Elementary School

From:

Leroy A. Christophersen, Safety & Loss Control Coordinator

Re:

Relocated Buildings

This memo is to advise that the following changes have been made at the sites listed above.

- Room P-1 has been moved from Chico Junior High School and relocated to John McManus Elementary Schoo.
- Room 15 & 16 have been moved from the former Fair View High School (now CCDS) and relocated to John McManus Elementary School.
- Room 12 has been moved from the Former Fair View High School (now CCDS) and relocated to Shasta Elementary School.
- Room C5 has been moved from the Former Fair View High School (now CCDS) and relocated to Shasta Elementary School.

LC/dlg



RECORD OF FRIABLE AND NONFRIABLE ACM (FORM B)

THREE-YEAR REINSPECTION

	THREE-TEAR REINSFECTION					
				CDS CODE 04-61424-6057137		
SCHOOL Chico Junior High Scho	ool			SCHOOL PHONE NUMBER (530) 891-3066		
ADDRESS 280 Memorial Way	(NUMBER)	(STREET)	(CITY) Chico, CA	(ZIP) 95926	11111	

-IMPORTANT-

Each building and functional space with friable ACBM or friable assumed ACBM listed on this form requires completion of FORM C (PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE ACBM OR FRIABLE ASSUMED ACBM). Indicate location of material on blueprint, diagram or narrative in square or linear feet, and attach a copy (Sec. 763.93).

	·	СНЕ	CHECK ONE			CHEC	K ONE	NE	
LINE	BUILDING NAME & FUNCTIONAL SPACE	SUR-			AC	вм	ASSUMED ACBM		
	(Indicate Address if Different From Above)	FACING	TSI	MISC	FRIABLE	NON- FRIABLE	FRIABLE	NON- FRIABLE	
1	B - (AKA HALLWAYS) NO ACBM								
2.	C - (AKA CLASSROOMS 200, 202, 204, 206, & 208)	х		х		x		х	
3.	D - (AKA CLASSROOMS 300, 302, 304, & 306)	х		х		X		Х	
4.	F - (AKA CLASSROOMS 500, 502, 504, & 506)	х	х	Х		х		х	
5.	G - (AKA MAINTENANCE)		х					х	
6.	H & N - (AKA CLASSROOMS 501, 503, & 505)			х				Х	
7.	J - (AKA MAIN OFFICE BUILDING)	X		х		X		х	
8.	K - (AKA CLASSROOMS 201, 203, 205, 207, 209, & 211)			х				x	
9.	L - (AKA CLASSROOMS 301, 303, 305, 309, & 311)		: 	x		·		Х	
10.	M - (AKA CLASSROOMS 401, 403, 405, 407, & 409)		-	х				x	
11.	METAL STORAGE'S (2) NO SUSPECT ACBM								
12.	MPR - (AKA BUILDING A)	х		Х		Х		Х	
13.	O - (AKA GYMNASIUM)			х				Х	
14.	P - (AKA PE LOCKER ROOMS)		х	х		x		Х	
15.	STORAGE NO SUSPECT ACBM								
16.	SPEECH UNIT DISTRICT MUST CERTIFY								
17.	UNIT 600 COUNTY CH DISTRICT MUST CERTIFY								

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B. O:\Shannon's Doc\REINSPT\ChicoUSD\Z004\ChicoJHS\FORM.B.wpd



San Francisco • Los Angeles • Sacramento • Chicago • Las Vegas • Portland

Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist Ron Jones

Job ID/Site:

Sample ID

CJH1

СЈН2

2455 Carmichael Drive Chico, CA 95928

Client ID:

2921

Report Number: Date Received:

B079144 11/22/05

Date Analyzed:

11/25/05

Date Printed:

11/25/05

First Reported:

11/25/05

Reroof - Chico Jr High - PO# 050289

FASI Job ID:

Layer

2921-78

Layer

Total Samples Submitted: 7

Date(s)	Conectea:	: 11/18/2005

Lao Number		1 ype
• • •	-	
10471734		

Layer: Black Tar Layer: Black Felt

Layer: Black Tar Layer: Black Felt

Layer: Black Tar Layer: Black Felt

Layer: Black Tar r: Black Felt

> الد Composite Values of Fibrous Components: Asbestos (ND) Fibrous Glass (30 %)

Cellulose (30 %) Comment: Bulk complex sample.

10471735

Layer: Black Tar Layer: Black Felt

Layer: Black Tar Layer: Black Felt

Layer: Black Tar Layer: Black Felt Layer: Black Tar

Layer: Black Felt Layer: Black Tar Layer: Black Felt

Total Composite Values of Fibrous Components:

Cellulose (10 %) Fibrous Glass (55 %)

Comment: Bulk complex sample.

Total Samples Analyzed: Percent in Asbestos Percent in

Type

ND

Percent in

Layer

Asbestos

Type

ND

ND

ND ND

ND ND

ND

Asbestos

ND ND ND

ND ND

ND ND

ND ND ND



Comment: Bulk complex sample.

Forensic Analytical

San Francisco • Los Angeles • Sacramento • Chicago • Las Vegas

'and

Report Number: B079144 Client Name: Chico Unified School Dist Date Printed: 11/25/05

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
СЈН3	10471736						
Layer: Black Tar			ND		4		
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND			•	
Total Composite Values of Fibrous Cor	nponents: As	sbestos (ND)					
Cellulose (Trace) Fibrous Glass (5	A						
Comment: Bulk complex sample.							
CJH4	10471737	134 왕왕왕왕 _년 151일	ar [1] [4] [4] [4] [4] [5] [6] [6] [6] [6] [6] [6] [6] [6] [6] [6	Market Lista (1)	s (144) 147, 14		1 - 1 - 11
Layer: Black Tar	10171757		ND				
Layer: Black Felt		•	ND		•		•
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				4
Layer: Black Felt			ND				١
Total Composite Values of Fibrous Con	nnonents: 🛦 🕻	bestos (ND)	and the contract of the second				
Cellulose (Trace) Eibrous Glass (55		incstos (IND)	Maria de la composición del composición de la composición de la composición de la composición del composición de la composición de la composición de la composición de la composición del composición de la composición del composic		i i kanya (iso)		
Comment: Bulk complex sample.							
그리고 하는 사람이 들어요. 그 사람들은 하는 생생님은 함께 모양했다.							
CJH5	10471738						
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				•
Layer: Black Felt			ND				
Layer: Black Tar Layer: Black Felt			ND				
Layer: Black Felt Layer: Black Tar			ND				
			ND				
Layer: Black Felt	en den en e	gava vilje i se ki	ND				
Total Composite Values of Fibrous Con Cellulose (20 %) Fibrous Glass (35		bestos (ND)					



Forensic Analytical

San Francisco • Los Angeles • Sacramento • Chicago • Las Vegas • Portland

Report Number:

B079144 1/25/05

		-	report numbers	
leπι Name:	Chico Un	ified School Dist	Date Printed:	11

		Asbestos	Percent in	Asbestos	Percent in	Asbestos	Percent in
Sample ID	Lab Number	Type	Layer	Type	Layer	Type	Layer
СЈН6	10471739						····
Layer: Black Tar Stones	•		ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt	•		ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND		•		
Layer: Black Felt			ND				
Cellulose (10 %) Fibrous Gla Comment: Bulk complex sample CJH7	[1] (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	- 12 (4) (4) (4) (5) (5) (5) (5) (5) (5) (5) (5) (5) (5					
Layer: Black Tar	104/1/40		ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				*
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Y -ver: Black Felt			ND				
r: Black Tar			ND				
yer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Total Composite Values of Fibro	us Components: A	sbestos (ND)					
Cellulose (Trace) Fibrous Gl							

Comment: Bulk complex sample.

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

Maintenance and Operations 2455 Carmichael Drive Chico, CA 95928 Phone: (530) 891-3195 Fax: (530) 891-3190

Chico Unified School District

Fed Ex Airbill #8358 1795 0920

May 24, 2005

Forensic Analytical Specialties, Inc. 3777 Depot Road, Suite 409 Hayward, CA 94545

Re:

Chico Junior High School Unit I Roof & Chico Country Day School Unit G Roof

To Whom It May Concern:

Please test the enclosed samples from the Chico Junior High School and Chico Country Day School for asbestos. We would like a 48-hour turnaround on the samples. Please fax the results to us as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled:

Location: Date Sampled:

Number of Samples:

Site Sampled:

Location: Date Sampled:

Number of Samples:

Chico Junior High School

Unit I Roof November 18, 2005

Seven (#CJH 1 through #CJH 7)

Chico Country Day School

Unit G Roof November 18, 2005

Seven (#CCD 1 through #CCD 7)

Thank you for your prompt response to this request.

Sincerely,

Leroy Christophersen Safety & Loss Coordinator

LC:dlg Enclosures

Forensic Anal	ytical	* 			Ar	nalvsis F	Request	Form
Client Name & Addres	s:		P.o. #: 050289 Analysis Request Form					
Chico Unified Sc	chool Di	strict	71.27.103					
2455 Carmichael	Drive		Turn Around Time:hr/ 12hr / 24hr / 48 hr / ext: Due Date: / / Due Time: am/pm					
Chico, CA 95928			□ PLM: €	Standard	/ D Point Co		PCM: NIO	
Contact: Leroy A. Phone #: 530- Ichristo	☐ TEM Air: ☐ AHERA / ☐ Yamate2 / ☐ NIOSH 7402 ☐ TEM Bulk: ☐ Quantitative / ☐ Qualitative / ☐ Chatfield ☐ TEM Water: ☐ Potable / ☐ Non-Potable / ☐ Wt % ☐ TEM Microvac							
	(530) 891-3190							-
Site: Chico JR.			☐ Metals /	Analysis: N	lethod			
Job:	myn_		Matrix:					
Reroof Comments:			Analytes:					
- Juliuoritoi	T							
Sample ID	Date/ Time	Sample Location/De	scription	Type	FOR AIR SA Time Oh/Off	MPLES ONE Avg. LPM		Sample Area or Air
CJH I	148	Unit & Roof	1/Black	A P C			s in e	Volume
CJH 2	1/18			A _P -				
CT43	"/18			A _P -				
CJH4	1/18			A P C				
CJH5	4/18			A _P C				
CT#6	1/18		·	A P C				
CJH7	4/18			P C				
				P _C				
0				A P C				
Sampled by:	y A.C.	hristophersen	Date:	111/	8105	Time:	1:00 7	PM
Shipped via: Ted Ex			Mail ☐ Co	urier 🗆	Drop Off	 ☐ Other:		<u>: </u>
Relinquished by:	· · · · · · · · · · · · · · · · · · ·	Relinquished by:	·			shed by:		
Date / Time:		Date / Time:			Date / Ti	me:		
Received by:	300(010	Received by:			Receive	d by:	·	
Date / Time:	Incoll	Date / Time:			Date / Ti	me:		
Condition Acceptable?	Yes d	Condition Accepta	ble? 🛘 Yes	□ No	Conditio	n Acceptabl	e? 🗆 Yes	∏ No

