MEASURE E SCHOOL SITE SURVEY

CHICO HIGH SCHOOL

Lighting for walkway between Gym and student parking Lighting for Interior of campus Security Cameras on campus	General Items Lighting for walkway between Gym and student parking Improved computers in Library Security Cameras on campus Poor drainage in parking lot
Lighting for Interior of campus Security Cameras on campus	Improved computers in Library Security Cameras on campus
Security Cameras on campus	Security Cameras on campus
HVAC in Library	Poor drainage in parking lot
I I I I I I I I I I I I I I I I I I I	1 oor aramage in parking for
Roof Repair (Gym & offices, A-Bldg., F-wing, Library, H-wing)	Roof Repair (Gym & offices, A-Bldg., F-wing, Library, H-wing)
Painting exterior of school	Painting exterior of school
D-wing hallway (music) needs interior painting	Poor drainage on blacktop path between Gym and parking lot
Misc. seat repair in Williams Theater	Misc. seat repair in Williams Theater and poor lighting
Blind entrance/exit to staff parking lot on W. Sac is dangerous	Blind entrance/exit to staff parking lot on W. Sac is dangerous
Drinking fountains around campus	Drinking fountains around campus
Replacement of old locks (need to lock from inside during Code Red)	New hand dryers in B & C wings
Visitor check-in system with immediate background check	Football stands
Athletic Fields	
Stands for seating next to track/football field (1500-2000 people)	
Attached press box	
Restrooms that serve 1500-2000 people	
Resurfaced track	
Fencing to secure field	
A-Building .	A-Building
Modernization of A-Building	Modernization of A-Building
Women staff restroom toilets do not work properly	Drains on roof of A-Building
Doors throughout the A-Wing do not close properly	Leaky rook (see above)
Drains on roof of A-Building (currently run off like a waterfall)	
Faculty restrooms in A-Building (remodel)	
Leaky rook (see above)	
F-wing (Art)	F-wing (Art)
Cover, enclose, and secure storage area	Add covers to the security lights around the building
Repair leaking roof in at least six locations	Repair leaking roof in at least six locations

Staff Recommendations	Student Input
Sink drains-drain lines & traps need to be replaced	Sink drains-drain lines & traps need to be replaced
Add covers to the security lights around the building	
F-4 and F-5 need more electrical outlets, power poles and data lines	
F-3 needs more electrical outlets for potter's wheels	
F-1 needs window above door replaced	
Extend roof line or add cover above our doors to protect from rain	
P.E. Facilities	P.E. Facilities
Bell & Speakers in P.E. fields	Bell & Speakers in P.E. fields
Code Red Lighting (flashing lights) in gym	Code Red Lighting (flashing lights) in gym
Heating units in the gym	Heating units in the gym
Gym backboards in need of repair	Re-surface track
Boy's and Girl's locker room lockers broken	Boy's and Girl's locker room lockers broken
Fencing separating the parking lot and athletic fields for safety	
Fix HVAC in wrestling/matt room and weight room	
Cover or insulate fans in wrestling/matt room and weight room	
S-Wing (Science)	S-Wing (Science)
Poor drainage around S-wing during storms	Poor drainage around S-wing during storms
A/C in Science Equipment Storage area (backroom)	Replacement of old locks (need to lock from inside during Code Red)
Replacement of old locks (need to lock from inside during Code Red)	